



友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

KMHJ3813MG4184975

TP China

Hui Rong

LKK

DATE: 24/04/2022 OUR REF: UAPL1523
REPAIR ESTIMATE TO THE HYUNDAI TUCSON NO: SLA7744T

- 1 REAR TAILGATE ASSY *Detec*
- 1 RE/ R TAILGATE LAMP. (R) *Crushed*
- 1 REAR TAILGATE INNER LOCK *2nd*
- 1 REAR TAILGATE STRIKER *New*
- 2 REAR TAILGATE HINGES *New*
- 1 REAR TAILGATE WEATHERSTRIP *it*
- 1 REAR TAILGATE HYUNDAI EMBLEM ASSY *3 new*
- 1 REAR TAILGATE TUCSON EMBLEM *not new*
- 2 REAR TALGATE NUMBER PLATE LAMP *Deformed.*
- 1 REAR TAILGATE OUTER GARNISH *Crushed.*
- 1 REAR TAILGATE OUTER GARNISH BRACKET *Crushed.*
- 1 REAR TAILGATE INNER TRIM BOARD *Crushed.*
- 1 REAR TAILGATE STAY ABSORBER *new*
- 1 REAR TAILGATE INNER HANDLE GARNISH *Not in*
- 1 REAR TAILGATE GLASS ASSY *Shattered*
- 1 REAR TAILGATE WIPER MOTOR ASSY *2nd*
- 1 REAR TAILGATE WIPER ARM *3 not in*
- 1 REAR TAILGATE WIPER BLANDE *new*
- 1 REAR TAILGATE GLASS MOULDING *new*
- 1 REAR TAILLAMP ASSY (R) *Crushed*
- 1 REAR BUMPER FACE (TOP) *3 Deformed*
- 1 REAR BUMPER FACE (LOWER) *Crushed.*
- 1 REAR BUMPER REINFORCEMENT *new*
- 1 REAR BUMPER INNER SPONGE *new*
- 2 REAR BUMPER SIDE RETAINER *new*
- 1 REAR BUMPER TOW COVER GARNISH *2nd*
- 1 REAR R/H BUMPER REFLECTOR LAMP *Crushed*
- 8 REAR BUMPER CLIPS *new*
- 1 REAR EXHAUST BOX *Not in*
- 1 TAIL END PANEL *new*
- 1 PANEL LINING *Deformed*

\$	1,938.00	1758
\$	686.20	✓
\$	667.00	395
\$	38.70	X
\$	196.80	X
\$	159.80	✓
\$	48.30	✓
\$	88.40	✓
\$	90.40	X
\$	618.40	✓
\$	145.70	✓
\$	338.80	✓
\$	599.20	X
\$	42.60	X
\$	1,644.80	1358
\$	889.60	585
\$	222.40	X
\$	84.60	X
\$	105.60	✓
\$	886.60	✓
\$	755.80	✓
\$	543.20	✓
\$	432.80	271
\$	286.50	X
\$	68.00	X
\$	25.80	✓
\$	102.70	✓
\$	48.00	30
\$	914.80	X
\$	785.80	X
\$	120.80	✓
\$	13,576.10	
\$	1,357.61	
\$	12,218.49	

LESS 10%

20%

9023.10

7218.48



友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

SPECIAL NETT:-

- 1 REAR NUMBER PLATE *Not rec*
- 1 SET REAR CCTV CAMERA *Not rec*
- 1 REAR TAILGATE OUTER GARNISH CHROME STRIP *let*
- 1 REAR BUMPER TOP CHROME STRIP GARNISH *rec*
- 1 REAR BUMPER LOWER SPOILER *cracked*
- 1 REAR BUMPER REVERSE SENSOR *rec*
- 1 REAR WINDSCREEN RUBBER SEALANT *rec*
- 1 REAR EXHAUST CHROME PIPE *Best*

\$ 50.00 X
\$ 420.00 X
\$ 180.00 150
\$ 220.00 180
\$ 550.00 ✓
\$ 280.00 200
\$ 80.00 60
\$ 120.00 80

1220

LABOUR CHARGES:-

TO SPRAY UNDERCOATING IN REPAIR

TO DISM/REWIRE DAMAGED PORTION

TO DISM/REFIX REAR WINDSCREEN GLASS

TO DISM/RENEW REAR REVERSE SENSOR/CAMERA

TO RENEW REAR BUMPER LOWER SPOILER

TO DISM/RENEW REAR EXHAUST PIPE

TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS

TO PUTTY AND RESPRAY DAMAGED PORTION

\$ 200.00 30
\$ 180.00 30
\$ 180.00 120
\$ 200.00 100
\$ 200.00 X
\$ 150.00 60
\$ 1,200.00 600
\$ 1,000.00 600
\$ 17,428.49

1540

total: 9978.48

L/S: 79K

05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



BOGICE FORCE
SINGAPORE

