

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY #07-16  
AIG BUILDING, SINGAPORE 079120  
TEL: 64193000 FAX: 68357416  
ATTN: Motor Claim Department

Estimate No: EST2200115  
Date: 19 Apr 2022  
Veh Reg No: SMK5398H  
Make/Model: TOYOTA VIOS 1.5G (AUTO)  
Chasis No: MR2B23F3101171851  
Reg. Date: 15/04/2019  
Your Ref No: SKK3344A

Claim Type: Third Party  
Accident Date: 14/04/2022  
TP Veh Reg No: SKK3344A

*Xiao Tony*

## Estimate Repair Cost to Vehicle No :SMK5398H

| Quantity | Description                                    | List Price | Amount |
|----------|------------------------------------------------|------------|--------|
|          |                                                | SS         | SS     |
|          | <b>List Price</b>                              |            |        |
| 1        | 1 PC BOOT LID <i>Dented</i>                    | 758.70     | ✓      |
| 2        | 2 PCS BOOT LID HINGE <i>Bent</i>               | 155.60     | ✓      |
| 3        | 1 PC BOOT LID LOGO <i>new</i>                  | 52.20      | ✓      |
| 4        | 1 PC BOOT LID "VIOS" EMBLEM <i>new</i>         | 43.60      | ✓      |
| 5        | 1 PC BOOTLID "G" EMBLEM                        | 42.20      | ✓      |
| 6        | 1 PC BOOT LID LOCK <i>Dented</i>               | 360.40     | ✓      |
| 7        | 1 PC BOOT LID LOCK CHECKER <i>new</i>          | 49.20      | ✓      |
| 8        | 1 PC BOOT LID RUBBER <i>cut</i>                | 166.40     | ✓      |
| 9        | 1 PC BOOT LID LAMP LH <i>new</i>               | 230.30     | ✓      |
| 10       | 1 PC BOOT LID LAMP RH <i>new</i>               | 230.30     | ✓      |
| 11       | 1 PC BOOT LID TRIM <i>new</i>                  | 187.70     | ✓      |
| 12       | 1 PC REAR FENDER RH <i>new</i>                 | 804.80     | ✓      |
| 13       | 1 PC REAR FENDER TRIM RH <i>Dented</i>         | 355.90     | ✓      |
| 14       | 1 PC TAIL LAMP - RH <i>cracked</i>             | 397.50     | ✓      |
| 15       | 1 PC TAIL LAMP LH <i>new</i>                   | 397.50     | ✓      |
| 16       | 1 PC REAR LH FENDER TRIM <i>new</i>            | 355.90     | ✓      |
| 17       | 1 PC REAR PANEL <i>Dented</i>                  | 680.00     | ✓      |
| 18       | 1 PC REAR PANEL TRIM <i>Dented</i>             | 232.20     | ✓      |
| 19       | 1 PC REAR PANEL ANTENNA <i>cracked</i>         | 167.20     | ✓      |
| 20       | 1 PC SPARE TYRE PANEL RH SPONGE <i>Dented</i>  | 128.80     | ✓      |
| 21       | 1 PC SPARE TYRE PANEL LH SPONGE <i>new</i>     | 128.80     | ✓      |
| 22       | 1 PC REAR BUMPER <i>Distorted</i>              | 452.20     | ✓      |
| 23       | 1 PC REAR BUMPER REINFORCEMENT <i>Dented</i>   | 316.60     | ✓      |
| 24       | 2 PCS REAR BUMPER SIDE RETAINER <i>new</i>     | 263.80     | ✓      |
| 25       | 2 PCS REAR BUMPER SMALL RETAINER <i>new</i>    | 102.20     | ✓      |
| 26       | 1 PC REAR BUMPER REFLECTOR - RH <i>cracked</i> | 162.80     | ✓      |
| 27       | 1 PC BONNET <i>Dented</i>                      | 853.70     | ✓      |
| 28       | 2 PCS BONNET HINGE <i>Bent</i>                 | 175.80     | ✓      |
| 29       | 1 PC BONNET LOCK <i>Dented</i>                 | 195.10     | ✓      |

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST: 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY #07-16  
AIG BUILDING, SINGAPORE 079120  
TEL: 64193000 FAX: 68357416  
ATTN: Motor Claim Department

Estimate No: EST2200115  
Date: 19 Apr 2022  
Veh Reg No: SMK5398H  
Make/Model: TOYOTA VIOS 1.5G (AUTO)  
Chasis No: MR2B23F3101171851  
Reg. Date: 15/04/2019  
Your Ref No: SKK3344A

Claim Type: Third Party  
Accident Date: 14/04/2022  
TP Veh Reg No: SKK3344A

## Estimate Repair Cost to Vehicle No :SMK5398H

| Quantity | Description                                          | List Price             | Amount    |
|----------|------------------------------------------------------|------------------------|-----------|
|          |                                                      | SS                     | SS        |
| 30       | 1 PC FRT BRACE PANEL <i>Best</i>                     | 128.80                 | ✓         |
| 31       | 1 PC FRT GRILLE <i>crushed</i>                       | <del>268.80</del>      | 65        |
| 32       | 1 PC FRT GRILLE EMBLEM <i>pc</i>                     | 72.20                  | ✓         |
| 33       | 1 PC FRT GRILLE EMBLEM BASE <i>crushed</i>           | 213.30                 | ✓         |
| 34       | 2 PCS FRT GRILLE CHROME <i>crushed</i>               | 122.80                 | ✓         |
| 35       | 1 PC FRONT TOP GRILLE GARNISH COVER <i>Delnd</i>     | 148.40                 | ✓         |
| 36       | 1 PC FRT GRILLE RUBBER <i>xt m</i>                   | 61.20                  | ✓         |
| 37       | 1 PC HEADLAMP LH <i>crushed</i>                      | 1,254.60               | ✓         |
| 38       | 1 PC HEADLAMP RH <i>crushed</i>                      | 1,254.60               | ✓         |
| 39       | 1 PC FRT BUMPER <i>Delnd</i>                         | 495.70                 | ✓         |
| 40       | 1 PC FRT BUMPER REINFORCEMENT <i>Best</i>            | 372.10                 | ✓         |
| 41       | 1 PC FRT BUMPER CENTRE GRILLE <i>Delnd</i>           | 212.70                 | ✓         |
| 42       | 1 PC FRT BUMPER BOTTOM GRILLE <i>Delnd</i>           | 388.20                 | ✓         |
| 43       | 1 PC FRT TOWING COVER <i>xt m</i>                    | 48.50                  | ✓         |
| 44       | 1 PC FRT BUMPER RH DAYLIGHT <i>nt</i>                | 279.80                 | ✓         |
| 45       | 1 PC FRT BUMPER LH DAYLIGHT <i>nt</i>                | 279.80                 | ✓         |
| 46       | 1 PC RADIATOR UNDER COVER <i>xt m</i>                | 209.30                 | ✓         |
| 47       | 1 PC AIR CONDENSER <i>Delnd</i>                      | 935.90                 | ✓         |
| 48       | 3 PC AIRCON CONDENSER RH SIDE GARNISH <i>crushed</i> | <del>5100</del> 154.80 | ✓         |
|          | <del>Wiper Panel Side Garnish 43</del> <i>xt</i>     | 15,245.70              |           |
|          |                                                      | Less 25%               | 3,811.43  |
|          |                                                      |                        | 11,434.36 |
|          | Special Net                                          |                        |           |
| 49       | 1 PC REAR NUMBER PLATE <i>Delnd</i>                  | 50.00                  | ✓         |
| 50       | 1 PC REVERSE CAMERA <i>xt m</i>                      | 480.00                 | ✓         |
| 51       | 1 SET BOOT LID TRIM CLIPS <i>xt m</i>                | 60.00                  | ✓         |
| 52       | 1 SET REAR FENDER TRIM CLIPS RH <i>xt m</i>          | <del>60.00</del> 30    |           |
| 53       | 1 SET REAR FENDER TRIM CLIPS LH <i>xt m</i>          | 60.00                  | ✓         |
| 54       | 1 PC REAR WINDSCREEN SEAL <i>xt m</i>                | 60.00                  | ✓         |
| 55       | 1 PC REAR WINDSCREEN SEALANT <i>xt m</i>             | 60.00                  | ✓         |
| 56       | 1 SET REAR PANEL TRIM CLIPS <i>xt m</i>              | <del>40.00</del> 20    |           |



# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883  
TEL: 6742 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY #07-16  
AIG BUILDING, SINGAPORE 079120  
TEL: 64193000 FAX: 68357416  
ATTN: Motor Claim Department

Estimate No: EST2200115  
Date: 19 Apr 2022  
Veh Reg No: SMK5398H  
Make/Model: TOYOTA VIOS 1.5G (AUTO)  
Chasis No: MR2B23F3101171851  
Reg. Date: 15/04/2019  
Your Ref No: SKK3344A

Claim Type: Third Party  
Accident Date: 14/04/2022  
TP Veh Reg No: SKK3344A

## Estimate Repair Cost to Vehicle No :SMK5398H

| Quantity | Description                                                                                                   | List Price          | Amount   |
|----------|---------------------------------------------------------------------------------------------------------------|---------------------|----------|
|          |                                                                                                               | SS                  | SS       |
| 57       | 1 SET REVERSE SENSORS <i>Dented</i>                                                                           | <del>400.00</del>   | 360.     |
| 58       | 1 SET REAR BUMPER CLIPS <i>new</i>                                                                            | <del>40.00</del>    | 30       |
| 59       | 1 SET FRT GRILLE CLIPS <i>new</i>                                                                             | <del>60.00</del>    | 20       |
| 60       | 1 SET FRT BUMPER SMALL GRILLE CLIPS <i>new</i>                                                                | <del>40.00</del>    | 10       |
| 61       | 1 SET FRT BUMPER GRILLE CLIPS <i>new</i>                                                                      | <del>40.00</del>    | 30       |
| 62       | 1 PC FRT NUMBER PLATE <i>Bent</i>                                                                             | 50.00               | —        |
| 63       | 1 SET RADIATOR UNDER COVER CLIP <i>new</i>                                                                    | <del>60.00</del>    | 4        |
|          |                                                                                                               | 1,560.00            | 1,560.00 |
|          | <b>Labour</b>                                                                                                 |                     |          |
| 64       | 1 TO CHECK WIRING                                                                                             | <del>50.00</del>    | 30       |
| 65       | 1 TO REMOVE AND REFIT REAR WINDSCREEN                                                                         | 120.00              | 4        |
| 66       | 1 TO REMOVE AND REFIT SEAT CUSHION & TRIM                                                                     | <del>250.00</del>   | 60       |
| 67       | 1 TO REMOVE AND REFIT REVERSE CAMERA                                                                          | <del>80.00</del>    | 50       |
| 68       | 1 TO REMOVE AND REFIT REVERSE SENSOR                                                                          | <del>80.00</del>    | 50       |
| 69       | 1 TO SPRAY PANEL SEALANT                                                                                      | <del>120.00</del>   | 60       |
| 70       | 1 (REAR) TO SPRAY PAINTING                                                                                    | <del>1,500.00</del> | 100      |
| 71       | 1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS. | <del>1,500.00</del> | 1100     |
| 72       | 1 TO CHECK WIRING                                                                                             | <del>50.00</del>    | 30       |
| 73       | 1 TO REFILL AIRCON GAS                                                                                        | <del>120.00</del>   | 60       |
| 74       | 1 TO SPRAY PANEL SEALANT                                                                                      | 100.00              | 4        |
| 75       | 1 (FRONT) TO SPRAY PAINTING                                                                                   | <del>1,200.00</del> | 750      |
| 76       | 1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS. | <del>1,200.00</del> | 800      |
|          |                                                                                                               | 6,370.00            | 6,370.00 |

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY #07-16  
AIG BUILDING, SINGAPORE 079120  
TEL: 64193000 FAX: 68357416  
ATTN: Motor Claim Department

Claim Type: Third Party  
Accident Date: 14/04/2022  
TP Veh Reg No: SKK3344A

Estimate No: EST2200115  
Date: 19 Apr 2022  
Veh Reg No: SMK5398H  
Make/Model: TOYOTA VIOS 1.5G (AUTO)  
Chasis No: MR2B23F3101171851  
Reg. Date: 15/04/2019  
Your Ref No: SKK3344A


## Estimate Repair Cost to Vehicle No :SMK5398H

| Quantity | Description          | List Price | Amount        |
|----------|----------------------|------------|---------------|
|          |                      | SS         | SS            |
|          | Total                |            | S\$ 19,364.36 |
|          | Add GST @ 7%         |            | 1,355.51      |
|          | Total Amount Payable |            | S\$ 20,719.87 |

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND SEVEN HUNDRED NINETEEN AND CENTS EIGHTY SEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Li

L/S 19/04/22.

11 Days.

total: 13944.55

L/S: (P/P)

P/P.

13944.15