

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2200115
Date: 19 Apr 2022
Veh Reg No: SMK5398H
Make/Model: TOYOTA VIOS 1.5G (AUTO)
Chasis No: MR2B23F3101171851
Reg. Date: 15/04/2019
Your Ref No: SKK3344A

Claim Type: Third Party
Accident Date: 14/04/2022
TP Veh Reg No: SKK3344A

Estimate Repair Cost to Vehicle No :SMK5398H

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC BOOT LID	758.70	
2	2 PCS BOOT LID HINGE	155.60	
3	1 PC BOOT LID LOGO	52.20	
4	1 PC BOOT LID "VIOS" EMBLEM	43.60	
5	1 PC BOOTLID "G" EMBLEM	42.20	
6	1 PC BOOT LID LOCK	360.40	
7	1 PC BOOT LID LOCK CHECKER	49.20	
8	1 PC BOOT LID RUBBER	166.40	
9	1 PC BOOT LID LAMP LH	230.30	
10	1 PC BOOT LID LAMP RH	230.30	
11	1 PC BOOT LID TRIM	187.70	
12	1 PC REAR FENDER RH	804.80	
13	1 PC REAR FENDER TRIM RH	355.90	
14	1 PC TAIL LAMP - RH	397.50	
15	1 PC TAIL LAMP LH	397.50	
16	1 PC REAR LH FENDER TRIM	355.90	
17	1 PC REAR PANEL	680.00	
18	1 PC REAR PANEL TRIM	232.20	
19	1 PC REAR PANEL ANTENNA	167.20	
20	1 PC SPARE TYRE PANEL RH SPONGE	128.80	
21	1 PC SPARE TYRE PANEL LH SPONGE	128.80	
22	1 PC REAR BUMPER	452.20	
23	1 PC REAR BUMPER REINFORCEMENT	316.60	
24	2 PCS REAR BUMPER SIDE RETAINER	263.80	
25	2 PCS REAR BUMPER SMALL RETAINER	102.20	
26	1 PC REAR BUMPER REFLECTOR - RH	162.80	
27	1 PC BONNET	853.70	
28	2 PCS BONNET HINGE	175.80	
29	1 PC BONNET LOCK	195.10	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 AIG BUILDING, SINGAPORE 079120
 TEL: 64193000 FAX: 68357416
 ATTN: Motor Claim Department

Estimate No: EST2200115
Date: 19 Apr 2022
Veh Reg No: SMK5398H
Make/Model: TOYOTA VIOS 1.5G (AUTO)
Chasis No: MR2B23F3101171851
Reg. Date: 15/04/2019
Your Ref No: SKK3344A

Claim Type: Third Party
Accident Date: 14/04/2022
TP Veh Reg No: SKK3344A

Estimate Repair Cost to Vehicle No :SMK5398H

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
30	1 PC FRT BRACE PANEL	128.80	
31	1 PC FRT GRILLE	268.80	
32	1 PC FRT GRILLE EMBLEM	72.20	
33	1 PC FRT GRILLE EMBLEM BASE	213.30	
34	2 PCS FRT GRILLE CHROME	122.80	
35	1 PC FRONT TOP GRILLE GARNISH COVER	148.40	
36	1 PC FRT GRILLE RUBBER	61.20	
37	1 PC HEADLAMP LH	1,254.60	
38	1 PC HEADLAMP RH	1,254.60	
39	1 PC FRT BUMPER	495.70	
40	1 PC FRT BUMPER REINFORCEMENT	372.10	
41	1 PC FRT BUMPER CENTRE GRILLE	212.70	
42	1 PC FRT BUMPER BOTTOM GRILLE	388.20	
43	1 PC FRT TOWING COVER	48.50	
44	1 PC FRT BUMPER RH DAYLIGHT	279.80	
45	1 PC FRT BUMPER LH DAYLIGHT	279.80	
46	1 PC RADIATOR UNDER COVER	209.30	
47	1 PC AIR CONDENSER	935.90	
48	1 PC AIRCON CONDENSER RH SIDE GARNISH	51.60	
		15,245.70	
		Less 25%	
		3,811.43	11,434.36
	Special Net		
49	1 PC REAR NUMBER PLATE	50.00	
50	1 PC REVERSE CAMERA	480.00	
51	1 SET BOOT LID TRIM CLIPS	60.00	
52	1 SET REAR FENDER TRIM CLIPS RH	60.00	
53	1 SET REAR FENDER TRIM CLIPS LH	60.00	
54	1 PC REAR WINDSCREEN SEAL	60.00	
55	1 PC REAR WINDSCREEN SEALANT	60.00	
56	1 SET REAR PANEL TRIM CLIPS	40.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2200115
Date: 19 Apr 2022
Veh Reg No: SMK5398H
Make/Model: TOYOTA VIOS 1.5G (AUTO)
Chasis No: MR2B23F3101171851
Reg. Date: 15/04/2019
Your Ref No: SKK3344A

Claim Type: Third Party
Accident Date: 14/04/2022
TP Veh Reg No: SKK3344A

Estimate Repair Cost to Vehicle No :SMK5398H

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
57	1 SET REVERSE SENSORS	400.00	
58	1 SET REAR BUMPER CLIPS	40.00	
59	1 SET FRT GRILLE CLIPS	60.00	
60	1 SET FRT BUMPER SMALL GRILLE CLIPS	40.00	
61	1 SET FRT BUMPER GRILLE CLIPS	40.00	
62	1 PC FRT NUMBER PLATE	50.00	
63	1 SET RADIATOR UNDER COVER CLIP	60.00	
		1,560.00	1,560.00
	Labour		
64	1 TO CHECK WIRING	50.00	
65	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	
66	1 TO REMOVE AND REFIT SEAT CUSHION & TRIM	250.00	
67	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00	
68	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	
69	1 TO SPRAY PANEL SEALANT	120.00	
70	1 (REAR) TO SPRAY PAINTING	1,500.00	
71	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,500.00	
72	1 TO CHECK WIRING	50.00	
73	1 TO REFILL AIRCON GAS	120.00	
74	1 TO SPRAY PANEL SEALANT	100.00	
75	1 (FRONT) TO SPRAY PAINTING	1,200.00	
76	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00	
		6,370.00	6,370.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 14/04/2022
TP Veh Reg No: SKK3344A

Estimate No: EST2200115
Date: 19 Apr 2022
Veh Reg No: SMK5398H
Make/Model: TOYOTA VIOS 1.5G (AUTO)
Chasis No: MR2B23F3101171851
Reg. Date: 15/04/2019
Your Ref No: SKK3344A

Estimate Repair Cost to Vehicle No :SMK5398H

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Total		S\$ 19,364.36
	Add GST @ 7%		1,355.51
	Total Amount Payable		<u><u>S\$ 20,719.87</u></u>

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND SEVEN HUNDRED NINETEEN AND CENTS EIGHTY SEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE