

CARSMITH PRIVATE LIMITED

Bartley Biz Centre 13 Kaki Bukit Road 4 #01-20 Singapore 417807

Tel: 9619 5936 / Email: info@speedwerk.biz

LJK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

VEHICLE NO: SNC5684L

MAKE & MODEL: INFINITI Q30

DOA: 15 April 2022

CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
REAR BUMPER X Repair	1	\$ 1,740.00	
REAR BUMPER RETAINER LH X NN	1	\$ 130.00	
REAR BUMPER RETAINER RH X NN	1	\$ 130.00	
REAR BUMPER LOWER GARNISH ✓ DE	1	\$ 889.00	650
TOW COVER X NN	1	\$ 76.00	
REAR BUMPER REFLECTOR LH X NN	1	\$ 89.00	
REAR BUMPER REFLECTOR RH X NN	1	\$ 89.00	
REAR BUMPER REINFORCMENT X NN	1	\$ 509.00	
PD SENSOR X NN	4	\$ 700.00	
SENSOR HOLDER X NN	4	\$ 120.00	

\$ 4,472.00

LESS 10%

\$ 447.20

SUB TOTAL

\$ 4,024.80

585

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR BUMPER CLIPS X NN	1 SET	\$ 40.00	
SUB TOTAL		\$ 40.00	

LABOUR	QTY	PRICE (\$)	REMARKS
TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	1	\$ 600.00	200
TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS	1	\$ 100.00	X NN
TO REMOVE AND RENEW REAR REVERSE SENSOR	1	\$ 120.00	30
REMOVE AND STRAIGHTEN REAR EXHAUST	1	\$ 150.00	X NN
SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY BOOTLID, REAR BUMPER, REAR END PANEL AND OTHER AFFECTED AREAS.	1	\$ 600.00	200

SUB TOTAL

\$ 1,570.00

1015

GRAND TOTAL

\$ 5,634.80

-20%: 800

2 Days

Lumpsum repair

After repair photos