

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: EU 71712

at Workshop m/s

of

Insured: SML 8753R

Policy No. _____

Claims No. DMCF220016H

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$28k.

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

715C

Vehicle: IN / OUT

Date: _____ Person Contacted: LIA 822075

Veh No: EU 71712 Yr Regn: 23/06/14

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 3 c.c. 1496

Colour: S. hr A/C: Insured / Std / NI / NA

Sp. Reading: 214363 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BM 42A8E0128351

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 19/04/22 D.O.I. 20/4/22

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear 1/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 27 11 50

N244 85925 have GIA

28/4/22 4.5pm \$2700 in Road Acc. CRD \$6075.60, 69%

28/4/22 12.45pm revised to ECICS via Merimen.

Date/Time, File Pass to?

1) 28/4 12.45pm ☐ : Preli. Report☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Report Format: MER-TP

Lump Sum / I.B.I. (\$) 2700

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

TOTAL

submit to ins

not Authorized
2014/22
2/s \$2700
4 days

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 20006262D

VEHICLE No: EU 7171Z

1PC	REAR BUMPER	DD/70-1	\$1,061.30	50% s/n 530.65
1PC	REAR BUMPER BEAM	3erf	\$537.30	✓
1PC	REAR BUMPER REFLECTOR N/S	cr	\$48.50	✓
2PCS	REAR BUMPER SIDE RETAINERS	@\$46.50 n/s cr	\$93.00	1pc
1SET	REAR BUMPER CLIPS	nee	\$50.00	✓
1SET	REAR BUMPER REVERSE SENSOR	shorted	\$250.00	✓
1SET	REAR BUMPER LICENCE PLATE LAMP	1a	\$139.20	x
1PC	REAR LICENCE PLATE W/HOLDER	1a	\$50.00	x
1PC	REAR END PANEL	DD	\$435.70	✓
1PC	REAR END PANEL TOP GARNISH	1a	\$262.30	x
1PC	TAILLAMP N/S	suc	\$680.20	x
1PC	BOOTLID	1a	\$1,248.30	x
1PC	BOOTLID REAR LOGO	1a	\$66.80	x
1PC	BOOTLID 'MAZDA' EMBLEM	1a	\$52.00	x
1PC	REAR FENDER N/S	R	\$971.00	x
			\$5,945.60	

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REVERSE SENSOR	\$80.00	50
TO TRANSFER BOOTLID MECHANISM	1a \$80.00	x
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO SPRAY RUST PROOFING	\$50.00	✓
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,200.00	800
TO PUTTY & SPRAY PAINTING	\$1,200.00	750
TOTAL	\$8,725.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2- 1368
207
2-1094.40
s.n-530.65
2- 1750.00
3375.25
207
2700