



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRES SINGAPORE 239924			Ref: CS/AGI22003672/Tvy3s2 Date: 27/05/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLM 4071H	Veh. Inspected	SGW 6779T	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10014807/JM	Excess (\$)	0.00	
Assign From	SHAFAWATI MD RABU	Assign Date	20/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA YARIS	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	MR054HY9104020741	Colour	SILVER	
Odometer	124979 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/45 R16	TOURADOR	6 mm	
L/H Front Tyre	205/45 R16	TOURADOR	6 mm	
R/H Rear Tyre	205/45 R16	TOURADOR	6 mm	
L/H Rear Tyre	205/45 R16	TOURADOR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/04/2022	Inspection Date	21/04/2022	
Survey held at	M-TECH MOTOR SERVICES BLK 9005 TAMPINES STREET 93 #01-252, TAMPINES INDUSTRIAL PARK A SINGAPORE 528839			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	