

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

ROC:53360061L

GST:53360061L

QT22/PA6977Y/TPC

Budget Direct Insurance
190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore 239924

QUOTATION

Dear Sir,

Cost of Repair to Vehicle PA6977Y

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Front RH bumper / BR	1	1,550.00	1,550.00 /
2.	Front RH bumper bracket / M	1	385.00	385.00 /
3.	Front RH headlamp / BR	1	1,750.00	1,750.00 1500 /
4.	Front RH headlamp structure / BJ	1	730.00	730.00 500 /
5.	Front RH small compartment cover panel / M	1	1,300.00	1,300.00 /
6.	Front panel / BR	1	3,800.00	3,800.00 3500 /
7.	Front windscreen moulding / NEC	1	680.00	680.00 / nett
8.	Sealant / NEC	8	40.00	320.00 / nett
9.	ERP / NEC	1	26.00	26.00 / nett
10.	Labour to remove front windscreen to assist repair	1	1,000.00	1,000.00 /
11.	Labour charges	1	1,500.00 1200	1,500.00
12.	Check wiring	1	50.00 30	50.00
13.	Spray painting with design and multi colors	1	1,500.00 1200	1,500.00
SUB-TOTAL				S\$14,591.00


- Price before 7% gst

Steve (LKK)

22/4/21, 10.49

Thank you

Yours faithfully,

Winnie Chai
HP: 9850-9666

W AL
L/S
W AL Y
7 Y

P-8735

-10%

7861.50

n-1026

L-2430

= 11,317.50

L/S - 9054

= 9050