



Your Ref : 22.30287

Date: 17<sup>th</sup> Feb 2023

Our Ref : CS/ASM22003677/Rpa3q2

**M/s HSBC LIFE (SINGAPORE) PTE LTD**  
C/O SEAH ONG & PARTNERS LLP  
36 ROBINSON ROAD #12-03 CITY HOUSE  
SINGAPORE 068877  
(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SJH 5794Z**  
**INSURED VEHICLE: SKD 187T**  
**ACCIDENT ON 16/04/2022**

Instruction was received to inspect the vehicle Reg. No. SJH 5794Z. The inspection was conducted on 21/04/2022 at the premises of M/s J.E.W Auto Pte Ltd, 60 Jalan Lam Huat #03-72 Carros Centre, Singapore 737869.

The following vehicle information was recorded:

Registration Number	: SJH 5794Z
Make/Model	: SUZUKI SWIFT 1.3 AT
Year of Registration	: 2008
Body Colour	: BLUE
Chassis Number	: JSAEZC11S00407088
Engine Capacity	: 1328 cc
Speedometer Reading	: -

The vehicle sustained damages at the front o/s portion & n/s body. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as “**uneconomical Total Loss**”.

Market Value	S\$ 11,500.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 4,495.00)
Nett Liability	S\$ 7,005.00
	=====

Vehicle Inspected By:



MOHAMMED RASUL BIN MOHD YUNUS  
Automotive Assessor



K.K.LAU  
MSc(Eng M), B Eng(Hons), PEng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.