

# WINCAR AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200714616M  
GST Registration No. : 200714616M

KWEK SEOW KEW  
1 MARINE VISTA #07-77  
SINGAPORE 449025

Contact : 96658802

TP SMRT.  
Hui Rong.

## TAX INVOICE

Repair Code : CLM15501  
Date in : 19/04/2022  
Vehicle Num. : SLX1913R  
Model : TOYOTA CAMRY 2.0 AUTO  
Chassis/Eng# : MR053DK5100112774/6ARP390405

### Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Repis</i>	1	1213.60	<i>X.</i> 1,213.60
REAR BOOTLID '2.0' EMBLEM	1	37.80	<i>✓</i> 37.80
REAR BOOTLID 'CAMRY' EMBLEM	1	48.50	<i>✓</i> 48.50
REAR BOOTLID 'D-4S' EMBLEM	1	43.50	<i>✓</i> 43.50
REAR BOOTLID 'LOGO' EMBLEM	1	50.70	<i>✓</i> 50.70
REAR BOOTLID MECHANISM LOCK <i>Not Nec</i>	1	423.30	<i>X</i> 423.30
REAR BOOTLID WEATHER STRIP <i>Not Nec</i>	1	206.40	<i>X.</i> 206.40
REAR BUMPER <i>Dehd</i>	1	695.80	<i>✓</i> 695.80
REAR BUMPER LOWER LID <i>At</i>	1	204.50	<i>✓</i> 204.50
REAR BUMPER REFLECTOR L/R <i>Not Nec</i>	2	63.40	<i>X.</i> 126.80
REAR BUMPER REINFORCEMENT <i>Dented</i>	1	423.90	<i>✓</i> 423.90
REAR BUMPER REVERSE SENSOR <i>2 pieces dented.</i>	4	392.80	<i>500.</i> 1,571.20
REAR BUMPER REVERSE SENSOR HOLDER <i>Not Nec</i>	4	21.60	<i>✓</i> 86.40
REAR BUMPER SIDE RETAINER L/R <i>Not Nec</i>	2	117.40	<i>X</i> 234.80
REAR BUMPER UNDER COVER <i>Not Nec</i>	1	436.40	<i>X.</i> 436.40
REAR END PANEL <i>INNER TOP Garnish Dehd</i>	1	329.30	<i>X.</i> 329.30
REAR END PANEL <i>Repis</i>	1	710.40	<i>X.</i> 710.40
REAR END PANEL INNER TOP GARNISH CLIPS <i>Not Nec</i>	1	5.50	<i>✓</i> 5.50

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200714616M  
GST Registration No. : 200714616M

KWEK SEOW KEW  
1 MARINE VISTA #07-77  
SINGAPORE 449025

Contact : 96658802

## TAX INVOICE

Repair Code : CLM15501

Date in : 19/04/2022

Vehicle Num. : SLX1913R

Model : TOYOTA CAMRY 2.0 AUTO

Chassis/Eng# : MR053DK5100112774/6ARP390405

REAR TAILLAMP L/R	2	517.10	1,034.20
REAR TAILLAMP LOWER BRACKET L/R	2	117.40	234.80
Subtotal before discount			8,117.80
Percentage discount 25%			2,029.45
Sub-total 1			6,088.35
REAR BUMPER CLIPS - SET	1	80.00	80.00
Subtotal before discount			80.00
Percentage discount 0%			0.00
Sub-total 2			80.00
Parts-total			6,168.35

## LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	80.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	500.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	900.00
To apply anti-rust chemical on repaired and replaced panel.	100.00
To Transfer Rear Bootlid Mechanism Lock Outer Handle Reflector n other attachment parts.	80.00
Labour Total	2,160.00
Parts & Labour Total	8,328.35

2859.43

total: 2878.42  
4/5: 2.31c ✓  
03 Days

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: