

**ACE AUTOLUTION PTE LTD**

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

JN1TB AE12Z082113.

TP Sampo

Hui Rong

April 22.

Page No. 1

Vehicle No. SKV9053S NISSAN NOTE

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	FRONT BUMPER <i>Deformed.</i>		680.00	✓ 454.90
1	FRONT BUMPER REINFORCEMENT <i>Not Rec</i>		710.00	X.
1	FRONT BUMPER SPONGE <i>Cracked</i>		598.40	198.30
1	FRONT BUMPER LOGO <i>Rec</i>		97.40	✓
1	FRONT BUMPER RETAINER LH&RH @ 65.00 <i>Not Rec</i>		130.00	X.
1	FRONT HEADLAMP LH & RH @ 850.00 <i>Cracked</i>		1700.00	✓
1	FRONT BONNET <i>Rec</i>		1273.80	X
1	FRONT BONNET LOCK <i>Not Rec</i>		185.60	X.
1	FRONT GRILLE WITH CHROME <i>Cracked</i>		338.90	✓
1	FRONT SUPPORT PANEL TOP <i>Not Rec</i>		455.20	X
1	FRONT SUPPORT PANEL LOWER		325.10	X.
1	FRONT PANEL CENTER GARNISH <i>Deformed</i>		394.50	202
1	FRONT AIRCON CONDENSOR <i>Warpped.</i>		1044.80	696.60
1	FRONT INTER COOLER <i>Not Rec</i>		1137.10	X.
1	FRONT BUMPER FOGLAMP LH&RH @ 195.00 <i>Not Rec</i>		390.00	X
1	FRONT BUMPER TOW COVER <i>Not Rec</i>		91.00	X.
			9351.80	
10% less			30%	2805.54
				6546.26
SPECIAL NETT ITEMS				
1 SET	FRONT CAR PLATE WITH HOLDER <i>Not Rec</i>		70.00	X
1	FRONT BUMPER CLIPS <i>Rec</i>		100.00	30
1	FRONT PANEL CENTER GARNISH CLIPS <i>Rec</i>		100.00	23
1	FRONT GRILLE WITH CHROME CLIPS <i>Rec</i>		100.00	20.
1	FRONT BONNET INSULATOR CLIPS <i>Not Rec</i>		100.00	X
1	Coolant <i>Not Rec</i>		70.00	X
Total Parts			7086.26	

3688.10

3319.29

70.



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SKV9053S NISSAN NOTE

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	OUR ASSESSMENT (\$)
1	LABOUR To remove the affected parts & fittings to commence repairs and replace damaged parts	1800.00 500	
2	To supply paint materials, expandable items & putty, re-spray paint on parts replaced	1600.00 400	
3	To remove and refix wiring at damaged areas	180.00 30	
4	To remove and replace condenser and intercooler	150.00 60	
5	To perform anti rust treatment on affected areas	150.00 X	
6	To conduct water seepage test	100.00 X	
7	To remove and replace front headlamp	150.00 50	
Labour Total :		4130.00	
TOTAL (PARTS & LABOUR):		11216.26	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 4429.29

4/s: 3.5K.

04 Days.

3.5K