





# CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE #01-60/62, SIN MING ROAD, SINGAPORE 575643  
TEL: 6453 1235, 6452 0850 FAX: 6453 7944  
24hrs Towing Services Tel 9823 9898  
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

CHINA TAIPING INSURANCE (S) PTE LTD  
NO. 3  
ANSON RD  
SPRINGLEAF TOWER  
SINGAPORE 079909

*Not Authorized  
Return B4 gain*

Estimate : QUOT202204-000722(00)

Date : 21/04/2022

Vehicle No. : SML4892Z

Make/Model : HONDA FIT 1.3 GF CVT

Mileage (km) : 0

Chassis No. : GK31348604

Accident Date : 18/04/2022 00:00:00

Claim No. : SMD212E

Reference : JO202204-0932

Policy No. : D21MTPV01007269

Contact : -

Fax No. : 62247175

*14 days*

S/No	Particular	Quantity	Unit Price	Amount S\$
<b>LIST ITEMS :</b>				
1	Bonnet	1.0	573.20	573.20 ✓
2	Bonnet hinge	2.0	48.20	96.40 ✓
3	Bonnet lock	1.0	90.50	90.50 ✓
4	Bonnet top cover center	1.0	32.30	32.30 ✓
5	Bonnet top cover LH	1.0	32.30	32.30 ?
6	Bonnet top cover RH	1.0	101.20	101.20 ?
7	Bonnet seal	2.0	95.30	190.60 ✓
8	Wiper garnish	1.0	196.70	196.70 ✓
9	Wiper garnish side cover LH	1.0	68.20	68.20 ✓
10	Wiper garnish side cover RH	1.0	68.20	68.20 ✓
11	Front windscreen glass	1.0	1,556.40	1,556.40 X
12	Front windscreen glass moulding	1.0	128.60	128.60 X
13	Headlamp	2.0	622.30	1,244.60 ✓
14	Headlamp lower bracket	2.0	37.80	75.60 ✓
15	Front grille base	1.0	246.90	246.90 ✓
16	Front grille chrome top	1.0	224.10	224.10 ✓
17	Front grille chrome bottom	1.0	202.80	202.80 ✓
18	Front grille logo	1.0	35.20	35.20 ✓
19	Front grille top cover	1.0	15.40	15.40 ✓
20	Front bumper	1.0	538.10	538.10 ✓
21	Front bumper tow cover	1.0	25.50	25.50 ✓
22	Front bumper lower grille	1.0	137.90	137.90 ✓
23	Front bumper side strip	2.0	18.50	37.00 ✓
24	Front bumper side cover	2.0	49.10	98.20 ✓
25	Front bumper reinforcement	1.0	227.10	227.10 ✓
26	Front bumper clip	12.0	4.20	50.40 ✓
27	Front fender	2.0	368.50	737.00 ✓
28	Front fender inner shield	2.0	85.10	170.20 ✓
29	Front fender inner shield clip	16.0	4.20	67.20 ✓
30	Support panel	1.0	550.10	550.10 ✓
31	Air con condenser	1.0	810.20	810.20 ✓
32	Air con discharge pipe	1.0	210.30	210.30 ?
33	Air con suction pipe	1.0	178.20	178.20 ?
34	Air con liquid pipe	1.0	175.10	175.10 ?

CONTINUE NEXT PAGE



# CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT202204-000722(00)

Date : 21/04/2022

Vehicle No. : SML4892Z

Make/Model : HONDA FIT 1.3 GF CVT

Mileage (km) : 0

Chassis No. : GK31348604

Accident Date : 18/04/2022 00:00:00

Claim No. : SMD212E

Reference : JO202204-0932

Policy No. : D21MTPV01007269

CHINA TAIPING INSURANCE (S) PTE LTD

NO. 3

ANSON RD

SPRINGLEAF TOWER

SINGAPORE 079909

Contact : -

Fax No. : 62247175

S/No	Particular	Quantity	Unit Price	Amount S\$	
35	Radiator	1.0	1,250.10	1,250.10	?
36	Radiator top hose	1.0	26.80	26.80	?
37	Radiator bottom hose	1.0	26.80	26.80	?
38	Fan cowling	2.0	125.50	251.00	?
39	Fan motor	2.0	318.20	636.40	?
40	Fan blade	2.0	78.20	156.40	?
41	Air intake manifold	1.0	<i>ndd ln</i> 389.40	389.40	✓
42	Air intake manifold vacuum hose	1.0	35.10	35.10	?
43	Air intake manifold batch	1.0	28.00	<i>me</i> 28.00	?
44	Air intake air duct	1.0	51.30	<i>nd</i> 51.30	✓
45	Air intake air duct guide	1.0	42.30	<i>nd</i> 42.30	✓
46	Radiator side air guide	2.0	<i>ols cm</i> 32.90	65.80	?
47	Support air guide	2.0	35.20	<i>dit</i> 70.40	?
48	Horn	1.0	49.60	49.60	?
49	Front grille support bracket	1.0	82.50	<i>nd</i> 82.50	✓
50	Washer tank	1.0	75.10	<i>nd</i> 75.10	✓
51	Washer motor	1.0	59.60	59.60	?
52	Washer filler neck	1.0	35.60	35.60	?
53	Coolant spare tank	1.0	83.10	83.10	?
54	Front bumper retainer	1.0	95.40	<i>dit</i> 95.40	✓
55	Bonnet insulator	1.0	94.50	<i>cm</i> 94.50	✓
56	Front RH fender inner intension panel	1.0	150.20	<i>R</i> 150.20	✓
57	Driver air bag	1.0	<i>Brny</i> 1,605.20	1,605.20	✓
58	Driver steering clock sping	1.0	289.90	<i>me</i> 289.90	✓
59	Passenger air bag	1.0	<i>Brny</i> 2,236.20	2,236.20	✓
60	Dashboard	1.0	718.20	<i>Tn</i> 718.20	✓
61	SRS ECU	1.0	747.60	<i>me</i> 747.60	✓
62	Front seat belt	2.0	535.10	<i>Tn</i> 1,070.20	✓
63	Front impact sensor	1.0	159.20	<i>me</i> 159.20	✓
64	Engine under cover	1.0	300.10	300.10	?
65	Front RH chassis member	1.0	628.30	<i>R</i> 628.30	X
66	Engine mounting - RH	1.0	172.30	172.30	?
67	Engine mounting - LH	1.0	260.20	260.20	?
68	Engine mounting - Rear	1.0	135.20	135.20	?

CONTINUE NEXT PAGE



# CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE #01-60/62, SIN MING ROAD, SINGAPORE 575643  
TEL: 6453 1235, 6452 0850 FAX: 6453 7944  
24hrs Towing Services Tel 9823 9898  
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

CHINA TAIPING INSURANCE (S) PTE LTD  
NO. 3  
ANSON RD  
SPRINGLEAF TOWER  
SINGAPORE 079909

Estimate : QUOT202204-000722(00)

Date : 21/04/2022

Vehicle No. : SML4892Z

Make/Model : HONDA FIT 1.3 GF CVT

Mileage (km) : 0

Chassis No. : GK31348604

Accident Date : 18/04/2022 00:00:00

Claim No. : SMD212E

Reference : JO202204-0932

Policy No. : D21MTPV01007269

Contact : -

Fax No. : 62247175

S/No	Particular	Quantity	Unit Price	Amount S\$
List Total :				21,460.30
20% Discount S\$				4,292.06
				<u>17,168.24</u>
<b>SPECIAL NET :</b>				
1	Front windscreen glass sealant	1.0	40.00	na 40.00 X
2	Battery	1.0	215.00	215.00 ?
3	Number plate	1.0	20.00	20.00
4	Number plate casing	1.0	25.00	CM 25.00 } ✓
SPECIAL NET Total S\$:				<u>300.00</u>
<b>LABOUR :</b>				
	- To remove and refit air intake manifold	1.0	80.00	80.00 501
	- To remove and refit air con components and recharge air con gas	1.0	100.00	100.00 —
	- To check wiring and lighting	1.0	60.00	60.00 201
	* To remove and refit front windscreen glass	1.0	150.00	na 150.00 X
	- To remove and refit air bags, dashboard, seat beat, and SRS ECU	1.0	380.00	380.00 2501
	- To put and realign front chassis member	1.0	280.00	280.00 ?
	- To use diagnostic computer to check and reset to default settings	1.0	280.00	280.00 ?
	* Towing charge	1.0	80.00	(Bill) 80.00 ?
	-To knock jackout damaged parts, panel beating,welding, align, refix and to renew accident parts	1.0	1,600.00	1,600.00 11001
	- Spray painting on affected & replace parts	1.0	1,600.00	1,600.00 14001
				<u>4,610.00</u>

### LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Page 3 of 3

Date:

Total S\$: 22,078.24

GST 7% S\$: 1,545.48

Amount Due S\$: 23,623.72

for CITY AUTO PTE LTD

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 18/04/2022 16:30 (SGT)  
Date of Accident ..... 18/04/2022 09:06 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... ALONG UPPER THOMSON ROAD  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SML4892Z  
INSURED/POLICYHOLDER  
Is company? ..... No  
Name Of Registered Owner ..... CHEN WEIJING  
NRIC No ..... SXXXX613G  
Email Address ..... wjchen0731@gmail.com  
Mobile Phone No ..... (Phone) +65-96520954  
Alternative Phone No ..... +65-96520954

## VEHICLE PARTICULARS

Manufacturer ..... Honda  
Model ..... Fit  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... -  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 1496

## INSURANCE COMPANY

Name of Insurance Company ..... Sompo Insurance Singapore Pte. Ltd.  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... D21MTPV01007269  
Cover Note Number ..... -

## DRIVER

Name of Driver ..... CHEN WEIJING  
NRIC No ..... SXXXX613G

SKETCH PLAN

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

**CITY AUTO PTE LTD**  
 Blk 8 Sin Ming Road  
 #01-58/60/62 Sin Ming Ind Est  
 Singapore 575643  
 Tel: 6453 1234 Fax: 6453 7944  
 (Claims Section)




Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

**Sketch Plan**



A - SML 4892Z

B - SMD 212E



**SINGAPORE  
POLICE FORCE**

T/20220418/2045

2 of 3

Report No. T/20220418/2045

Police Station Of Origin:  
Sengkang N.P.C  
2 Sengkang Square #01-02 SINGAPORE  
545025  
Tel No: 1800-343 8999

CONTINUATION OF REPORT

<b>Details of Person Involved</b>		Use of Pedestrian Crossing: NA	
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL			
<b>Driver</b>		ID No.	S8561613G
Name	CHEN WEIJING	Contact No.	96520954
Related Vehicle	SML4892Z (Car)	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Hospital/Clinic	NIL	Date Discharge	NIL
Date Treatment	NIL	Degree of Injury	NIL
No. of Days granted Medical Leave	NIL		

**Brief Details.**

I am Chen Weijing, NRIC S8561613G, DOB 31/07/1985 residing at Block 298A Punggol Place #13-891 Singapore 821289

On 18/04/2022 at about 0906hrs, I was driving my vehicle bearing the registration number SML4892Z (V1) along Upper Thomson Road when I was involved in an accident with another vehicle bearing the registration number SMD212E (V2).

I wish to inform that at that point in time, I had no passengers in my vehicle and I was driving along the leftmost lane of the three lane road and approaching a yellow-box on the said road along Upper Thomson nearby the junction of Jin Angklong. I also observed that there is no vehicles to the front of mine and proceeded ahead.

That was when V2 came out from the right turn pocket area from the opposite side of the road and I was unable to stop in time and my vehicle collided the the left portion of V2. I wish to inform that both my vehicle airbags were deployed due to the collision and my vehicle was damaged. The stop sign along the said road was also damaged due to V2 colliding into it. I also observed that there is a stop line located at the right turn pocket that V2 had came out from.

At that point in time, no injuries were reported at scene and traffic police also came down to attend to the accident. My SD card from my in-car camera was seized by the Traffic Police and I was advised to lodge a Traffic Accident report. However, at this point in time, I am starting to feel some pain due to the accident and will be going to see a doctor to get myself assessed. The cost of damage is yet to be determined. That is all.