



TRANS EUROAKRS PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
CASH REPAIR QUOTATION



Not Authorized
MR 90096608
28/4/22
the photo. After repair
including parts.
13 days.

				WIP : TBA	
				DATE: 1-Apr-22	
				REPAIR DAY(S) 15	
VEH NO :	SMA3008A	DATE IN :		CONTACT PERSON :	JESS
CHASSIS NO :	JM6GL1071J0146283	MILEAGE :		TYPE OF CLAIM :	CASH REPAIR
MODEL :	MAZDA 6	DATE REG.:	27-Apr-18		
NATURE OF WORKS					
DESCRIPTION	QTY	UNIT PRICE	1ST SUPP	PART NO	PRICES
1 BODY SIDE MIRROR RH	1	475.90		MGSB9-69-121A	475.90
2 BODY SIDE MIRROR LH	1	475.90		MGSB9-69-181A	475.90
3 GARNISH TRIANGLE RH	1	45.20		MGHP9-69-15YB	45.20
4 GARNISH TRIANGLE LH	1	45.20		MGHP9-69-16YB	45.20
5 MOULD(R),FRT.SASH'A'	1	139.00		MGHP9-50-981F	139.00
6 MOULD(L),FRT.SASH'A'	1	139.00		MGHP9-50-985E	139.00
7 MOULD(R),RR.SASH'A' rear	1	122.30		MGHK1-50-991H	122.30
8 MOULD(L),RR.SASH'A' rear	1	102.90		MGHK1-50-995G	102.90
9 GARNISH(R),C.PILLAR	1	224.00		MGHK1-50-N10C	224.00
10 GARNISH(L),C.PILLAR	1	191.10		MGHK1-50-N50C	191.10
11 CHROME MOULD(R),FRT.BELTLINE	1	96.00		MGHP9-50-640F	96.00
12 CHROME MOULD(L),FRT.BELTLINE	1	96.00		MGHP9-50-650F	96.00
13 CHROME MOULD(R),RR.BELTLINE	1	80.40		MGHK1-50-660E	80.40
14 CHROME MOULD(L),RR.BELTLINE	1	84.70		MGHK1-50-670E	84.70
15 GARNISH(R),FRT DR (Black)	1	62.40		MGHP9-50-M10D	62.40
16 GARNISH(L),FRT DR (Black)	1	62.40		MGHP9-50-M20D	62.40
17 GARNISH(R),REAR DR (Black)	1	87.20		MGHP9-50-M30D	87.20
18 GARNISH(L),REAR DR (Black)	1	97.70		MGHP9-50-M40D	97.70
19 GARNISH RHR DR	1	46.70		MGHK1-50-M50A	46.70
20 GARNISH LHR DR	1	41.60		MGHK1-50-M60A	41.60
21 GUARD STONE RH	1	17.40		MGHP9-50-4P2A	17.40
22 GUARD STONE LH	1	17.40		MGHP9-50-4R2A	17.40
23 FRT WINDSCREEN	1	1,499.40		MGRV6-63-900A	1,499.40
24 MOULD,WINDOW-FRT	1	65.10		MGHP9-50-601	65.10
25 RR WINDSCREEN	1	902.40		MGHK3-63-930E	902.40
26 MOULD,RR.WINDOW	1	117.10		MGHK1-50-611B	117.10
27 SPACER	1	12.80		MGJ5A-50-897	12.80
28 GLASS RH FRT DOOR	1	294.70		MGR7-58-510	294.70
29 GLASS LH FRT DOOR	1	294.80		MGR7-59-510	294.80
30 GLASS RH REAR DOOR	1	339.30		MGHK1-72-510C	339.30
31 GLASS LH REAR DOOR LH	1	339.30		MGHK1-73-510C	339.30
32 ARM,WIPER DRIVER	1	146.20		MG44N-67-321A	146.20

33	WIPER COVER GRILLE RH	1	297.50		MGJE8-50-7R0B	Dye	297.50	/
34	WIPER COVER GRILLE LH	1	302.00		MGJE8-50-7S0A	Dye	302.00	/
35	MLDG(R),FENDER-FRT	1	49.30		MGHP9-51-PB1A	Dye	49.30	/
36	MLDG(L),FENDER-FRT	1	49.30		MGHP9-51-PC1A	Dye	49.30	/
37	WEATHERSTRIP, TRUNK	1	135.60		MGHK1-56-951A	11	135.60	X
38	GLASS & HOLDER(R),BODY SIDE MIRROR	1	282.50		MB63C-69-1G1		282.50	?
39	GLASS & HOLDER(L),BODY SIDE MIRROR	1	282.50		MB63C-69-1G7		282.50	?
40	ARM,WIPER PASSENGER	1	170.60		MGKM1-67-321	Dye	170.60	/
41	WIPER BLADE RH	1	57.30		MK068-67-330A		57.30	?
42	WIPER BLADE LH	1	44.00		MK015-67-330		44.00	?
43	COVER WIPER	2	9.20		MGS1M-67-395		18.40	?

TOTAL PARTS

8,450.50

LESS 15%

1,267.58

TOTAL PARTS COST

7,182.93

Labour Description

PRICES

1	TO RESPRAY WHOLE CAR (EXTERIOR WITH SAME COLOUR CODE).	270.0	2,750.00
2	TO REPROGRAMME AFTER REPAIR.	100	150.00
3	SUNDRIES.	11 X	50.00
4	RENTAL CAR @ 160.00/DAY X 19 DAYS (INCLUDING SATURDAYS & SUNDAYS) >> REPAIR REQ 15 WORKING DAYS.		3,040.00

NOTES: QUOTATION NOT INCLUDED THE REPLACEMENT CAR FEE.

REMARKS:

THIS IS ONLY AS ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORM PRIOR BEFORE WE CARRIED OUT THE REPAIRS. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$200.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TOTAL LABOUR	5,990.00
TOTAL PARTS	7,182.93
TOTAL	13,172.93
GST 7%	922.10
GRAND TOTAL	14,095.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: