



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD C/O TOPLIS AND HARDING (S) PTE LTD 133 CECIL STREET #17-01A KECK SENG TOWER SINGAPORE 069535			Ref: CS/TPS22003682/Uvy3e2 Date: 02/08/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SMA 3008A	
Policy No.	Y226205	Coverage (\$)	0.00	
Claim No.	SNC22D200008	Excess (\$)	0.00	
Assign From	VICTOR FONG	Assign Date	20/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 6	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JM6GL1071J0146283	Colour	GREY	
Odometer	81608 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	BRIDGESTONE	8 mm	
L/H Front Tyre	225/55 R17	BRIDGESTONE	8 mm	
R/H Rear Tyre	225/55 R17	BRIDGESTONE	8 mm	
L/H Rear Tyre	225/55 R17	BRIDGESTONE	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE WHOLE VEHICLE. THE CAUSE OF DAMAGE DUE TO AFFECTED BY FINE SPRAY PAINTING DROPLETS. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/03/2022	Inspection Date	28/04/2022	
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			13 Working Days	