



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD C/O TOPLIS AND HARDING (S) PTE LTD 133 CECIL STREET #17-01A KECK SENG TOWER SINGAPORE 069535			Ref: CS/TPS22003683/Rqy3e2	
			Date: 23/09/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SKD 5157Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	SNC22D200008	Excess (\$)	0.00	
Assign From	VICTOR FONG	Assign Date	20/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 216I GT LED	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WBA2D920105K80932	Colour	WHITE	
Odometer	57956 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	CONTINENTAL	6 mm	
L/H Front Tyre	205/60 R16	CONTINENTAL	6 mm	
R/H Rear Tyre	205/60 R16	CONTINENTAL	6 mm	
L/H Rear Tyre	205/60 R16	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE WHOLE VEHICLE. THE CAUSE OF DAMAGE DUE TO AFFECTED BY FINE SPRAY PAINTING DROPLETS. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/03/2022	Inspection Date	22/04/2022	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			18 Working Days	