

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.	: b1 61254	Page No. : 1 of 6
Date Estimated	: 23/03/2022	
Prepared By	: Jack Ng Guo Ming	

- ESTIMATE REPAIR FOR - How Guo Jun (Hou Guojun) Blk 9 Boon Keng Road #19-156 Singapore 330009	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKD5157Y	WBA2D920105K80932	28/05/2018	216i GT	55825

DESCRIPTION	VALUE
Stripping and rebuilding for whole car spray painting including replacement of all door trims, seals, wiper arms. @850	2975 4,250.00
To respray whole vehicle. (due paint overspray)	12124 15,000.00
To check electrical wiring system for proper function.	168 177.00
To replace front windscreen glass. photo	545 574.00
To replace rear windscreen glass. photo	545 574.00
To conduct water leak tests.	142 150.00
To replace rear door fixed side window glass. photo	642 678.00
To replace rear side window glass. photo	642 678.00
To replace both left and right headlights. photo	795 837.00
To replace left and right tail-light photo	795 837.00
To replace front or rear PDC sensor wire harness including reset and conduct check for proper function.	253 268.00
To supply and install front windscreen solar film. photo	505 531.00
To supply and install rear windscreen solar film. photo	505 531.00
Sundries.	150 300.00

Total Labour 1: 25,379.00

DESCRIPTION	QTY	PRIC	VALUE
LH ROOF RAILS BLACK ?	1	482.80	482.80

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 61254
Date Estimated : 23/03/2022
Prepared By : Jack Ng Guo Ming

Page No. : 2 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKD5157Y	WBA2D920105K80932	28/05/2018	216i GT	55825

DESCRIPTION	QTY	PRIC	VALUE
RH ROOF RAILS BLACK <i>Rec</i>	1	482.80	482.80
PLAQUE 74MM <i>Rec</i>	1	72.85	72.85
LH SUPPORTING RING ?	1	59.00	59.00
LH SUPPORTING RING ?	1	59.00	59.00
RH SUPPORTING RING ?	1	59.00	59.00
RH SUPPORTING RING ?	1	59.00	59.00
LH EXTERIOR MIRROR W/O MOUNTING PAR <i>Rec</i>	1	496.10	496.10
LH EXTERIOR MIRROR W/O MOUNTING PAR <i>Rec</i>	1	496.10	496.10
RH EXTERIOR MIRROR W/O MOUNTING PAR <i>Rec</i>	1	496.10	496.10
RH EXTERIOR MIRROR W/O MOUNTING PAR <i>Rec</i>	1	496.10	496.10
FRT WINDSCREEN (KAFAS) <i>Rec</i> <i>photo</i>	1	826.50	826.50
LH DRIP MOULDING <i>Rec</i>	1	73.45	73.45
RH DRIP MOULDING <i>Rec</i> <i>photo</i>	1	73.45	73.45
REAR WINDOW (ESG) <i>Rec</i> <i>photo</i>	1	620.90	620.90
FRT LH DOOR COLUMN B COVER <i>Rec</i>	1	56.00	56.00
FRT RH DOOR COLUMN B COVER <i>Rec</i>	1	56.00	56.00
FRT LH DOOR WINDOW GLASS ? <i>repair</i>	1	209.05	209.05
FRT RH DOOR WINDOW GLASS ? <i>repair</i>	1	209.05	209.05
FRT LH DOOR EXTERIOR CHANNEL COVER <i>Rec</i>	1	100.30	100.30
FRT RH DOOR EXTERIOR CHANNEL COVER <i>Rec</i>	1	100.30	100.30
FRT LH DOOR WINDOW FRAME COVER (ALU) ?	1	60.50	60.50
FRT RH DOOR WINDOW FRAME COVER (ALU) ?	1	60.50	60.50
REAR LH DOOR WINDOW FRAME COVER (AL) ?	1	60.50	60.50
REAR RH DOOR WINDOW FRAME COVER (AL) ?	1	60.50	60.50
FRT LH DOOR WINDOW GUIDE <i>Rec</i> ?	1	123.20	123.20
FRT RH DOOR WINDOW GUIDE <i>Rec</i> ?	1	123.20	123.20
REAR LH DOOR COLUMN B COVER <i>Rec</i>	1	56.00	56.00
REAR RH DOOR COLUMN B COVER <i>Rec</i>	1	56.00	56.00
RR LH DOOR WINDOW GLASS ? <i>repair</i>	1	209.05	209.05
RR RH DOOR WINDOW GLASS ? <i>repair</i>	1	209.05	209.05
REAR LH DOOR OUTER WEATHERSTRIP (AL) <i>Rec</i>	1	100.30	100.30
REAR RH DOOR OUTER WEATHERSTRIP (AL) <i>Rec</i>	1	100.30	100.30
REAR LH DOOR WINDOW GUIDE ?	1	129.70	129.70
REAR RH DOOR WINDOW GUIDE ?	1	129.70	129.70
REAR LH SIDE WINDOW FIXED (ALU HOCH) <i>Rec</i>	1	301.05	301.05
REAR RH SIDE WINDOW FIXED (ALU HOCH) <i>Rec</i>	1	301.05	301.05
LH FIXED DOOR WINDOW ?	1	135.90	135.90
RH FIXED DOOR WINDOW ?	1	135.90	135.90
PLAQUE 82MM <i>Rec</i>	1	72.85	72.85
SET OF WIPER BLADES <i>Rec</i>	1	131.25	131.25
GROMMET <i>Rec</i>	1	6.85	6.85
WIPER ARM DRIVER'S SIDE <i>Rec</i>	1	91.15	91.15
WIPER ARM PASSENGER'S SIDE <i>Rec</i>	1	91.15	91.15
REAR WINDOW WIPER ARM <i>Rec</i>	1	72.90	72.90
REAR WIPER BLADE <i>Rec</i>	1	45.95	45.95
WIPER ARM COVER <i>Rec</i>	1	13.65	13.65
LH HEADLIGHT LED TECHNOLOGY ?	1	2,363.65	2,363.65
RH HEADLIGHT LED TECHNOLOGY ?	1	2,363.65	2,363.65
REAR LH LIGHT IN THE TRUNK LID ?	1	263.40	263.40

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

289, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 61254
Date Estimated : 23/03/2022
Prepared By : Jack Ng Guo Ming

Page No. : 3 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKD5157Y	WBA2D920105K80932	28/05/2018	2161 GT	55825

DESCRIPTION	QTY	PRIC	VALUE
REAR RH LIGHT IN THE TRUNK LID ?	1	263.40	263.40
REAR LH LIGHT IN THE SIDE PANEL ?	1	376.30	376.30
REAR RH LIGHT IN THE SIDE PANEL ?	1	376.30	376.30
SET ADHESIVE PADS FOR ACE 2.0	1	37.35	37.35
(DG) CLEANER R1 (100ML)	2	26.15	52.30
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	4	131.55	526.20
(DG/SL)ADHESIVE PRIMER VP 206 (30ML)	2	27.85	55.70

Total Parts : 15,140.25

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 22/04/22 @ 10:20 Excess S\$ _____

Surveyor's Name Rasul Sign _____

Surveyor's Tel 9006068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail rasul@lkkauto.com

No. of Working Days Recommend 17 - 18 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



Labour 1	:	25,379.00
Parts	:	15,140.25
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,836.35
Grand Total	:	43,355.60

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **