

Shiau Chan (LKKAuto)

From: Rasul (LKKAuto)
Sent: Friday, 12 August 2022 9:55 AM
To: Mohamad Bin Mohd Sanif; Shiau Chan (LKKAuto)
Subject: Re: DIRECT SETTLEMENT61254---SKD5157Y-PL.xlsx
Attachments: skd 5157(suppl).png

Hi Mr Mohamad,

We will be advising our principal a cost of repair of P/P \$31,986.17 /- with 18 days of repair, subject to their approval.

Aside to Shiau Chan, refer to attachment for the supplementary

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Mohamad Bin Mohd Sanif <mohd.sanif@sime-darby.com.sg>

Sent: Thursday, 11 August 2022 10:03 am

To: Rasul (LKKAuto) <Rasul@lkkauto.com>

Subject: RE: DIRECT SETTLEMENT61254---SKD5157Y-PL.xlsx

As Requested

Thank you.

Best regard,

Mohd.Sanif
Bodyshop

BMW
Performance Motors

DDI: +65 6319 0148

FAX: +65 6474 3229

Address : 303 Alexandra Road, Singapore 159941

Email: mohd.sanif@sime-darby.com.sg

www.bmw.com.sg

Sime Darby Motors
A member of the Sime Darby Group



From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Thursday, 11 August 2022 9:31 am
To: Mohamad Bin Mohd Sanif <mohd.sanif@simedarby.com.sg>
Subject: Re: DIRECT SETTLEMENT61254---SKD5157Y-PL.xlsx

CAUTION: This email originated from outside the organisation. Do not click links or open attachments unless you recognise the sender and know the content is safe. Click "Report Phishing" if you think it is malicious.

Hi Mr Mohamad,

apologise, there are 2 more item in invoice, GROMMET, but in my estimate quoted only 1 item.
Kindly check and confirm. if it is another item, kindly raise supplementary.

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Mohamad Bin Mohd Sanif <mohd.sanif@simedarby.com.sg>
Sent: Wednesday, 10 August 2022 2:26 pm
To: Rasul (LKKAuto) <Rasul@lkkauto.com>; Toh Jing Xuan <toh.jing.xuan@simedarby.com.sg>; Lee Tong Ren Kenji <lee.tong.ren.kenji@simedarby.com.sg>; Jack Ng Guoming <jack.ng.guoming@simedarby.com.sg>
Cc: Keith Leo Chi Yung <keith.leo.chiyung@simedarby.com.sg>; Bernard Wan Chong Huat <bernard.wan@simedarby.com.sg>; Inthiran Thurasamy <inthiran.thurasamy@simedarby.com.sg>
Subject: RE: DIRECT SETTLEMENT61254---SKD5157Y-PL.xlsx

As Requested

Thank you.

Best regard,

Mohd.Sanif
Bodyshop

BMW
Performance Motors

DDI: +65 6319 0148
FAX: +65 6474 3229
Address : 303 Alexandra Road, Singapore 159941

Email: mohd.sanif@sime-darby.com.sg

www.bmw.com.sg

Sime Darby Motors
A member of the Sime Darby Group



From: Rasul (LKKAuto) <Rasul@lkkauto.com>

Sent: Wednesday, 10 August 2022 2:17 pm

To: Mohamad Bin Mohd Sanif <mohd.sanif@sime-darby.com.sg>; Toh Jing Xuan <toh.jing.xuan@sime-darby.com.sg>; Lee Tong Ren Kenji <lee.tong.ren.kenji@sime-darby.com.sg>; Jack Ng Guoming <jack.ng.guoming@sime-darby.com.sg>

Cc: Keith Leo Chi Yung <keith.leo.chiyung@sime-darby.com.sg>; Bernard Wan Chong Huat <bernard.wan@sime-darby.com.sg>; Inthiran Thurasamy <inthiran.thurasamy@sime-darby.com.sg>

Subject: Re: DIRECT SETTLEMENT61254---SKD5157Y-PL.xlsx

CAUTION: This email originated from outside the organisation. Do not click links or open attachments unless you recognise the sender and know the content is safe. Click "Report Phishing" if you think it is malicious.

Hi Mr Mohamad,

The PAINT PROTECTION COATING was not inside the estimate, so it should be raised in supplementary.

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Mohamad Bin Mohd Sanif <mohd.sanif@sime-darby.com.sg>

Sent: Sunday, 7 August 2022 11:40 pm

To: Mohamad Bin Mohd Sanif <mohd.sanif@sime-darby.com.sg>; Rasul (LKKAuto) <Rasul@lkkauto.com>; Toh Jing Xuan <toh.jing.xuan@sime-darby.com.sg>; Lee Tong Ren Kenji <lee.tong.ren.kenji@sime-darby.com.sg>; Jack Ng Guoming <jack.ng.guoming@sime-darby.com.sg>

Cc: Keith Leo Chi Yung <keith.leo.chiyung@sime-darby.com.sg>; Bernard Wan Chong Huat <bernard.wan@sime-darby.com.sg>; Inthiran Thurasamy <inthiran.thurasamy@sime-darby.com.sg>

Subject: DIRECT SETTLEMENT61254---SKD5157Y-PL.xlsx

Without Prejudice,

Total Labour : \$24952.00

Total Parts : \$7034.17

Total Labour and Parts : \$31986.17

Repair workdays : 18 days.

CAR RENTAL=\$2340.00

GIA SEARCH FEE=\$2.00

Thank you.

Best regard,

Mohd.Sanif

Bodyshop

BMW

Performance Motors

DDI: +65 6319 0148

FAX: +65 6474 3229

Address : 303 Alexandra Road, Singapore 159941

Email: mohd.sanif@simedarby.com.sg

www.bmw.com.sg

Sime Darby Motors

A member of the Sime Darby Group



"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."