

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 2848S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT COWLING (CONSISTENT)	CUT	320.00	280.00
1	FRONT COWLING INNER (R) (CONSISTENT)	BROKEN	85.00	85.00
1	HEADLAMP STAY (CONSISTENT)	BENT	190.00	150.00
1	CENTRE COWLING (R) (CONSISTENT)	CRUSHED	210.00	210.00
1	CENTRE COWLING OUTER (R) (CONSISTENT)	CUT	125.00	125.00
1	FUEL TANK COVER (R) (CONSISTENT)	CUT	225.00	225.00
1	FRONT SIGNAL LAMP (RH) (CONSISTENT)	CUT	55.00	55.00
1	HANDLE BAR (CONSISTENT)	BENT	220.00	170.00
1	HANDLE GRIP (CONSISTENT)	TORN	45.00	45.00
1	HANDLE BALANCER (CONSISTENT)	BENT	60.00	60.00
1	BRAKE LEVER (RH) (CONSISTENT)	CUT	45.00	45.00
1	FRONT BRAKE PUMP (CONSISTENT)	BROKEN	285.00	260.00
1	MIRROR (CONSISTENT)	CUT	95.00	95.00
1	FRONT FOOTREST (CONSISTENT)	NOT NECESSARY	85.00	-
1	BRAKE PEDAL (CONSISTENT)	NOT NECESSARY	125.00	-
1	EXHAUST PIPE PROTECTOR (CONSISTENT)	CUT	165.00	165.00
1	MUFFLER END CAP (CONSISTENT)	CUT	120.00	120.00
1	REAR FOOTREST (CONSISTENT)	CUT	45.00	45.00
1	CENTRE COWLING OUTER (L) (CONSISTENT)	BROKEN	125.00	125.00
1	FRONT SIGNAL LAMP (L) (CONSISTENT)	CUT	55.00	55.00
	LESS 10% DISCOUNT		-268.00	-231.50
			2,412.00	2,083.50
	SPECIAL NETT ITEMS			
1	REAR BOX (SN) (CONSISTENT)	CUT	200.00	180.00
	, , ,		200.00	180.00
	LABOUR			
	REPAIR ALIGNMENT.		350.00	200.00
	TOWING 2 WAY.		100.00	80.00

Report Ref No. CC4/ASM22003684/Ega3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

2,200.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR.		450.00	200.00
			900.00	480.00
	GRAND TOTAL		3,512.00	2,743.50

(TO ITS PRE-ACCIDENT CONDITION)

Report Ref No. CC4/ASM22003684/Ega3q2

**RECOMMENDED COST OF LUMP SUM REPAIRS** 

CHEN TSUE YEE

**Automotive Assessor** 

Amonto

**HO LEONG CHUAN** 

**Automotive Assessor**