

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III22003685/TQY3E2

Date: 27/05/2022

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0006751\_01

Claimant Vehicle No : FBH9287P Insured Vehicle No : SLP9644G

Date of Loss: 24/01/2021 Nature of Claim: TP Claim No: MFL2021D0000387

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBH9287P**  
Make & Model: BMW F800GS, 798cc ADVENTURE Engine No: 802EA08827252  
Reg. Date: 11/11/2013 (Man. Year: 2013) Chassis No: WB10B0507EZ302002  
Colour: Red Odometer: 0 km  
Engine Capacity: 798 cc  
Market Value/New Car Price: N/A  
Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 90/90-21 Rear Tyre Size: 150/40 R17  
Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 4 mm  
Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,926.00	1,643.00	2,283.00	58.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	700.00	500.00	41.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>5,126.00</b>	<b>2,343.00</b>	<b>2,783.00</b>	<b>54.29</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,850.00</b>		
<b>Nett Amount (\$\$)</b>	<b>5,126.00</b>	<b>1,850.00</b>	<b>3,276.00</b>	<b>63.91</b>

### INSPECTION

Date of Assignment: 20/04/2022

Date Inspected: 22/04/2022 Inspected At: RS Bikes Centre  
1 Kaki Bukit Avenue 6 #02-45  
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 27 May 2022)	
<b>Parts:</b>	N/A	BMW F800GS 798cc ADVENTURE (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBH9287P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Replaced	185.00 FL	*185.00 FL
2	1		*FRONT INNER TUBE	Not Necessary	280.00 FL	*- FL
3	1		*FRONT OUTER TUBE	Not Necessary	520.00 FL	*- FL
4	1		*FRONT RIM	Replaced	150.00 FL	*150.00 FL
5	1		*TOP FAIRING	Repaired	290.00 FL	*- FL
6	1		*HANDLE BAR	Not Necessary	390.00 FL	*- FL
7	1		*HANDLE BAR END	Not Necessary	90.00 FL	*- FL
8	1		*SET HANDLE PROTECTOR	Replaced	80.00 FL	*80.00 FL
9	1		*O/S SIDE FAIRING TOP	Replaced	175.00 FL	*175.00 FL
10	1		*EXHAUST UNDE COVER	Replaced	180.00 FL	*180.00 FL
11	1		*REAR BOX	Not Necessary	450.00 FS	*- FS
12	1		*REAR BOX BRACKET	Not Necessary	220.00 FS	*- FS
13	1		*SET FRONT CRASH BAR	Replaced	500.00 FS	*500.00 FS
14	1		*SIDE BOX	Replaced	450.00 FS	*450.00 FS
15	1		*SET SIDE BOX BRACKET	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>4,160.00</b>	<b>1,720.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	234.00	77.00
<b>Total Parts (\$)</b>	<b>3,926.00</b>	<b>1,643.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REPLACE, REPAIR AND STRAIGHTEN THE ABOVE DAMAGED PARTS. TO RE-ADJUST TO THE ORIGINAL POSITION	New	600.00	400.00
2	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	600.00	300.00
<b>Gross Labour Cost (\$)</b>			<b>1,200.00</b>	<b>700.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >