

Date: 19/04/2022

Vehicle No: SLX3301T

Model: TOYOTA ALPHARD 2.5X CVT

Chassis: AGH300028534-2015

Reg.Year: 2018

Third Party Insurer: AIG

Third Party Veh No: SLV5009K

Date of Accident: 19/04/2022

Estimator: TING AN

Surveyor:

*Not Notified  
11 Days*

*Recovery After Repair  
5-6 days*

## ESTIMATE

| NO.         | DESCRIPTION                                 | QTY | UNIT S\$     | AMOUNT S\$             |
|-------------|---------------------------------------------|-----|--------------|------------------------|
| 1           | FRONT BONNET                                | 1   |              | <i>Ry</i> \$855.00 ✓   |
| 2           | FRONT BONNET HINGE LH                       | 1   |              | <i>R</i> \$60.00 X     |
| 3           | FRONT BONNET HINGE RH                       | 1   |              | <i>Diy</i> \$60.00 ✓   |
| 4           | FRONT HEADLAMP RH                           | 1   |              | <i>cm</i> \$3,900.00 ✓ |
| 5           | FRONT HEADLAMP CONTROL UNIT                 | 1   |              | \$850.00 7             |
| 6           | FRONT HEADLAMP UPPER PANEL RH               | 1   |              | <i>An</i> \$365.00 ✓   |
| 7           | FRONT GRILLE ASSY                           | 1   |              | \$855.00 7             |
| 8           | FRONT BUMPER                                | 1   |              | <i>th</i> \$667.00 ✓   |
| 9           | FRONT BUMPER SIDE BRACKET RH                | 1   |              | <i>cm</i> \$115.00 ✓   |
| 10          | FRONT BUMPER TOWING COVER RH                | 1   |              | <i>sn</i> \$30.00 X    |
| 11          | FRONT BUMPER PARKING SENSOR RH              | 1   |              | <i>sn</i> \$488.00 X   |
| 12          | FRONT BUMPER FOG LAMP COVER RH              | 1   |              | <i>sn</i> \$165.00 X   |
| 13          | FRONT BUMPER FOG LAMP RH                    | 1   |              | <i>mjcm</i> \$290.00 ✓ |
| 14          | FRONT BUMPER REINFORCEMENT                  | 1   |              | <i>R</i> \$452.00 X    |
| 15          | FRONT BUMPER ABSORBER FOAM                  | 1   |              | <i>sn</i> \$75.00 X    |
| 16          | FRONT BUMPER LOWER GRILLE                   | 1   |              | \$215.00 7             |
| 17          | FRONT SUPPORT PANEL                         | 1   |              | \$580.00 7             |
| 18          | FRONT SUPPORT PANEL UPPER COVER             | 1   |              | <i>sn</i> \$265.00 X   |
| 19          | FRONT FENDER RH                             | 1   |              | <i>Ry</i> \$1,249.00 ✓ |
| 20          | FRONT FENDER INNER SHIELD RH                | 1   |              | <i>Diy</i> \$298.00 ✓  |
| 21          | FRONT QUARTER GLASS WITH CHROME MOULDING RH | 1   |              | <i>nd</i> \$490.00 ✓   |
| 22          | FRONT RIM RH                                | 1   | <i>R SCR</i> | \$1,706.00 150Jn       |
| 23          | FRONT ABSORBER RH                           | 1   |              | \$500.00 7             |
| 24          | FRONT LOWER ARM RH                          | 1   |              | \$815.00 7             |
| 25          | FRONT KNUCKLE ARM RH                        | 1   |              | \$625.00 7             |
| 26          | FRONT WHEEL BEARING RH                      | 1   |              | \$585.00 7             |
| 27          | FRONT DOOR RH                               | 1   |              | REPAIR                 |
| SUB TOTAL   |                                             |     |              | \$16,555.00            |
| LESS 25%    |                                             |     |              | -\$4,138.75            |
| PARTS TOTAL |                                             |     |              | \$12,416.25            |

### Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

### Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 19/04/2022  
 Vehicle No: SLX3301T  
 Model: TOYOTA ALPHARD 2.5X CVT  
 Chassis: AGH300028534-2015  
 Reg.Year: 2018

Third Party Insurer: AIG  
 Third Party Veh No: SLV5009K  
 Date of Accident: 19/04/2022  
 Estimator: TING AN  
 Surveyor:

| NO. | SPECIAL NETT                          | QTY | UNIT S\$  | AMOUNT S\$        |
|-----|---------------------------------------|-----|-----------|-------------------|
| 1   | FRONT GRILLE CLIPS                    | 1   |           | \$50.00           |
| 2   | FRONT BUMPER CLIPS                    | 1   |           | <i>na</i> \$60.00 |
| 3   | FRONT FENDER INNER SHIELD CLIPS RH    | 1   |           | <i>na</i> \$40.00 |
| 4   | FRONT QUARTER GALSS SEALANT RH        | 1   |           | <i>na</i> \$60.00 |
| 5   | FRONT SUPPORT PANEL UPPER COVER CLIPS | 1   |           | <i>na</i> \$40.00 |
|     |                                       |     | S/N TOTAL | \$250.00          |

## LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

\$1,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER RH, FRONT DOOR RH & ETC.

\$1,000.00

LABOUR CHARGES TO REMOVE & REPLACE FRONT BUMPER PARKING SENSOR & ETC.

\$120.00

LABOUR CHARGES TO REMOVE & REPLACE FRONT FENDER QUARTER GLASS RH, FRONT FENDER QUARTER GLASS SEALANT & ETC.

\$120.00

LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER RH, FRONT LOWER ARM RH, FRONT KNUCKLE ARM RH & ETC.

\$250.00

TO WHEEL ALIGNMENT & BALANCING.

\$80.00

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

\$150.00

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$150.00

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$120.00

LABOUR TOTAL \$2,990.00

TING AN

TOTAL

\$15,656.25

### Head office

6 Kung Chong Road Singapore 159143  
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

### Branch

9A Serangoon North Ave 5 Singapore 554500  
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

