

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192
SINGAPORE 510607
BUSINESS REGN. No. 53193457L
Email: willybjt@gmail.com / Mobile: 96699986

VEHICLE DAMAGE INSPECTION REPORT

Mr. Abdul Munaff Mohamed Imran
c/o Goh JP & Wong LLC
133 New Bridge Road # 16-09
Chinatown Point
Singapore 059413

Our Ref : PA/FBS4439/1021/tpw
Date : 17 March 2022

REFERENCES

| | | | |
|-------------------|------------------|-----------------------|---------------------|
| Claim Type | : Third Party | Date of Accident | : 01 October 2021 |
| Vehicle No | : FBS 4439 T | Date of Assignment | : 05 October 2021 |
| Make | : Yamaha | Date of Inspection | : 06 October 2021 |
| Model | : FZS ABS Manual | Date of Re-inspection | : 12 March 2022 |
| Registration Date | : 19 April 2021 | COE Expiry | : 18 April 2031 |
| Color | : Red | Chassis No | : ME1RG6627L0049453 |
| Odometer | : 7,347km | Engine No | : Blocked |

TYRE CONDITION

| | <u>Make</u> | <u>Size</u> | <u>Thread Balance</u> |
|-------|----------------|-------------|-----------------------|
| Front | Ceat Zoom Plus | 100/80-17 | 8mm |
| Rear | Ceat Zoom Plus | 140/60-17 | 8mm |

GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at rear and right sides.
Please refer to photographs and assessment of repairs for details
Enclosed (44) photographs depicting damages and after repaired

INSPECTION AND ADJUSTMENT

Original Quotation : \$5,248.12 Revised Assessment \$3,950.00 Lump sum

Survey conducted at M1 Motoring (Changi)

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately
Six (6) days to complete.

This survey was conducted on a "WITHOUT PREJUDICE" basis.

Note:

The workshop has agreed to undertake the repair on a lump sum basis, and or the use of ex-stock reconditioned parts whichever is possible

PRUDENT ADJUSTORS SERVICES

Vehicle No: FBS 4439 T

Our Ref: PA/FBS4439/1021/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

| <u>S/N</u> | <u>Description Material</u> | <u>Qty</u> | <u>Condition</u> | <u>Original</u> <u>Quotation</u> | <u>Revised</u> <u>Quotation</u> |
|------------------------------|----------------------------------|------------|------------------|-------------------------------------|------------------------------------|
| 1 | Handle bar | 1 pc | Bent | 114.40 | 114.40 ✓ |
| 2 | Handle balance RH | 1 set | PC Cut | 50.00 | 50.00 25 ✓ |
| 3 | Brake lever | 1 pc | Bent/Cut | 38.00 | 38.00 ✓ |
| 4 | Front brake master pump complete | 1 pc | Cut | 425.50 | 425.50 |
| 5 | Mirror RH | 1 set | PC Grazed cut | 130.00 | 130.00 65 ✓ |
| 6 | Front indicator light RH | 1 pc | Grazed cut | 85.50 | 85.50 ✓ |
| 7 | Front mudguard (mat black) | 1 pc | Scratches | 105.00 | 105.00 XR |
| 8 | Fuel Tank side cover RH | 1 pc | Cracked | 165.20 | 165.20 |
| 9 | Rider footrest @ \$68/- | 2 pcs | Cut RH | 136.00 | 68.00 |
| 10 | Rider footrest bracket RH | 1 pc | Bent | 115.00 | 115.00 XR |
| 11 | Front brake pedal | 1 pc | Cut/bent | 65.00 | 65.00 |
| 12 | Exhaust protector | 1 pc | Grazed | 118.50 | 118.50 |
| 13 | Exhaust muffler cap | 1 pc | Scratches | 98.00 | 98.00 XSVC |
| 14 | Rear mudguard | 1 pc | Deformed | 125.80 | 125.80 XNN |
| 15 | Rear mudguard side reflector LH | 1 pc | Cut | 58.00 | 58.00 |
| 16 | Rear chain cover | 1 pc | Torn | 106.90 | 106.90 |
| | | | | 1,936.80 | 1,868.80 |
| | Less 10% | | | 193.68 | 186.88 |
| | | | | 1,743.12 | 1,681.92 |
| <u>Add special nett item</u> | | | | | |
| 17 | Front number plate | 1 pc | Cut | 20.00 | 18.00 10 |
| 18 | Rear number plate | 1 pc | Bent | 25.00 | 20.00 15 |
| 19 | Steering cone & bearing | 1 set | Necessary | 180.00 | 140.00 X7 |
| 20 | Front fork oil seal & dust cover | 2 set | Necessary | 160.00 | 120.00 X } NN |
| 21 | Front fork hydraulic fluid | 4 lits | Necessary | 80.00 | 60.00 X ✓ |
| 22 | Body sticker | 1 set | Necessary | 100.00 | 80.00 50 |
| 23 | Rear swing arm bushes | 1 set | Necessary | 120.00 | 80.00 XNN |
| 24 | Rear top box (45L) | 1 pc | Cut | 350.00 | 280.00 200 |
| 25 | Rear box rack with base | 1 set | Bent | 180.00 | 150.00 XSVC |
| | | | | 1,215.00 | 948.00 |

PRUDENT ADJUSTORS SERVICES

Vehicle No: **FBS 4439 T**

Our Ref: PA/FBS4439/1021/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

Labour charges

| | | |
|--|-----------------|----------------------|
| Towing (2 trips) | 150.00 | 120.00 60 |
| Front wheel balance | 120.00 | 80.00 X |
| Rear wheel balance | 120.00 | 80.00 X |
| Front fork repair & align | 400.00 | 300.00 X |
| Steering stem repair & align | 200.00 | 150.00 X |
| Rear swing arm repair & align | 350.00 | 280.00 150 |
| Body frame alignment | 450.00 | 350.00 X |
| Remove & replace accident damage parts | 500.00 | 400.00 300 |
| | <u>2,290.00</u> | <u>1,760.00</u> |

Total parts & labour concluded 5,248.12 4,389.92

Final lump sum adjustment (less 10% due to no used parts) 3,950.00

4 days

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.


Prudent Adjustors Services
Bok Jee Tan