

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0308/2022/JT
DATE : 19-Apr-22
WIP : 20038

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 20/4/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Steve

15 days exclude 2 PH & 2 Sundays

Johnny Boo 17 Jun 22

OWNER'S NAME : MR LOOI WING YEW
ADDRESS : BLK 4 TOH YI DRIVE
#10-217
SINGAPORE 590004
TELEPHONE : HP +65 98388427
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800093184-02
VEHICLE NO : **SKC 206 C**
MODEL CODE : AUDI A5 SB 2.0 TFSI
MODEL YEAR : 3/8/2018
ENGINE NO : CVK 065315
CHASSIS NO : WAUZZZF52JA19536
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-Apr-22
PLACE OF ACCIDENT : SLIP ROAD EXITING PIE FROM JALAN BAHAR

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKC 206 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	800.00	\$ 500.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS.	S/N \$	1,700.00	\$ 1,700.00
4	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.	S/N \$	560.00	\$ 560.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT DOORS AND BOTH UPPER A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	8,000.00	\$ 3,000.00
<i>(Lock carrier replacement x 3 days for A5)</i>				
SUB TOTAL LABOUR CHARGES		:	\$ 11,540.00	\$ 6,240.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKC 206 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 6,240.00
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS, BOTH FRONT DOORS AND BOTH UPPER A-PILLARS.	\$	8,000.00	\$ 2,750.00
7	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$	280.00	
8	Added labour - see attached	\$	1,860.00	\$ 1,310.00
9	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	\$ 384.00
TOTAL LABOUR CHARGES		:	\$ 22,064.00	\$ 10,684.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 206 C

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,493.00	\$	1,800.80
2	FRONT BUMPER FIXING PARTS	1	\$ 425.00		
3	FRONT BUMPER SECURING STRIP	2	\$ 79.00	\$	31.60
4	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00	\$	174.80
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 254.00	\$	203.20
6	FRONT BUMPER SPOILER	1	\$ 599.00		
7	FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 144.00	\$	114.40
8	RADIATOR GRILLE	1	\$ 2,576.00	\$	2,060.80
9	FRONT PARKING AID SENSOR SUPPORT - LH / RH	2	\$ 116.00	\$	91.52
10	RADIATOR GRILLE COVER - UPPER	1	\$ 209.00	\$	166.80
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 1,058.00	\$	423.20
12	FRONT BUMPER FOAM FILLER PIECE	1	\$ 139.00	\$	110.80
13	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00	\$	719.20
14	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 82.00		
15	FRONT BUMPER BRACKET - LH / RH	2	\$ 508.00	\$	406.40
16	FRONT BUMPER TOP COVER	1	\$ 143.00	\$	114.00
17	CAUTION STICKER	1	\$ 16.00	\$	12.40
18	AIR COND STICKER	1	\$ 9.00	\$	6.64
19	FRONT BUMPER LOCK CARRIER BRACKET	1	\$ 154.00	\$	122.80
20	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00	\$	51.04
SUB TOTAL SPARE PARTS		:	\$ 10,186.00	\$	6,610.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 206 C

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	6,610.40
21	POP RIVET	4	\$ 4.00	\$	2.88
22	FRONT PARKING AID SENSOR - INNER / OUTER	4	\$ 1,060.00	\$	390.24
23	FRONT PARKING AID SENSOR SEAL RING	4	\$ 10.00		
24	FRONT BUMPER WIRING SET	1	\$ 567.00		
25	HORN - LH / RH	2	\$ 273.00		
26	HORN SUPPORT - LH / RH	2	\$ 66.00		
27	FRONT FENDER - LH / RH	2	\$ 2,378.00	\$	951.20
28	FRONT FENDER ATTACHMENT PARTS	1	\$ 55.00		
29	FRONT FENDER CLOSING ELEMENT - LH / RH	2	\$ 166.00	\$	65.84
30	FRONT FENDER BRACKET - LH / RH	2	\$ 82.00	\$	32.72
31	FRONT FENDER POP RIVET	10	\$ 38.00	\$	30.40
32	FRONT FENDER BRACE - LH / RH	2	\$ 264.00	\$	105.20
33	FRONT FENDER BRACKET CENTER - LH / RH	2	\$ 79.00		
34	FRONT FENDER BRACKET CENTER - LH / RH	2	\$ 110.00		
35	FRONT FENDER TRIM - LH / RH	2	\$ 342.00	\$	136.40
36	FRONT WHEEL HOUSING LINER -LH / RH	2	\$ 598.00	\$	238.80
37	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 176.00	\$	140.80
38	FRONT WHEEL SPOILER - LH / RH	2	\$ 164.00		
39	FRONT WHEEL SPOILER LOWER - LH / RH	2	\$ 79.00		
40	FRONT FENDER LEDGE COVER LONG - LH / RH	2	\$ 80.00	\$	31.44
SUB TOTAL SPARE PARTS			:	\$ 6,591.00	\$ 8,736.32

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 206 C

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	8,736.32
41	FRONT FENDER LEDGE COVER SHORT - LH / RH	2	\$ 36.00	\$	13.92
42	BONNET	1	\$ 3,491.00	\$	2,792.80
43	BONNET CAP NUT	6	\$ 27.00		
44	BONNET ATTACHMENT PARTS	1	\$ 128.00		
45	BONNET HINGE - LH / RH	2	\$ 932.00		
46	BONNET IMPACT PROTECTION - LH / RH / CENTER	3	\$ 93.00	\$	73.20
47	BONNET STRIKER - LH / RH	2	\$ 112.00	\$	89.12
48	BONNET LID LOCK	2	\$ 455.00	\$	364.00
49	BONNET BOWDEN CABLE - CENTER	1	\$ 64.00		
50	BONNET RELEASE CABLE COVER	1	\$ 11.00		
51	BONNET BOWDEN CABLE - CENTER UPPER	1	\$ 64.00	\$	50.56
52	BONNET RELEASE LEVER	1	\$ 15.00		
53	BONNET ABSORBER	2	\$ 256.00	\$	204.80
54	BONNET LOCK CABLE	1	\$ 82.00		
55	BONNET PLENUM CHAMBER	1	\$ 108.00		
56	HEADLIGHT - LH / RH	2	\$ 16,832.00	\$	13,465.60
57	HEADLIGHT HOSE	2	\$ 83.00		
58	SPACER	6	\$ 270.00		
59	LIFT CYLINDER - LH / RH	2	\$ 434.00		
60	LIFT CYLINDER BRACKET - LH / RH	2	\$ 34.00		
SUB TOTAL SPARE PARTS		:	\$ 23,527.00	\$	25,790.32

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 206 C

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	25,790.32
61	LIFT CYLINDER CORRUGATED PIPE	1 \$	100.00	\$	79.44
62	LOCK CARRIER	1 \$	1,127.00	\$	901.60
63	LOCK CARRIER SUPPORT - LH / RH	2 \$	85.00	\$	67.68
64	A/C CONDENSER	1 \$	682.50	\$	546.00
65	REFRIGERANT LINE	1 \$	186.00	\$	148.80
66	REFRIGERANT LINE	1 \$	381.00	\$	304.80
67	REFRIGERANT LINE	1 \$	277.00	\$	221.60
68	HIGH-PRESSURE VALVE	1 \$	52.00		
69	PRESSURE SENDER	1 \$	206.00		
70	CHARGE AIR COOLER	1 \$	654.00	\$	522.80
71	CHARGE AIR COOLER PRESSURE HOSE	1 \$	413.00		
72	CHARGE AIR COOLER PRESSURE PIPE	1 \$	496.00		
73	RADIATOR	1 \$	1,010.00	\$	808.00
74	RADIATOR COOLANT	6 \$	282.00	\$	225.60
75	RADIATOR FAN RING	1 \$	291.00	\$	232.40
76	RADIATOR FAN CONTROL UNIT	1 \$	2,483.00	\$	1,986.40
77	RADIATOR AIR GUIDE INNER - LH / RH	2 \$	72.00	\$	56.56
78	RADIATOR AIR GUIDE OUTER - LH / RH	2 \$	38.00	\$	29.28
79	RADIATOR AIR GUIDE - LOWER	1 \$	25.00	\$	19.68
80	OUTSIDE TEMPERATURE SENSOR BRACKET	1 \$	21.00	\$	16.32
SUB TOTAL SPARE PARTS			:	\$ 8,881.50	\$ 31,957.28

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 206 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 31,957.28</i>
81	OUTSIDE TEMPERATURE SENSOR	1	\$ 64.00	
82	INTAKE AIR DUCT - RH	1	\$ 25.00	
83	INTAKE AIR GUIDE - TOP	1	\$ 61.00	
84	INTAKE HOSE	1	\$ 110.00	
85	AIR FILTER BOX	1	\$ 418.00	
86	FRONT DOOR - LH / RH	2	\$ 342.00	<i>\$ 272.80</i>
87	ROOF MOLDING - LH / RH	2	\$ 1,412.00	
88	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - LH / RH	2	\$ 892.00	
89	FRONT WINDSCREEN DEFLECTOR SRTIP - LH / RH	2	\$ 150.00	
90	RADIATOR AIR GUIDE UPPER	1	\$ 19.00	
91	NOISE INSULATION	1	\$ 640.00	
92	FRONT NO PLATE	S/N	\$ 60.00	<i>\$ 60.00</i>
93	ADDED PARTS - SEE ATTACHED		<i>\$ 4,102.00</i>	<i>\$ 1,791.44</i>
94	ADDED PARTS - SEE ATTACHED		<i>\$ 590.00</i>	<i>\$ 472.00</i>
95	SUNDRIES		\$ 500.00	<i>\$ 251.28</i>
TOTAL SPARE PARTS			\$ 58,570.50	\$ 34,804.80
TOTAL LABOUR CHARGES			\$ 22,064.00	\$ 10,684.00
GRAND TOTAL			\$ 80,634.50	\$ 45,488.80

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-10/06/22



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0308/2022/JT 28-Apr-22 CHANG 1 of 1 SKC 206 C AUDI A5 SB 2.0 TFSI	
Quantity	Description		Unit Price	Amount
<u>Labours</u>				
1	TO RENEW LHS INNER AIR COND PIPE. S/N		\$ 280.00	\$ 280.00
2	TO REPAIR RHS FRONT CHASSIS FRAME COVER.		\$ 800.00	\$ 250.00
3	TO DISMANTLE AND RENEW TIMING CASE S/N AND OTHER ENGINE COMPONENTS.		\$ 780.00	\$ 780.00
				\$ 1,310.00
<u>Parts</u>				
1	BONNET SOUND ABSORBER	1	\$ 382.00	\$ 305.60
2	REFRIGERANT PIPE	1	\$ 585.00	\$ 468.00
3	ENGINE OIL	1	\$ 299.00	\$ 239.20
4	TIMING CASE	1	\$ 316.00	\$ 252.80
5	SILICONE SEALANT	2	\$ 127.00	\$ 101.44
6	BELT TENSIONER DAMPER	1	\$ 162.00	\$ 129.20
7	POLY-V-BELT	1	\$ 56.00	\$ 44.24
8	VIBRATION DAMPER	1	\$ 301.00	\$ 240.40
9	FLAT CONTACT HOUSING	1	\$ 14.00	\$ 10.56
				\$ 4,411.44
GRAND TOTAL			\$ 4,102.00	\$ 3,101.44

For Premium Automobiles Pte Ltd

Authorised Signature



Supplementary Estimate-2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0308/2022/JT 18-May-22 CHANG 1 of 1 SKC 206 C AUDI A5 SB 2.0 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	POTENTIAL DISTRIBUTOR	\$ 590.00	\$ 472.00	
	GRAND TOTAL	\$ 590.00	\$ 472.00	

For Premium Automobiles Pte Ltd

Authorized Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT