



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0308/2022/JT  
DATE : 19-Apr-22  
WIP : 20038

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 20/4/22

## AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LOOI WING YEW  
ADDRESS : BLK 4 TOH YI DRIVE  
#10-217  
SINGAPORE 590004  
TELEPHONE : HP +65 98388427  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 1800093184-02  
VEHICLE NO : SKC 206 C  
MODEL CODE : AUDI A5 SB 2.0 TFSI  
MODEL YEAR : 3/8/2018  
ENGINE NO : CVK 065315  
CHASSIS NO : WAUZZZF52JA19536  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 15-Apr-22  
PLACE OF ACCIDENT : SLIP ROAD EXITING PIE FROM JALAN BAHAR

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKC 206 C

| S/N                      | NATURE OF JOBS                                                                                                                                                                                                                                                         | ESTIMATED CHARGES       | SURVEYOR'S RECOMMENDATIONS |
|--------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|----------------------------|
| 1                        | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. S/N \$                                                                                                                | 480.00 /                |                            |
| 2                        | TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE. S/N \$<br>250 X 2                                                                                                                                                                               | 800.00 500              |                            |
| 3                        | TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS. S/N \$                                                                                                        | 1,700.00 /              |                            |
| 4                        | TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR. S/N \$<br>280 X 2                                                                                                       | 560.00 /                |                            |
| 5                        | TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT DOORS AND BOTH UPPER A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. S/N \$ | 8,000.00 3000 /<br>7750 |                            |
| SUB TOTAL LABOUR CHARGES |                                                                                                                                                                                                                                                                        | : \$ 11,540.00          |                            |

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKC 206 C

| S/N                  | NATURE OF JOBS                                                                                                       | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATIONS |
|----------------------|----------------------------------------------------------------------------------------------------------------------|-------------------|----------------------------|
| 6                    | TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS, BOTH FRONT DOORS AND BOTH UPPER A-PILLARS.<br>(1 CLH) 2 | \$ 8,000.00       | 2750 ✓                     |
| 7                    | TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.                                                                         | S/N \$ 280.00     | X                          |
| 8                    | TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.                                                                              | S/N \$ 384.00     | ✓                          |
| TOTAL LABOUR CHARGES |                                                                                                                      | : \$ 20,204.00    |                            |



## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 206 C

| S/N                   | PARTS DESCRIPTION                                    | QTY | DAMAGED PARTS & PRICES |                   | REMARKS   |
|-----------------------|------------------------------------------------------|-----|------------------------|-------------------|-----------|
|                       |                                                      |     | S/NETT                 |                   |           |
| 1                     | FRONT BUMPER / BR                                    | 1   | \$                     | 2,493.00 /        | 1800.80   |
| 2                     | FRONT BUMPER FIXING PARTS X AN                       | 1   | \$                     | 425.00            |           |
| 3                     | FRONT BUMPER SECURING STRIP / (LH) BT                | 21  | \$                     | 79.00 31.60 /     | ✓         |
| 4                     | FRONT BUMPER GRILLE - CENTER / BR                    | 1   | \$                     | 219.00 /          | 174.80    |
| 5                     | FRONT BUMPER CLOSING ELEMENT - LOWER CENTER ?        | 1   | \$                     | 254.00 / BR       | 203.20    |
| 6                     | FRONT BUMPER SPOILER ? X M                           | 1   | \$                     | 599.00            |           |
| 7                     | FRONT BUMPER AIR GUIDE - LH / RH ? / BR              | (2) | \$                     | 144.00 /          | 114.40    |
| 8                     | RADIATOR GRILLE / BR                                 | 1   | \$                     | 2,576.00 /        | 2060.80   |
| 9                     | FRONT PARKING AID SENSOR SUPPORT - LH / RH / CUT (2) | 2   | \$                     | 116.00 /          | 91.52     |
| 10                    | RADIATOR GRILLE COVER - UPPER / BR                   | 1   | \$                     | 209.00 /          | 166.80    |
| 11                    | FRONT BUMPER AIR GUIDE GRILLE - LH / RH / CUT        | 21  | \$                     | 1,058.00 423.20 / | ✓         |
| 12                    | FRONT BUMPER FOAM FILLER PIECE / BR                  | 1   | \$                     | 139.00 /          | 110.80    |
| 13                    | FRONT BUMPER REINFORCEMENT BEAM / M                  | 1   | \$                     | 899.00 /          | 719.20    |
| 14                    | FRONT BUMPER GUIDE SECTION - LH / RH ? X M           | 2   | \$                     | 82.00             |           |
| 15                    | FRONT BUMPER BRACKET - LH / RH ? / BT                | (2) | \$                     | 508.00 /          | 406.40    |
| 16                    | FRONT BUMPER TOP COVER / CR4                         | 1   | \$                     | 143.00 /          | 114.00    |
| 17                    | CAUTION STICKER / AC                                 | 1   | \$                     | 16.00 /           | 12.40     |
| 18                    | AIR COND STICKER / AC                                | 1   | \$                     | 9.00 /            | 6.64      |
| 19                    | FRONT BUMPER LOCK CARRIER BRACKET / BR               | 1   | \$                     | 154.00 /          | 122.80    |
| 20                    | FRONT BUMPER SUPPORT - LH / RH / AC                  | 2   | \$                     | 64.00 /           | 51.04     |
| SUB TOTAL SPARE PARTS |                                                      |     | :                      | \$                | 10,186.00 |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.





55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 206 C

| S/N                   | PARTS DESCRIPTION                                    | QTY   | DAMAGED PARTS & PRICES |          | REMARKS |
|-----------------------|------------------------------------------------------|-------|------------------------|----------|---------|
|                       |                                                      |       | S/NETT                 |          |         |
| 21                    | POP RIVET - <i>nc</i>                                | 4 \$  | 4.00                   | / 2.88   |         |
| 22                    | FRONT PARKING AID SENSOR - INNER / OUTER <i>? BR</i> | 2 \$  | 1,060.00               | 390.24   | ✓       |
| 23                    | FRONT PARKING AID SENSOR SEAL RING <i>nc</i>         | 4 \$  | 10.00                  |          |         |
| 24                    | FRONT BUMPER WIRING SET <i>? X nn</i>                | 1 \$  | 567.00                 |          |         |
| 25                    | HORN - LH / RH <i>? X nn</i>                         | 2 \$  | 273.00                 |          |         |
| 26                    | HORN SUPPORT - LH / RH <i>? X nn</i>                 | 2 \$  | 66.00                  |          |         |
| 27                    | FRONT FENDER - LH / RH <i>nc</i>                     | 21 \$ | 2,378.00               | 951.20   | ✓       |
| 28                    | FRONT FENDER ATTACHMENT PARTS <i>X nn</i>            | 1 \$  | 55.00                  |          |         |
| 29                    | FRONT FENDER CLOSING ELEMENT - LH / RH <i>nc</i>     | 21 \$ | 166.00                 | 65.84    | ✓       |
| 30                    | FRONT FENDER BRACKET - LH / RH <i>nc</i>             | 21 \$ | 82.00                  | 32.76    | ✓       |
| 31                    | FRONT FENDER POP RIVET <i>nc</i>                     | 10 \$ | 38.00                  | 30.40    |         |
| 32                    | FRONT FENDER BRACE - LH / RH <i>? BT</i>             | 21 \$ | 264.00                 | 105.20   | ✓       |
| 33                    | FRONT FENDER BRACKET CENTER - LH / RH <i>? X nn</i>  | 2 \$  | 79.00                  |          |         |
| 34                    | FRONT FENDER BRACKET CENTER - LH / RH <i>? X nn</i>  | 2 \$  | 110.00                 |          |         |
| 35                    | FRONT FENDER TRIM - LH / RH <i>nc</i>                | 21 \$ | 342.00                 | 136.40   | ✓       |
| 36                    | FRONT WHEEL HOUSING LINER - LH / RH <i>nc</i>        | 21 \$ | 598.00                 | 238.80   | ✓       |
| 37                    | FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>nc</i> | 1 \$  | 176.00                 | 140.80   |         |
| 38                    | FRONT WHEEL SPOILER - LH / RH <i>? X nn</i>          | 2 \$  | 164.00                 |          |         |
| 39                    | FRONT WHEEL SPOILER LOWER - LH / RH <i>? X nn</i>    | 2 \$  | 79.00                  |          |         |
| 40                    | FRONT FENDER LEDGE COVER LONG - LH / RH <i>? BR</i>  | 21 \$ | 80.00                  | 31.24    | ✓       |
| SUB TOTAL SPARE PARTS |                                                      |       | \$                     | 6,591.00 |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 206 C

| S/N                   | PARTS DESCRIPTION                           | QTY   | DAMAGED PARTS & PRICES |           | REMARKS   |
|-----------------------|---------------------------------------------|-------|------------------------|-----------|-----------|
|                       |                                             |       | S/NETT                 |           |           |
| 41                    | FRONT FENDER LEDGE COVER SHORT - LH / RH ?  | 21 \$ | 1 BR                   | 36.00     | 13-92 / ✓ |
| 42                    | BONNET                                      | 1 \$  |                        | 3,491.00  | 2792.80   |
| 43                    | BONNET CAP NUT                              | 6 \$  |                        | 27.00     |           |
| 44                    | BONNET ATTACHMENT PARTS                     | 1 \$  |                        | 128.00    |           |
| 45                    | BONNET HINGE - LH / RH                      | 2 \$  |                        | 932.00    |           |
| 46                    | BONNET IMPACT PROTECTION - LH / RH / CENTER | 3 \$  |                        | 93.00     | 73.20     |
| 47                    | BONNET STRIKER - LH / RH                    | 2 \$  |                        | 112.00    | 89.12     |
| 48                    | BONNET LID LOCK                             | 2 \$  |                        | 455.00    | 364.00    |
| 49                    | BONNET BOWDEN CABLE - CENTER                | 1 \$  |                        | 64.00     | X NN      |
| 50                    | BONNET RELEASE CABLE COVER                  | 1 \$  |                        | 11.00     |           |
| 51                    | BONNET BOWDEN CABLE - CENTER UPPER          | 1 \$  |                        | 64.00     | 50.56     |
| 52                    | BONNET RELEASE LEVER                        | 2 \$  |                        | 256.00    | 204.80    |
| 53                    | BONNET ABSORBER                             | 1 \$  |                        | 82.00     |           |
| 54                    | BONNET LOCK CABLE                           | 1 \$  |                        | 108.00    |           |
| 55                    | BONNET PLENUM CHAMBER                       | 1 \$  |                        | 16,832.00 | 13465.60  |
| 56                    | HEADLIGHT - LH / RH                         | 2 \$  |                        | 83.00     |           |
| 57                    | HEADLIGHT HOSE                              | 6 \$  |                        | 270.00    |           |
| 58                    | SPACER                                      | 2 \$  |                        | 434.00    |           |
| 59                    | LIFT CYLINDER - LH / RH                     | 2 \$  |                        | 34.00     |           |
| 60                    | LIFT CYLINDER BRACKET - LH / RH             | 2 \$  |                        |           |           |
| SUB TOTAL SPARE PARTS |                                             |       | :                      | \$        | 23,527.00 |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 206 C

| S/N                   | PARTS DESCRIPTION                        | QTY | DAMAGED PARTS & PRICES |                    | REMARKS |
|-----------------------|------------------------------------------|-----|------------------------|--------------------|---------|
|                       |                                          |     | S/NETT                 |                    |         |
| 61                    | LIFT CYLINDER CORRUGATED PIPE ? / CRV    | 1   | \$                     | 100.00 / 79.44     |         |
| 62                    | LOCK CARRIER / RR                        | 1   | \$                     | 1,127.00 / 901.60  |         |
| 63                    | LOCK CARRIER SUPPORT - LH / RH ?         | (2) | \$ / BR                | 85.00 / 67.68      |         |
| 64                    | A/C CONDENSER / DD                       | 1   | TBC                    | 687.50 / 546.00    |         |
| 65                    | REFRIGERANT LINE ? / BT                  | 1   | \$                     | 186.00 / 148.80    |         |
| 66                    | REFRIGERANT LINE ? / BT                  | 1   | \$                     | 381.00 / 304.80    |         |
| 67                    | REFRIGERANT LINE ? / BT                  | 1   | \$                     | 277.00 / 221.60    |         |
| 68                    | HIGH-PRESSURE VALVE ? X nn               | 1   | \$                     | 52.00              |         |
| 69                    | PRESSURE SENDER ? X nn                   | 1   | \$                     | 206.00             |         |
| 70                    | CHARGE AIR COOLER / DD                   | 1   | \$                     | 654.00 / 522.80    |         |
| 71                    | CHARGE AIR COOLER PRESSURE HOSE ? X nn   | 1   | \$                     | 413.00             |         |
| 72                    | CHARGE AIR COOLER PRESSURE PIPE ? X nn   | 1   | \$                     | 496.00             |         |
| 73                    | RADIATOR / DD                            | 1   | \$                     | 1,010.00 / 808     |         |
| 74                    | RADIATOR COOLANT / RC                    | 6   | \$                     | 282.00 / 225.60    |         |
| 75                    | RADIATOR FAN RING / BR                   | 1   | \$                     | 291.00 / 232.40    |         |
| 76                    | RADIATOR FAN CONTROL UNIT ? / DD         | 1   | \$                     | 2,483.00 / 1986.40 |         |
| 77                    | RADIATOR AIR GUIDE INNER - LH / RH / BR  | (2) | \$                     | 72.00 / 56.56      |         |
| 78                    | RADIATOR AIR GUIDE OUTER - LH / RH / mis | (2) | \$                     | 38.00 / 29.28      |         |
| 79                    | RADIATOR AIR GUIDE - LOWER ? X nn Bt     | 1   | \$                     | 25.00 19.68 ✓      |         |
| 80                    | OUTSIDE TEMPERATURE SENSOR BRACKET / nre | 1   | \$                     | 21.00 / 16.32      |         |
| SUB TOTAL SPARE PARTS |                                          |     | :                      | \$ 8,199.00        |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## **MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 206 C**

| S/N                         | PARTS DESCRIPTION                                            | QTY | DAMAGED PARTS & PRICES |                 | REMARKS    |
|-----------------------------|--------------------------------------------------------------|-----|------------------------|-----------------|------------|
|                             |                                                              |     | S/NETT                 |                 |            |
| 81                          | OUTSIDE TEMPERATURE SENSOR <i>Q X nn</i>                     | 1   | \$                     | 64.00           |            |
| 82                          | INTAKE AIR DUCT - RH <i><del>CR4</del> X nn</i>              | 1   | \$                     | 25.00           |            |
| 83                          | INTAKE AIR GUIDE - TOP <i>1 X nn</i>                         | 1   | \$                     | 61.00           |            |
| 84                          | INTAKE HOSE <i>1 X nn</i>                                    | 1   | \$                     | 110.00          |            |
| 85                          | AIR FILTER BOX <i>1 X nn</i>                                 | 1   | \$                     | 418.00          |            |
| 86                          | FRONT DOOR - LH / RH <i>X R (Door chrome trim) ②</i>         | 2   | \$ / BR                | 342.00 / 272.80 |            |
| 87                          | ROOF MOLDING - LH / RH <i>X nn</i>                           | 2   | \$                     | 1,412.00        |            |
| 88                          | FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - LH / RH <i>X nn</i> | 2   | \$ nn                  | 892.00          |            |
| 89                          | FRONT WINDSCREEN DEFLECTOR STRIP - LH / RH <i>X nn</i>       | 2   | \$                     | 150.00          |            |
| 90                          | RADIATOR AIR GUIDE UPPER <i>1 X nn</i>                       | 1   | \$                     | 19.00           |            |
| 91                          | NOISE INSULATION <i>X nn</i>                                 | 1   | \$                     | 640.00          |            |
| 92                          | FRONT NO PLATE <i>1 R</i>                                    | S/N | \$                     | 60.00           | ✓          |
| 93                          | SUNDRIES <i>1 / nec</i>                                      |     | \$                     | 500.00          | 251.28 / ✓ |
| <b>TOTAL SPARE PARTS</b>    |                                                              |     | :                      | \$              | 53,196.00  |
| <b>TOTAL LABOUR CHARGES</b> |                                                              |     | :                      | \$              | 20,204.00  |
| <b>GRAND TOTAL</b>          |                                                              |     | :                      | \$              | 73,400.00  |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED  
 SPARE PARTS ARE SPECIAL NETT.



# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :  
SURVEYED DATE :  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS :

Steve (LKK)  
29/4/22, 10:30am

OD-MAL  
EXCII-?  
P/P  
my PL my  
13 to dys

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT

# PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



## Supplementary Estimate-1

GST Reg No. 19-9902271-W

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Attn: Mr. Adrian Ling - Motor Claims Dept  
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.  
Date  
Service Advisor  
Pages  
Regn No  
Model No

PA/OD/0308/2022/JT  
28-Apr-22  
CHANG  
1 of 1  
SKC 206 C  
AUDI A5 SB 2.0 TFSI

| Quantity           | Description                                                         | Unit Price | Amount             |
|--------------------|---------------------------------------------------------------------|------------|--------------------|
| <b>Labours</b>     |                                                                     |            |                    |
| 1                  | TO RENEW LHS INNER AIR COND PIPE. S/N                               | \$ 280.00  | ✓                  |
| 2                  | TO REPAIR RHS FRONT CHASSIS FRAME COVER.                            | \$ 800.00  | 250 ✓              |
| 3                  | TO DISMANTLE AND RENEW TIMING CASE S/N AND OTHER ENGINE COMPONENTS. | \$ 780.00  | ✓                  |
| <b>Parts</b>       |                                                                     |            |                    |
| 1                  | BONNET SOUND ABSORBER / CR4                                         | \$ 382.00  | 305.60             |
| 2                  | REFRIGERANT PIPE / BT                                               | \$ 585.00  | 468.00             |
| 3                  | ENGINE OIL / AC                                                     | \$ 299.00  | 239.20             |
| 4                  | TIMING CASE / PD                                                    | \$ 316.00  | 252.80             |
| 5                  | SILICONE SEALANT / AC                                               | \$ 127.00  | 101.44             |
| 6                  | BELT TENSIONER DAMPER / OR                                          | \$ 162.00  | 129.20             |
| 7                  | POLY-V-BELT / TN                                                    | \$ 56.00   | 44.24              |
| 8                  | VIBRATION DAMPER (pulling) / BT                                     | \$ 301.00  | 240.40             |
| 9                  | FLAT CONTACT HOUSING / BR                                           | \$ 14.00   | 10.56              |
| <b>GRAND TOTAL</b> |                                                                     |            | <b>\$ 4,102.00</b> |

For Premium Automobiles Pte Ltd

  
Authorised Signature

Stew  
28/4/22

3 & dys

# PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



## Supplementary Estimate-2

GST Reg No. 19-9902271-W

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0308/2022/JT

18-May-22

CHANG

1 of 1

SKC 206 C

AUDI A5 SB 2.0 TFSI

| Quantity           | Description                              | Unit Price       | Amount |
|--------------------|------------------------------------------|------------------|--------|
| <b>Parts</b>       |                                          |                  |        |
| 1                  | POTENTIAL DISTRIBUTOR ✓ <i>Shorted</i> 1 | \$ 590.00        | 472    |
| <b>GRAND TOTAL</b> |                                          | <b>\$ 590.00</b> |        |

For Premium Automobiles Pte Ltd



Authorised Signature

*Steve (LKK)*

*18/5/22*