



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0304/2022/JT
DATE	:	19-Apr-22
WIP	:	20243

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 20/4/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME	:	MR MOHAMMAD RAWI BIN MARJUNI
ADDRESS	:	BLK 358 WOODLANDS AVE 5 #11-382 SINGAPORE 730358
TELEPHONE	:	HP +65 96554370
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1900249263-01
VEHICLE NO	:	SMQ 5633 Y
MODEL CODE	:	AUDI A4 SEDAN 2.0 TFSI
MODEL YEAR	:	25/11/2019
ENGINE NO	:	CVK 080345
CHASSIS NO	:	WAUZZZF48KA111627
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	17-Apr-22
PLACE OF ACCIDENT	:	MARSILING DRIVE TURNING LEFT TOWARDS MARSILING ROAD

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMQ 5633 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 X	
2	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 350.00 280	
3	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, AB PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N \$ 1,800.00 1800 ✓	
4	TO REMOVE CENTER CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL. INSPECT FOR DAMAGES.	S/N \$ 3,200.00 X	x X
5	TO RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$ 2,400.00 X	
SUB TOTAL LABOUR CHARGES		: \$ <u>8,230.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMQ 5633 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISMANTLE AND INSTALL FRONT BUMPER. TO RENEW RHS FRONT FENDER AND RHS FRONT DOOR. TO CUT OUT AND WELD RHS A-PILLAR WITH RHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,300.00	2500
7	TO RESPRAY RHS FRONT FENDER, RHS FRONT DOOR, RHS A-PILLAR, RHS SILL PANEL AND DOOR ENTRANCE.	\$ 4,000.00	3.5 x 550 = 1925
8	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	280
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 19,242.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 5633 Y

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
1	FRONT BUMPER GUIDE SECTION - RH <i>Not New</i>	1	\$	41.00	*	
2	FRONT FENDER - RH <i>Distorted</i>	1	\$	861.00	✓	688.8
3	FRONT FENDER ATTACHMENT PARTS <i>Not New</i>	1	\$	211.00	*	
4	FRONT FENDER END PLATE - RH	1	\$	81.00	✓	64.24
5	FRONT FENDER BRACKET - RH	1	\$	41.00	✓	32.72
6	FRONT FENDER BRACKET - CENTER RH	1	\$	55.00	✓	44
7	FRONT FENDER POP RIVET <i>New</i>	6	\$	23.00	✓	18.24
8	FRONT FENDER BRACE - RH	1	\$	132.00	?	X
9	FRONT FENDER BRACKET END - RH	1	\$	36.00	✓	?
10	FRONT FENDER BRACKET - CENTER RH	1	\$	37.00	✓	?
11	FRONT FENDER BRACKET UPPER - RH	1	\$	37.00	✓	?
12	FRONT FENDER BRACKET COVER - RH	1	\$	13.00	✓	?
13	FRONT WHEEL HOUSING LINER - RH <i>Delud</i>	1	\$	262.00	✓	209.6
14	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not New</i>	1	\$	149.00	*	
15	FRONT WHEEL SPOILER - RH <i>Not New</i>	1	\$	82.00	+	
16	FRONT WHEEL SPOILER LOWER - RH <i>Not New</i>	1	\$	40.00	+	
17	FRONT STONE CHIP GUARD - RH <i>Delud</i>	1	\$	57.00	✓	45.28
18	FRONT FENDER LEDGE COVER - LONG	1	\$	35.00	✓	27.52
19	FRONT FENDER LEDGE COVER - SHORT	1	\$	26.00	✓	20.16
20	A/B PILLAR - RH <i>Delud</i>	1	\$	2,874.00	✓	2299.2
SUB TOTAL SPARE PARTS			:	\$	5,093.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMO 5633 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	RIVETTED CAP NUT ⁷	2	\$ 12.00	? X
22	FRONT SILL TRIM STRIP - RH <i>Neu</i>	1	\$ 133.00	✓ 106
23	DATA TAG <i>Neu</i>	1	\$ 515.00	✓ 412
24	FRONT DOOR - RH <i>Repair</i>	1	\$ 3,431.00	X
25	FRONT DOOR OUTER SEAL - RH <i>?</i>	1	\$ 229.00	X
26	BONDING AGENT	1	\$ 51.00	✓
27	CLEANING SOLUTION <i>HP Neu</i>	1	\$ 74.00	X
28	APPLICATOR	1	\$ 8.00	X
29	FRONT DOOR BUNGS	1	\$ 5.00	X
30	FRONT DOOR ATTACHMENT PARTS <i>HP Neu</i>	1	\$ 1,153.00	X
31	FRONT DOOR CATCH - RH	1	\$ 116.00	X
32	FRONT DOOR WINDOW GUIDE TRIM STRIP <i>HP Neu</i>	1	\$ 287.00	X
33	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - RH <i>HP Neu</i>	1	\$ 344.00	X
34	ASSEMBLY CARRIER <i>?</i>	1	\$ 2,096.00	? X
35	WISHBONE LINK - RH <i>?</i>	1	\$ 605.00	? X
36	WISHBONE SUSPENSION GUIDE - RH <i>?</i>	1	\$ 1,057.00	? X
37	FRONT WISHBONE GUIDE - RH	1	\$ 575.00	? X
38	FRONT WISHBONE GUIDE - RH <i>?</i>	1	\$ 575.00	? X
39	FRONT WHEEL BEARING HOUSING - RH	1	\$ 1,070.00	? X
40	SWIVEL JOINT <i>?</i>	1	\$ 214.00	? X
SUB TOTAL SPARE PARTS		:	\$ 12,550.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 5633 Y

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT WHEEL HUB ?	1	\$ 498.00	? X
42	FRONT WHEEL BEARING DOUBLED FLANGE ?	1	\$ 273.00	? X
43	SUSPENSION FORKS - RH ?	1	\$ 293.00	? X
44	COUPLING ROD ?	2	\$ 258.00	? X
45	GAS SHOCK ABSORBER ?	1	\$ 332.00	? X
46	TRACK ROD ?	1	\$ 109.00	? X
47	TIE ROD END ?	1	\$ 217.00	? X
48	ARYLIC SEALANT } Nec	S/N	\$ 180.00	✓
49	CAVITY WAX }	S/N	\$ 140.00	✓
50	STONE CHIP }	S/N	\$ 180.00	✓
51	METAL FILLER POWDER Nec	S/N	\$ 280.00	✓
52	RHS FRONT TYRE Not Nec	S/N	TBC	X
53	RHS FRONT RIM Lt	S/N	TBC	✓
54	SUNDRIES ?		\$ 500.00	? ✓ 31.12
TOTAL SPARE PARTS		:	\$ 20,903.00	
TOTAL LABOUR CHARGES		:	\$ 19,242.00	
GRAND TOTAL		:	\$ 40,145.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ling*
SURVEYED DATE : *20/04/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 09 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: