

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0304/2022/JT
DATE : 19-Apr-22
WIP : 20243

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 20/4/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

9 days exclude 1 Sunday

Johnny Boo 5 Sep 22

OWNER'S NAME : MR MOHAMMAD RAWI BIN MARJUNI
ADDRESS : BLK 358 WOODLANDS AVE 5
#11-382
SINGAPORE 730358
TELEPHONE : HP +65 96554370
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900249263-01
VEHICLE NO : **SMQ 5633 Y**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI
MODEL YEAR : 25/11/2019
ENGINE NO : CVK 080345
CHASSIS NO : WAUZZZF48KA111627
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Apr-22
PLACE OF ACCIDENT : MARSILING DRIVE TURNING LEFT
TOWARDS MARSILING ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMQ 5633 Y

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	
2	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	350.00	\$ 280.00
3	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, AB PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N \$	1,800.00	\$ 1,800.00
4	TO REMOVE CENTER CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL. INSPECT FOR DAMAGES.	S/N \$	3,200.00	
5	TO RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$	2,400.00	
SUB TOTAL LABOUR CHARGES		:	\$ 8,230.00	\$ 2,080.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMQ 5633 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	C/F		\$ 2,080.00
6	TO DISMANTLE AND INSTALL FRONT BUMPER. TO RENEW RHS FRONT FENDER AND RHS FRONT DOOR. TO CUT OUT AND WELD RHS A-PILLAR WITH RHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,300.00	\$ 2,500.00
7	TO RESPRAY RHS FRONT FENDER, RHS FRONT DOOR, RHS A-PILLAR, RHS SILL PANEL AND DOOR ENTRANCE.	\$ 4,000.00	\$ 1,925.00
8	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	\$ 280.00
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 19,242.00	\$ 6,977.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 5633 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER GUIDE SECTION - RH	1	\$ 41.00	
2	FRONT FENDER - RH	1	\$ 861.00	\$ 688.80
3	FRONT FENDER ATTACHMENT PARTS	1	\$ 211.00	
4	FRONT FENDER END PLATE - RH	1	\$ 81.00	\$ 64.24
5	FRONT FENDER BRACKET - RH	1	\$ 41.00	\$ 32.72
6	FRONT FENDER BRACKET - CENTER RH	1	\$ 55.00	\$ 44.00
7	FRONT FENDER POP RIVET	6	\$ 23.00	\$ 18.24
8	FRONT FENDER BRACE - RH	1	\$ 132.00	
9	FRONT FENDER BRACKET END - RH	1	\$ 36.00	
10	FRONT FENDER BRACKET - CENTER RH	1	\$ 37.00	
11	FRONT FENDER BRACKET UPPER - RH	1	\$ 37.00	
12	FRONT FENDER BRACKET COVER - RH	1	\$ 13.00	
13	FRONT WHEEL HOUSING LINER - RH	1	\$ 262.00	\$ 209.60
14	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 149.00	
15	FRONT WHEEL SPOILER - RH	1	\$ 82.00	
16	FRONT WHEEL SPOILER LOWER - RH	1	\$ 40.00	
17	FRONT STONE CHIP GUARD - RH	1	\$ 57.00	\$ 45.28
18	FRONT FENDER LEDGE COVER - LONG	1	\$ 35.00	\$ 27.52
19	FRONT FENDER LEDGE COVER - SHORT	1	\$ 26.00	\$ 20.16
20	A/B PILLAR - RH	1	\$ 2,874.00	\$ 2,299.20
SUB TOTAL SPARE PARTS		:	\$ 5,093.00	\$ 3,449.76

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 5633 Y

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>3,449.76</i>
21	RIVETTED CAP NUT	2	\$ 12.00		
22	FRONT SILL TRIM STRIP -RH	1	\$ 133.00	<i>\$</i>	<i>106.00</i>
23	DATA TAG	1	\$ 515.00	<i>\$</i>	<i>412.00</i>
24	FRONT DOOR - RH	1	\$ 3,431.00		
25	FRONT DOOR OUTER SEAL - RH	1	\$ 229.00		
26	BONDING AGENT	1	\$ 51.00		
27	CLEANING SOLUTION	1	\$ 74.00		
28	APPLICATOR	1	\$ 8.00		
29	FRONT DOOR BUNGS	1	\$ 5.00		
30	FRONT DOOR ATTACHMENT PARTS	1	\$ 1,153.00		
31	FRONT DOOR CATCH - RH	1	\$ 116.00		
32	FRONT DOOR WINDOW GUIDE TRIM STRIP	1	\$ 287.00		
33	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - RH	1	\$ 344.00		
34	ASSEMBLY CARRIER	1	\$ 2,096.00		
35	WISHBONE LINK - RH	1	\$ 605.00		
36	WISHBONE SUSPENSION GUIDE - RH	1	\$ 1,057.00		
37	FRONT WISHBONE GUIDE - RH	1	\$ 575.00		
38	REAR WISHBONE GUIDE - RH	1	\$ 575.00		
39	FRONT WHEEL BEARING HOUSING - RH	1	\$ 1,070.00		
40	SWIVEL JOINT	1	\$ 214.00		
SUB TOTAL SPARE PARTS		:	\$ 12,550.00	<i>\$</i>	<i>3,967.76</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 5633 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 3,967.76</i>
41	FRONT WHEEL HUB	1	\$ 498.00	
42	FRONT WHEEL BEARING DOUBLED FLANGE	1	\$ 273.00	
43	SUSPENSION FORKS - RH	1	\$ 293.00	
44	COUPLING ROD	2	\$ 258.00	
45	GAS SHOCK ABSORBER	1	\$ 332.00	
46	TRACK ROD	1	\$ 109.00	
47	TIE ROD END	1	\$ 217.00	
48	ARYLIC SEALANT	S/N	\$ 180.00	<i>\$ 180.00</i>
49	CAVITY WAX	S/N	\$ 140.00	<i>\$ 140.00</i>
50	STONE CHIP	S/N	\$ 180.00	<i>\$ 180.00</i>
51	METAL FILLER POWDER	S/N	\$ 280.00	<i>\$ 280.00</i>
52	RHS FRONT TYRE	S/N	TBC	
53	RHS FRONT RIM	S/N	TBC	
54	ADDED PARTS - SEE ATTACHED		<i>\$ 202.00</i>	<i>\$ 160.72</i>
55	SUNDRIES		\$ 500.00	<i>\$ 31.12</i>
TOTAL SPARE PARTS			\$ 21,105.00	\$ 4,939.60
TOTAL LABOUR CHARGES			\$ 19,242.00	\$ 6,977.00
GRAND TOTAL			\$ 40,347.00	\$ 11,916.60

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-31/08/22



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0304/2022/JT 19-May-22 CHANG 1 of 1 SMQ 5633 Y AUDI A4 SEDAN 2.0 TFSI	
Quantity	Description		Unit Price	Amount
<u>Parts</u>				
1	WASH WATER RESERVIOR	1	\$ 160.00	\$ 127.60
2	FRONT FENDER INNER BRACKET - RH	1	\$ 42.00	\$ 33.12
	GRAND TOTAL		\$ 202.00	\$ 160.72

For Premium Automobiles Pte Ltd

Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT