

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHD82Y

Not Authorized
1/Rmy S

AAD2204-

Vehicle No.:
 Chassis No.:
 UEN No:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

20 APR 2022

SHD82Y
 VF1ABL15AUC282661
 200303878K
 RENAULT
 LATITUDE
 19/04/22
 China - S3N9157E.
 22/03/2016

PART	LIST
1 BUMPER COVER REAR	\$ B 561.70 ✓
1 BUMPER LOWER REAR	\$ M 411.90 ✓
1 BUMPER REFLECTOR RH	\$ P 16.60 X
1 BUMPER REFLECTOR LH	\$ CM 16.60 ✓
1 BUMPER BRACKET CTR REAR	\$ CM 98.10 ✓
1 BUMPER BRACKET SIDE RH REAR	\$ P 82.10 X
1 BUMPER RETAINER RH REAR	\$ L 59.80 X
1 BUMPER BRACKET SIDE LH REAR	\$ L 80.80 X
1 BUMPER RETAINER LH REAR	\$ L 54.20 X
1 FENDER PANEL REAR RH	\$ R 1,933.20 X
1 WHEELARCH REAR RH	\$ P 275.40 X
1 BUMPER BEAM REAR	\$ B 547.80 ✓
1 BUMPER BEAM BRACKET LH REAR	\$ D 114.50 ✓
1 BUMPER BEAM BRACKET RH REAR	\$ D 114.50 ✓
1 OUTER PANEL REAR (End Panel)	\$ B 745.80 ✓
1 OUTER PANEL REAR (End Panel)TRIM	\$ P 404.56 X
1 BOOT REAR	\$ B 1,677.20 ✓
1 BOOT LOCK	\$ R 246.60 X
1 BOOT LOCK CATCH	\$ R 41.70 X
1 BOOT FINISHER	\$ P 344.70 X
1 BOOT WEATHERSTRIP	\$ G 178.20 50% ✓
1 BOOT STRUT LH	\$ P 145.10 X
1 BOOT STRUT RH	\$ L 145.10 X
1 BOOT HINGE LH	\$ R 254.20 X
1 BOOT HINGE RH	\$ R 254.20 X
1 BOOT BADGE 'RENAULT'	\$ R 82.40 ✓

Trans-cab Auto Services Pte Ltd

AAD2204-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD82Y

1 BOOT BADGE	\$	<i>RM</i>	95.80	✓
1 BOOT REFLECTOR LAMP LH	\$	<i>CM</i>	277.70	✓
1 BOOT REFLECTOR LAMP RH	\$	<i>CM</i>	277.70	✓
1 SPARE WHEEL PANEL	\$	<i>R</i>	1,229.40	X
1 TAILLAMP LH	\$	<i>mgcm</i>	401.40	✓
1 TAILLAMP RH	\$	<i>u u</i>	401.40	✓
1 BUMPER COVER FRT	\$	<i>Bj</i>	747.20	✓
1 BUMPER UNDERTRAY FRT	\$	<i>Diy</i>	292.50	✓
1 BUMPER SPOILER FRT	\$	<i>mtj</i>	344.70	✓
1 BUMPER ABSORBER FRT	\$		394.68	?
1 BUMPER BRACKET KIT FRT LH	\$	<i>R</i>	101.40	X
1 BUMPER RETAINER FRT LH	\$	<i>Diy</i>	101.40	✓
1 BUMPER BRACKET KIT FRT RH	\$	<i>R</i>	101.40	X
1 BUMPER RETAINER FRT RH	\$	<i>Diy</i>	101.40	✓
1 BUMPER SUPPORT FRT	\$	<i>R</i>	10.70	X
1 BUMPER GRILLE LOWER FRT	\$	<i>Diy</i>	147.00	✓
1 BUMPER FOG LAMP GRILLE LH	\$	<i>R</i>	207.21	X
1 BUMPER FOG LAMP GRILLE RH	\$	<i>R</i>	207.21	X
1 TOW COVER FRT	\$	<i>R</i>	60.90	X
1 FENDER PANEL FRT LH	\$	<i>R</i>	437.10	X
1 FENDER PANEL FRT RH	\$	<i>R</i>	437.10	X
1 BUMPER UNDERTRAY FRT	\$	<i>R</i>	292.50	X
1 RADIATOR GRILLE	\$	<i>CM</i>	969.90	✓
1 RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>R</i>	225.36	✓
1 RADIATOR GRILLE FRAME	\$		686.00	?
1 FRAME FULL SUPPORT PANEL	\$		592.70	?
1 BONNET	\$	<i>Bj</i>	1,312.70	✓
1 BONNET HINGE LH	\$	<i>R</i>	237.40	X
1 BONNET HINGE RH	\$	<i>R</i>	237.40	X
1 BONNET LOCK	\$	<i>R</i>	152.80	X
1 HEADLAMP LH	\$	<i>mgcm</i>	743.60	✓
1 HEADLAMP RH	\$	<i>u u</i>	744.60	✓
	\$		21,457.22	
10%	\$		2,145.72	
	\$		19,311.50	

Special Nett

1SET PARKING AID

\$

Short 700.00 & own

Trans-cab Auto Services Pte Ltd

AAD2204-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD82Y

1SET REAR BUMPER CLIP	\$	nn	66.00	✓
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	nn	20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	nn	20.00	X
1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	✓
1 REAR BOOT STICKER 'Trans-cab'	\$	nn	80.00	30sn
1 REAR BOOT STICKER '6555-3333'	\$	nn	80.00	30sn
1 EXHAUST MOUNTING REAR	\$	sn	17.82	X
1 FRONT BUMPER CLIP	\$	nn	66.00	✓
1 LICENSE PLATE WITH HOLDER REAR	\$	nd	120.00	45sn
2 LICENSE PLATE WITH HOLDER FRT	\$	miy	121.00	45sn
2 WINDSCREEN SEALANT	\$	nn	150.00	X
1 WINDSCREEN MOULDING	\$	nn	200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	nn	130.00	X
TOTAL	\$		1,856.82	
TOTAL PARTS	\$		21,168.32	

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	nn	300.00	X
Putty And Spray Painting Of The Affected Portion.	\$		3,000.00	132d
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		3,000.00	100d
To Rust-Proofing Of The Affected Areas.	\$		170.00	90d
To reinstall rear bumper parking sensor.	\$		170.00	60d
To transfer of bootlid fittings, attachments and perform water seepage test.	\$		170.00	60d
To repair and realign rear exhaust pipe.	\$	nn	170.00	X

Trans-cab Auto Services Pte Ltd

AAD2204-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD82Y

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i>	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$		170.00	<i>60</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i>	170.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00	X
To Check Electrical Lighting Concerned.	\$		170.00	<i>40</i>
TOTAL	\$		7,880.00	

Over All Total \$ 48,359.81

(LUMP SUM)

Repair Days

20 DAYS

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:


Date:

PTE (EUNOS)

A: SHD82Y

B: STN9157E

C: SMC5663J



Policyholder's Signature & Time:

Driver's Signature (If driver is not the policyholder) Date & Time:

VERIFIED BY AJAX MARS (ARC) REPORTING OFFICER WONG JUN KEAT

Reporting Centre Personnel's Signature Name: NRIC/FIN No.: