



**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD82Y***Not Authorized*  
*1/1/2022 \$8,200.00***AAD2204-**

Vehicle No.:		<b>SHD82Y</b>
Chassis No.:		VF1ABL15AUC282661
UEN No:		200303878K
Vehicle Make:		RENAULT
Vehicle Model:		LATITUDE
Date of Accident :		19/04/22
Third Party Insurer :		China - SJN9157E.
Date of Registration :		22/03/2016

**20 APR 2022**

<b>PART</b>		<b>LIST</b>	
1 BUMPER COVER REAR	\$	<i>B</i> 561.70	✓
1 BUMPER LOWER REAR	\$	<i>M</i> 411.90	✓
1 BUMPER REFLECTOR RH	\$	<i>P</i> 16.60	X
1 BUMPER REFLECTOR LH	\$	<i>CM</i> 16.60	✓
1 BUMPER BRACKET CTR REAR	\$	<i>CM</i> 98.10	✓
1 BUMPER BRACKET SIDE RH REAR	\$	<i>P</i> 82.10	X
1 BUMPER RETAINER RH REAR	\$	<i>P</i> 59.80	X
1 BUMPER BRACKET SIDE LH REAR	\$	<i>P</i> 80.80	X
1 BUMPER RETAINER LH REAR	\$	<i>P</i> 54.20	X
1 FENDER PANEL REAR RH	\$	<i>R</i> 1,933.20	X
1 WHEELARCH REAR RH	\$	<i>P</i> 275.40	X
1 BUMPER BEAM REAR	\$	<i>B</i> 547.80	✓
1 BUMPER BEAM BRACKET LH REAR	\$	<i>D</i> 114.50	✓
1 BUMPER BEAM BRACKET RH REAR	\$	<i>D</i> 114.50	✓
1 OUTER PANEL REAR (End Panel)	\$	<i>B</i> 745.80	✓
1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>P</i> 404.56	X
1 BOOT REAR	\$	<i>B</i> 1,677.20	✓
1 BOOT LOCK	\$	<i>R</i> 246.60	X
1 BOOT LOCK CATCH	\$	<i>R</i> 41.70	X
1 BOOT FINISHER	\$	<i>P</i> 344.70	X
1 BOOT WEATHERSTRIP	\$	<i>GT</i> 178.20	<i>50% on</i>
1 BOOT STRUT LH	\$	<i>P</i> 145.10	X
1 BOOT STRUT RH	\$	<i>P</i> 145.10	X
1 BOOT HINGE LH	\$	<i>R</i> 254.20	X
1 BOOT HINGE RH	\$	<i>R</i> 254.20	X
1 BOOT BADGE 'RENAULT'	\$	<i>M</i> 82.40	✓

**Trans-cab Auto Services Pte Ltd**

**AAD2204-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD82Y**

1 BOOT BADGE	\$	<i>Mr</i>	95.80	✓
1 BOOT REFLECTOR LAMP LH	\$	<i>CM</i>	277.70	✓
1 BOOT REFLECTOR LAMP RH	\$	<i>CM</i>	277.70	✓
1 SPARE WHEEL PANEL	\$	<i>R</i>	1,229.40	X
1 TAILLAMP LH	\$	<i>mgcm</i>	401.40	✓
1 TAILLAMP RH	\$	<i>u u</i>	401.40	✓
1 BUMPER COVER FRT	\$	<i>Bz</i>	747.20	✓
1 BUMPER UNDERTRAY FRT	\$	<i>Diy</i>	292.50	✓
1 BUMPER SPOILER FRT	\$	<i>msy</i>	344.70	✓
1 BUMPER ABSORBER FRT	\$	<i>R</i>	394.68	X
1 BUMPER BRACKET KIT FRT LH	\$	<i>Sn</i>	101.40	X
1 BUMPER RETAINER FRT LH	\$	<i>Diy</i>	101.40	✓
1 BUMPER BRACKET KIT FRT RH	\$	<i>Sn</i>	101.40	X
1 BUMPER RETAINER FRT RH	\$	<i>Diy</i>	101.40	✓
1 BUMPER SUPPORT FRT	\$	<i>Sn</i>	10.70	X
1 BUMPER GRILLE LOWER FRT	\$	<i>Diy</i>	147.00	✓
1 BUMPER FOG LAMP GRILLE LH	\$	<i>Sn</i>	207.21	X
1 BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i>	207.21	X
1 TOW COVER FRT	\$	<i>Sn</i>	60.90	X
1 FENDER PANEL FRT LH	\$	<i>R</i>	437.10	X
1 FENDER PANEL FRT RH	\$	<i>R</i>	437.10	X
1 BUMPER UNDERTRAY FRT	\$	<i>Sn</i>	292.50	X
1 RADIATOR GRILLE	\$	<i>CM</i>	969.90	—
1 RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Mr</i>	225.36	—
1 RADIATOR GRILLE FRAME	\$	<i>Sn</i>	686.00	X
1 FRAME FULL SUPPORT PANEL	\$	<i>Sn</i>	592.70	X
1 BONNET	\$	<i>Bz</i>	1,312.70	✓
1 BONNET HINGE LH	\$	<i>R</i>	237.40	X
1 BONNET HINGE RH	\$	<i>R</i>	237.40	X
1 BONNET LOCK	\$	<i>R</i>	152.80	X
1 HEADLAMP LH	\$	<i>mscm</i>	743.60	✓
1 HEADLAMP RH	\$	<i>u u</i>	744.60	✓
	\$		<b>21,457.22</b>	
	10% \$		<b>2,145.72</b>	
	\$		<b>19,311.50</b>	

**Special Nett**

1SET PARKING AID

\$ *short* 700.00 *4001N*

**Trans-cab Auto Services Pte Ltd**

AAD2204

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD82Y**

1SET REAR BUMPER CLIP	\$	na	66.00	✓
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
1 REAR BOOT STICKER 'Trans-cab'	\$	na	80.00	305na
1 REAR BOOT STICKER '6555-3333'	\$	na	80.00	305na
1 EXHAUST MOUNTING REAR	\$	sn	17.82	X
1 FRONT BUMPER CLIP	\$	na	66.00	✓
1 LICENSE PLATE WITH HOLDER REAR	\$	Red	120.00	455na
2 LICENSE PLATE WITH HOLDER FRT	\$	mi's	121.00	455na
2 WINDSCREEN SEALANT	\$	na	150.00	X
1 WINDSCREEN MOULDING	\$	na	200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	na	130.00	X
<b>TOTAL</b>	<b>\$</b>		<b>1,856.82</b>	
<b>TOTAL PARTS</b>	<b>\$</b>		<b>21,168.32</b>	

**LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	na	300.00	X
Putty And Spray Painting Of The Affected Portion.	\$		3,000.00	132d
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		3,000.00	100d
To Rust-Proofing Of The Affected Areas.	\$		170.00	90d
To reinstall rear bumper parking sensor.	\$		170.00	60d
To transfer of bootlid fittings, attachments and perform water seepage test.	\$		170.00	60d
To repair and realign rear exhaust pipe.	\$	na	170.00	X

**Trans-cab Auto Services Pte Ltd**

**AAD2204-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD82Y**

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i>	170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$		170.00	<i>601</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>401</i>

**TOTAL \$ 7,880.00**

**Over All Total \$ 48,359.81**

**(LUMP SUM)**

**Repair Days**

*20 DAYS*

*7 days*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: