



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MINISTRY OF DEFENCE

HQ TRANSPORT COMMAND

KRANJI CAMP 3

151 CHOA CHU KANG WAYSINGAPORE 688248

Ref: CC2/MIDA22003695/Apq2

Date: 23/08/2022

Code: MIDA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	MID 21263	Veh. Inspected	SLH 2415P
Policy No.		Coverage (\$)	0.00
Claim No.	CY 22/MID21263/130422/0014	Excess (\$)	0.00
Assign From		Assign Date	21/04/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VOXY HYBRID	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	ZWR800210501	Colour	WHITE
Odometer	112132 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	DUNLOP	6 mm
L/H Front Tyre	195/65 R15	DUNLOP	6 mm
R/H Rear Tyre	195/65 R15	DUNLOP	6 mm
L/H Rear Tyre	195/65 R15	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/04/2022	Inspection Date	18/04/2022
Survey held at	SIN FATT DIESEL MOTOR BLK 3020A UBI ROAD 1 #01-38 . SINGAPORE 408714		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 2415P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT HEAD LAMP -LH	CRACKED	1,655.20	1,655.20
1	FRONT HEAD LAMP LOWER BRACKET LH	NOT NECESSARY	78.20	-
1	FRONT BUMPER	DEFORMED	1,558.20	1,025.00
2	FRONT BUMPER SIDE BRACKET @\$135.20	NOT NECESSARY	270.40	-
10	FRONT BUMPER CLIPS @\$5.00	NECESSARY	50.00	30.00
1	FRONT BUMPER GRILL	NOT NECESSARY	285.60	-
1	FRONT BUMPER FOG LAMP -RH	NOT NECESSARY	185.20	-
1	FRONT RH SIDE MIRROR ASSY	CRACKED	925.20	925.20
1	REAR FENDER -RH	NOT NECESSARY	1,552.20	-
	LESS 25% DISCOUNT		-	-908.85
			6,560.20	2,726.55
	<u>LABOUR</u>			
	TO CHECK WIRING SYSTEM.		60.00	30.00
	TUFF KOTE.		120.00	30.00
	PANEL BEATING.		1,000.00	400.00
	SPRAY PAINTING.		1,000.00	500.00
			2,180.00	960.00
	GRAND TOTAL		8,740.20	3,686.55
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,900.00

Report Ref No. CC2/MIDA22003695/Apq2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLH 2415P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLH 2415P

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLH 2415P

RE-INSPECTION

