

SIN FATT DIESEL MOTOR

8 KAKI BUKIT AVE 4 #05-25 PREMIER @ KB SINGAPORE 415875

TAN WEE JIN
BLOCK 3020A UBI ROAD 1
01-33
Singapore 408714

18th APRIL 2022

TP Mindet.
Xiao Tony.

Accident date: 13th APRIL 2022

Estimated repair cost for vehicle no: SLH2415P Toyota Voxy 1.8 '2016'

ZWR800210501

S/n	Qty	Items	U/price	Amount
1	1	Front head lamp -LH <i>cracked</i>		\$1,655.20 ✓
2	1	Front head lamp lower bracket-LH <i>new</i>		\$78.20 X
3	1	Front bumper <i>Deband</i>		\$1,558.20 1025
4	2	Front bumper side bracket <i>new</i>	\$135.20	\$270.40 X
5	10	Front bumper clips <i>new</i>	\$5.00	\$50.00 30
6	1	Front bumper grille <i>new</i>		\$285.60 X
7	1	Front Bumper Fog lamp -RH <i>new</i>		\$185.20 X
8	1	Front RH side mirror Assy <i>cracked</i>		\$925.20 ✓
9	1	Rear fender -RH <i>new</i>		\$1,552.20 X

Subtotal :- \$6,560.20

3635.40
2726.55

Labour charges

To Check Wiring System

~~\$60.00~~ 30

Tuff Kote

960

~~\$120.00~~ 30

Panel beating

~~\$1,000.00~~ 400

Spray painting

~~\$1,000.00~~ 500

Subtotal :- \$2,180.00

Total:- \$8,740.20

total 3686.55
h/s: 2.9K
O/S Rep.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: