

220037001kv
ASSIGNMENT

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12
Singapore 737856

Tel: Fax: Email:

04/20/2022

INSURER :

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	
Policy No:		Date of Loss:	16/04/2022
Vehicle Reg. No.:	SJQ7748Y	Driveable?	no
Driver Age:		Third Party Vehicle No.:	SMP8995M
Any Injuries?	yes	Contact No:	
Insured/Claimant:	SHAIFUL AFIQ BIN MOHAMED SALLEH	Driver:	NUR NADIA BINTE KAMAL RUDIN

PARTS MODEL

Make/Model:	Hyundai, I30 1.6 - KMHDC51DM	Vehicle Reg. Date:	27/05/2009
Vehicle Colour:		Engine Number:	
Chassis No:	KMHDC51DR9U163241	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

DESCRIPTION OF ACCIDENT/LOSS

Description of Accident/loss Collision - Head to Rear
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	3,637.04
Miscellaneous Items	635.00
Labour	1,610.00
Paintwork Labour	1,310.00
Towing	0.00
Gross Total(S\$):	7,192.04
GST 7.00%(S\$):	503.44
Nett Amount(S\$):	7,695.48

This claim is handled by: Sky Toh T C

Not Notified
L1 Rep & 2450h
Resurvey After Paint
Kenneeth (LKK) 4 days
96910663

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

220037001kv ASSIGNMENT

Estimate Report

04/20/2022

AIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER	450.00	-20.00	360.00
2	1	REAR BUMPER SIDE RETAINER LH	80.00	-20.00	64.00
3	1	REAR BUMPER SIDE RETAINER RH	80.00	-20.00	64.00
4	1	REAR BUMPER INNER SPONGE	130.00	-20.00	104.00
5	1	REAR BUMPER REINFORCEMENT	280.00	-20.00	224.00
6	1	REAR TAILGATE	1,801.30	-20.00	1,441.04
7	1	REAR TAILGATE 130 EMBLEM	55.00	-20.00	44.00
8	1	REAR TAILGATE RUBBER	85.00	-20.00	68.00
9	1	REAR TAILGATE LOCK	170.00	-20.00	136.00
10	1	REAR END PANEL	380.00	-20.00	304.00
11	1	REAR END PANEL INNER GARNISH	45.00	-20.00	36.00
12	1	REAR TAILLAMP LH	495.00	-20.00	396.00
13	1	REAR TAILLAMP RH	495.00	-20.00	396.00
Total Parts (\$\$)					3,637.04

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR NUMBER PLATE	45.00	0.00	45.00
2	1	REAR BUMPER CLIPS (1 SET)	40.00	0.00	40.00
3	1	REAR BUMPER SENSORS (1 SET)	250.00	0.00	250.00
4	1	REAR BUMPER CAMERA	200.00	0.00	200.00
5	1	REAR WINDSCREEN SEALANT	100.00	0.00	100.00
Sub Total (\$\$)					635.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	50.00	0.00	50.00
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00
3	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	0.00	100.00
4	1	To Transfer Rear Tailgate.	80.00	0.00	80.00
5	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	1,300.00	0.00	1,300.00

Gross Labour Cost (\$\$) 1,610.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	50.00	0.00	50.00
2	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	60.00	0.00	60.00
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape	1,200.00	0.00	1,200.00