



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
NTUC INCOME INSURANCE CO-OPERATIVE LTD 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 ATTN: CYNDIIE YONG		Ref: CS3/INC21012107/Gvy3e2-1 Date: 26/05/2022 Code: INC	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SNA 2260G	Veh. Inspected	SLG 7000A
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1152798-001	Excess (\$)	0.00
Assign From	CYNDIIE YONG	Assign Date	19/04/2022
2. Vehicle Particulars & Condition			
Make & Model	AUDI TT COUPE 2.0	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	TRUZZZFV5F1007717	Colour	WHITE
Odometer	91837 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/35Z R19	DUNLOP	6 mm
L/H Front Tyre	245/35Z R19	DUNLOP	6 mm
R/H Rear Tyre	245/35Z R19	DUNLOP	6 mm
L/H Rear Tyre	245/35Z R19	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/11/2021	Inspection Date	30/11/2021
Survey held at	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	