



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD C/O TOPLIS AND HARDING (S) PTE LTD 133 CECIL STREET #17-01A KECK SENG TOWER SINGAPORE 069535			Ref: CS/TPS22003706/Evy3e2	
			Date: 02/08/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SKM 6318X	
Policy No.	Y226205	Coverage (\$)	0.00	
Claim No.	SNC22D200008	Excess (\$)	0.00	
Assign From	VICTOR FONG	Assign Date	21/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU FORESTER	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JF1SJ5KC5JG107630	Colour	GREY	
Odometer	55826 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R17	MICHELIN	5 mm	
L/H Front Tyre	225/60 R17	MICHELIN	5 mm	
R/H Rear Tyre	225/60 R17	MICHELIN	5 mm	
L/H Rear Tyre	225/60 R17	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE WHOLE VEHICLE, AFFECTED BY FINE SPRAY PAINTING DROPLETS. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/03/2022	Inspection Date	06/05/2022	
Survey held at	25 LENG KEE ROAD SINGAPORE 159097			
Repairer	MOTOR IMAGE ENTERPRISES PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			15 Working Days	