

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance  
(Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jacqueline Tan

Date: 18 May 2022

## **Preliminary Advice**

Vehicle No	: SMZ9927B	Accident Date	: 19/04/2022
Make	: TOYOTA CAMRY	Policy No.	: DMHCSNW00007662100
Assignment Date	: 21/04/2022	Excess	: S\$2,000.00
Date of Inspection	: 22/04/2022	Est. Duration of Repair	: 5
Inspection At	: DING AUTO PTE LTD (HQ) 176 SIN MING DRIVE #04-06, SIN MING AUTOCARE SINGAPORE 575721		

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 9,210.97	(Estimate \$8,997.97 + Supplementary \$213.00)
Revised Amount	:S\$ 6,743.41	(Inclusive of supplementary)
Check Items (Estimated)	:S\$ 0.00	
Total	:S\$ 6,743.41	
Lump Sum Repair	:S\$	

## **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$ 153,000.00
COE / PARF Rebate	:S\$ 59,532.00
Salvage Value	:S\$
Margin for Repair	:S\$ 93,468.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.