

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKV 8325P Yr Regn: 28/8/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 216i c.c. 1499Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 35942 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA2X92090RD11354

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R17R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front Rear

R/Bal. 4 mm R/Bal. 4 mmL/Bal. 4 mm L/Bal. 4 mmD.O.A. 21/3/22 D.O.I. 27/4/22Survey held at Performance MotorsDes. of Damages: Frt / Rear / O/S / N/S / U/C / Roof or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-114K

29/04/22@4.21pm revised to Victor by email.

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / L.S. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS. \$ _____

Photos _____

Others _____

TOTAL

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



Public only
27/04
loan - 12.000

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 61319
Date Estimated : 30/03/2022
Prepared By : Chua Kee Sin

Page No. : 1 of 6

- ESTIMATE REPAIR FOR -
Scharenguivel Royston George Jr
Blk 53 Chai Chee Street
#13-336

Singapore 460053

- ACCOUNT - 40000
Cash Sales - Service
Singapore

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------------|------------|--------------------|---------|
| SKV8325P | WBA2X92090VD11354 | 28/08/2018 | 216i Active Tourer | 34682 |

DESCRIPTION

Remove and replace the attachment parts item for whole car complete spray

850 x 86

5100

VALUE

10,200.00

Painting whole car surface

14,250 + 6,518

17,388.00

To replace front windscreen glass.

574.00

To conduct water leak tests.

75.00

To supply and install front windscreen solar film.

531.00

To supply and install rear windscreen solar film.

? 531.00

To replace rear windscreen glass.

? 574.00

To check electrical wiring system at the front and rear sections for proper function including adjustment of headlights.

280 295.00

To replace both left and right headlights.

795 837.00

To supply front and rear emboss number plate.

82 165.00

Sundries.

150.00

Estimation repair take a 3weeks to a month

0.00

Total Labour 1: **31,320.00**DESCRIPTION

QTY

PRIC

VALUE

HEX NUT

12

3.00

36.00

GRATE CENTRE CLOSED (LINES/PDC)

1

159.15

159.15

LH FINISHER

1

50.15

50.15

RH FINISHER

1

50.15

50.15

LH MOLDING (SPORT)

1

62.55

62.55

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 61319**
Date Estimated : **30/03/2022**
Prepared By : **Chua Kee Sin**

Page No. : 2 of 6

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------------|------------|--------------------|---------|
| SKV8325P | WBA2X92090VD11354 | 28/08/2018 | 216i Active Tourer | 34682 |

| DESCRIPTION | QTY | PRIC | VALUE |
|--|-----|--------|--------|
| RH MOLDING (SPORT) <i>(stained by paint)</i> | 1 | 62.55 | 62.55 |
| TRIM STRIP CENTRE (SPORT) | 1 | 55.05 | 55.05 |
| LH GRID LATERAL (LINES/PDC) | 1 | 95.55 | 95.55 |
| RH GRID LATERAL (LINES/PDC) | 1 | 95.55 | 95.55 |
| Grille, front left | 1 | 113.15 | 113.15 |
| Grille, front right | 1 | 113.15 | 113.15 |
| CLIP DRIP MOULDING <i>nc</i> | 11 | 2.35 | 25.85 |
| LH ROOF RAILS BLACK | 1 | 482.80 | 482.80 |
| RH ROOF RAILS BLACK | 1 | 482.80 | 482.80 |
| MODEL LETTERING M <i>nc</i> | 2 | 83.80 | 167.60 |
| MODEL LETTERING SIDE (SPORT LINE) <i>nc</i> | 2 | 47.35 | 94.70 |
| EMBLEM (M) <i>nc</i> | 1 | 83.80 | 83.80 |
| GROMMET <i>nc</i> | 2 | 0.80 | 1.60 |
| PLAQUE 74MM <i>nc</i> | 1 | 72.85 | 72.85 |
| RH MIRROR GLASS HEATED WIDE ANGLE <i>X</i> | 1 | 687.20 | 687.20 |
| LH MIRROR GLASS HEATED CONVEX <i>X</i> | 1 | 208.25 | 208.25 |
| LH SUPPORTING RING <i>X</i> | 1 | 59.00 | 59.00 |
| RH SUPPORTING RING <i>X</i> | 1 | 59.00 | 59.00 |
| LH LOWER HOUSING SECTION <i>X</i> | 1 | 46.10 | 46.10 |
| RH LOWER HOUSING SECTION <i>X</i> | 1 | 46.10 | 46.10 |
| LH EXTERIOR MIRROR W/O MOUNTING PAR <i>//</i> | 1 | 496.10 | 496.10 |
| RH EXTERIOR MIRROR W/O MOUNTING PAR <i>//</i> | 1 | 496.10 | 496.10 |
| LH ADDITIONAL TURN INDICATOR LAMP <i>X</i> | 1 | 63.15 | 63.15 |
| LH ADDITIONAL TURN INDICATOR LAMP <i>X</i> | 1 | 63.15 | 63.15 |
| RH ADDITIONAL TURN INDICATOR LAMP <i>X</i> | 1 | 63.15 | 63.15 |
| RH ADDITIONAL TURN INDICATOR LAMP <i>X</i> | 1 | 63.15 | 63.15 |
| BUMP STOP <i>nc</i> | 10 | 3.25 | 32.50 |
| COVER WINDSCREEN TOP <i>?</i> | 1 | 37.85 | 37.85 |
| FRT WINDSCREEN (KAFAS) <i>//</i> | 1 | 826.50 | 826.50 |
| LH DRIP MOULDING <i>//</i> | 1 | 73.45 | 73.45 |
| RH DRIP MOULDING <i>//</i> | 1 | 73.45 | 73.45 |
| REAR WINDOW ESG <i>?</i> | 1 | 620.90 | 620.90 |
| FRT LH DOOR WINDOW GLASS <i>?</i> | 1 | 209.05 | 209.05 |
| FRT RH DOOR WINDOW GLASS <i>?</i> | 1 | 209.05 | 209.05 |
| Seal, outer - mirror left <i>//</i> | 1 | 29.25 | 29.25 |
| RH SEAL OUTER MIRROR TRIANGLE <i>?</i> | 1 | 29.25 | 29.25 |
| FRT LH DOOR EXTERIOR CHANNEL COVER <i>//</i> | 1 | 100.30 | 100.30 |
| FRT RH DOOR EXTERIOR CHANNEL COVER <i>//</i> | 1 | 100.30 | 100.30 |
| FRT LH DOOR WINDOW FRAME COVER (ALU) <i>//</i> | 1 | 60.50 | 60.50 |
| FRT RH DOOR WINDOW FRAME COVER (ALU) <i>//</i> | 1 | 60.50 | 60.50 |
| FRT LH DOOR COLUMN B COVER <i>?</i> | 1 | 56.00 | 56.00 |
| FRT RH COLUMN B COVER <i>?</i> | 1 | 56.00 | 56.00 |
| REAR LH DOOR INNER WEATHERSTRIP <i>X</i> | 1 | 62.45 | 62.45 |
| REAR RH DOOR INNER WEATHERSTRIP <i>X</i> | 1 | 60.90 | 60.90 |
| RR LH DOOR WINDOW GLASS <i>?</i> | 1 | 209.05 | 209.05 |
| RR RH DOOR WINDOW GLASS <i>?</i> | 1 | 209.05 | 209.05 |
| REAR LH DOOR CORNER TRIM <i>?</i> | 1 | 56.35 | 56.35 |
| REAR RH DOOR CORNER TRIM <i>?</i> | 1 | 56.35 | 56.35 |
| LH SEALING COLUMN B BOTTOM <i>?</i> | 1 | 57.10 | 57.10 |

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 3 of 6

Estimate No. : b1 61319
Date Estimated : 30/03/2022
Prepared By : Chua Kee Sin

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------------|------------|--------------------|---------|
| SKV8325P | WBA2X92090VD11354 | 28/08/2018 | 216i Active Tourer | 34682 |

| DESCRIPTION | QTY | PRIC | VALUE |
|--|-----|----------|-----------|
| RH SEALING COLUMN B BOTTOM | 1 | 57.10 | 57.10 |
| REAR LH DOOR OUTER CHANNEL COVER (A | 1 | 100.30 | 100.30 |
| REAR RH DOOR OUTER CHANNEL COVER (A | 1 | 100.30 | 100.30 |
| REAR LH DOOR WINDOW FRAME COVER (AL | 1 | 53.75 | 53.75 |
| REAR RH DOOR WINDOW FRAME COVER (AL | 1 | 53.75 | 53.75 |
| COVER COLUMN B DOOR REAR LH | 1 | 56.00 | 56.00 |
| RR RH COLUMN B COVER | 1 | 56.00 | 56.00 |
| HOOK AND LOOP FASTENER | 4 | 2.50 | 10.00 |
| REAR LH SIDE WINDOW FIXED (ALU HOCH | 1 | 301.05 | 301.05 |
| REAR RH SIDE WINDOW FIXED (ALU HOCH | 1 | 301.05 | 301.05 |
| FRT LH QUARTER LIGHT FIXED (ALU HOC | 1 | 275.95 | 275.95 |
| FRT RH QUARTER LIGHT FIXED (ALU HOC | 1 | 275.95 | 275.95 |
| (S/L) SOUND INSULATION F APRON L136 | 1 | 73.70 | 73.70 |
| REAR DOOR JOINT SEAL | 2 | 33.60 | 67.20 |
| LH SEAL A PILLAR | 1 | 50.30 | 50.30 |
| RH SEAL A PILLAR | 1 | 50.30 | 50.30 |
| PLAQUE 82MM | 1 | 72.85 | 72.85 |
| FRT DOOR JOINT SEAL | 2 | 33.60 | 67.20 |
| LH HEADLIGHT LED TECHNOLOGY | 1 | 2,363.65 | 2,363.65 |
| RH HEADLIGHT LED TECHNOLOGY | 1 | 2,363.65 | 2,363.65 |
| REAR LH LIGHT IN THE SIDE PANEL | 1 | 376.30 | 376.30 |
| REAR RH LIGHT IN THE SIDE PANEL | 1 | 376.30 | 376.30 |
| REAR LH LIGHT IN TRUNK LID | 1 | 263.40 | 263.40 |
| REAR RH LIGHT IN TRUNK LID | 1 | 263.40 | 263.40 |
| LH GUTTER STRIP | 1 | 53.30 | 53.30 |
| RH GUTTER STRIP | 1 | 53.30 | 53.30 |
| THIRD STOPLAMP | 1 | 186.50 | 186.50 |
| (DG) CLEANER R1 (100ML) | 6 | 26.15 | 156.90 |
| (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) | 8 | 131.55 | 1,052.40 |
| (DG/SL)ADHESIVE PRIMER VP 206 (30ML) | 6 | 27.85 | 167.10 |
| Total Parts : | | | 17,640.50 |

Steve (LKK)
27/4/22, 11:30a

M NL
16 dy
PIP

Ng Br Sy

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts must be subject to confirmation
- Resurvey is on a "Without Prejudice" basis
- Repairs must be resurveyed and
- Approval from Insurance Company



Acknowledged by Repairer
Signature:

| | | |
|----------------|---|-----------|
| Labour 1 | : | 31,320.00 |
| Parts | : | 17,640.50 |
| Labour 2 | : | 0.00 |
| Excess | : | 0.00 |
| Total GST @ 7% | : | 3,427.24 |
| Grand Total | : | 52,387.74 |

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **