

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)



Public Buy only  
27/04  
loan - 12000

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Page No. : 1 of 6

Estimate No. : b1 61319  
Date Estimated : 30/03/2022  
Prepared By : Chua Kee Sin

- ESTIMATE REPAIR FOR -  
Scharenguivel Royston George Jr  
Blk 53 Chai Chee Street  
#13-336

Singapore 460053

- ACCOUNT - 40000  
Cash Sales - Service  
Singapore

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL              | MILEAGE |
|-----------|-------------------|------------|--------------------|---------|
| SKV8325P  | WBA2X92090VD11354 | 28/08/2018 | 216i Active Tourer | 34682   |

### DESCRIPTION

Remove and replace the attachment parts item for whole car complete spray

850 x 8

### VALUE

6800 / 10,200.00

Painting whole car surface

16,518 / 17,388.00

To replace front windscreen glass.

574.00

To conduct water leak tests.

75.00

To supply and install front windscreen solar film.

531.00

To supply and install rear windscreen solar film.

X 9 531.00

To replace rear windscreen glass.

X 9 574.00

To check electrical wiring system at the front and rear sections for proper function including adjustment of headlights.

280 / 295.00

To replace both left and right headlights.

795 / 837.00

To supply front and rear emboss number plate.

87 X 165.00

Sundries.

150.00

Estimation repair take a 3 weeks to a month

0.00

Total Labour 1: 31,320.00

| DESCRIPTION                     | QTY | PRIC   | VALUE  |
|---------------------------------|-----|--------|--------|
| HEX NUT                         | 12  | 3.00   | 36.00  |
| GRATE CENTRE CLOSED (LINES/PDC) | 1   | 159.15 | 159.15 |
| LH FINISHER                     | 1   | 50.15  | 50.15  |
| RH FINISHER                     | 1   | 50.15  | 50.15  |
| LH MOLDING (SPORT)              | 1   | 62.55  | 62.55  |

## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438160  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 61319  
Date Estimated : 30/03/2022  
Prepared By : Chua Kee Sin

Page No. : 2 of 6

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL              | MILEAGE |
|-----------|-------------------|------------|--------------------|---------|
| SKV8325P  | WBA2X92090VD11354 | 28/08/2018 | 216i Active Tourer | 34682   |

| DESCRIPTION                                  | QTY | PRIC   | VALUE  |
|----------------------------------------------|-----|--------|--------|
| RH MOLDING (SPORT) <i>(stamped by Point)</i> | 1   | 62.55  | 62.55  |
| TRIM STRIP CENTRE (SPORT)                    | 1   | 55.05  | 55.05  |
| LH GRID LATERAL (LINES/PDC)                  | 1   | 95.55  | 95.55  |
| RH GRID LATERAL (LINES/PDC)                  | 1   | 95.55  | 95.55  |
| Grille, front left                           | 1   | 113.15 | 113.15 |
| Grille, front right                          | 1   | 113.15 | 113.15 |
| CLIP DRIP MOULDING                           | 11  | 2.35   | 25.85  |
| LH ROOF RAILS BLACK                          | 1   | 482.80 | 482.80 |
| RH ROOF RAILS BLACK                          | 1   | 482.80 | 482.80 |
| MODEL LETTERING M                            | 1   | 83.80  | 167.60 |
| MODEL LETTERING SIDE (SPORT LINE)            | 1   | 47.35  | 94.70  |
| EMBLEM (M)                                   | 1   | 83.80  | 83.80  |
| GROMMET                                      | 2   | 0.80   | 1.60   |
| PLAQUE 74MM                                  | 1   | 72.85  | 72.85  |
| RH MIRROR GLASS HEATED WIDE ANGLE            | 1   | 687.20 | 687.20 |
| LH MIRROR GLASS HEATED CONVEX                | 1   | 208.25 | 208.25 |
| LH SUPPORTING RING                           | 1   | 59.00  | 59.00  |
| RH SUPPORTING RING                           | 1   | 59.00  | 59.00  |
| LH LOWER HOUSING SECTION                     | 1   | 46.10  | 46.10  |
| RH LOWER HOUSING SECTION                     | 1   | 46.10  | 46.10  |
| LH EXTERIOR MIRROR W/O MOUNTING PAR          | 1   | 496.10 | 496.10 |
| RH EXTERIOR MIRROR W/O MOUNTING PAR          | 1   | 496.10 | 496.10 |
| LH ADDITIONAL TURN INDICATOR LAMP            | 1   | 63.15  | 63.15  |
| LH ADDITIONAL TURN INDICATOR LAMP            | 1   | 63.15  | 63.15  |
| RH ADDITIONAL TURN INDICATOR LAMP            | 1   | 63.15  | 63.15  |
| RH ADDITIONAL TURN INDICATOR LAMP            | 1   | 63.15  | 63.15  |
| BUMP STOP                                    | 10  | 3.25   | 32.50  |
| COVER WINDSCREEN TOP                         | 1   | 37.85  | 37.85  |
| FRT WINDSCREEN (KAFAS)                       | 1   | 826.50 | 826.50 |
| LH DRIP MOULDING                             | 1   | 73.45  | 73.45  |
| RH DRIP MOULDING                             | 1   | 73.45  | 73.45  |
| REAR WINDOW ESG                              | 1   | 620.90 | 620.90 |
| FRT LH DOOR WINDOW GLASS                     | 1   | 209.05 | 209.05 |
| FRT RH DOOR WINDOW GLASS                     | 1   | 209.05 | 209.05 |
| Seal, outer - mirror left                    | 1   | 29.25  | 29.25  |
| RH SEAL OUTER MIRROR TRIANGLE                | 1   | 29.25  | 29.25  |
| FRT LH DOOR EXTERIOR CHANNEL COVER           | 1   | 100.30 | 100.30 |
| FRT RH DOOR EXTERIOR CHANNEL COVER           | 1   | 100.30 | 100.30 |
| FRT LH DOOR WINDOW FRAME COVER (ALU)         | 1   | 60.50  | 60.50  |
| FRT RH DOOR WINDOW FRAME COVER (ALU)         | 1   | 60.50  | 60.50  |
| FRT LH DOOR COLUMN B COVER                   | 1   | 56.00  | 56.00  |
| FRT RH COLUMN B COVER                        | 1   | 56.00  | 56.00  |
| REAR LH DOOR INNER WEATHERSTRIP              | 1   | 62.45  | 62.45  |
| REAR RH DOOR INNER WEATHERSTRIP              | 1   | 60.90  | 60.90  |
| RR LH DOOR WINDOW GLASS                      | 1   | 209.05 | 209.05 |
| RR RH DOOR WINDOW GLASS                      | 1   | 209.05 | 209.05 |
| REAR LH DOOR CORNER TRIM                     | 1   | 56.35  | 56.35  |
| REAR RH DOOR CORNER TRIM                     | 1   | 56.35  | 56.35  |
| LH SEALING COLUMN B BOTTOM                   | 1   | 57.10  | 57.10  |

## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Page No. : 3 of 6

Estimate No. : b1 61319  
Date Estimated : 30/03/2022  
Prepared By : Chua Kee Sin

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL              | MILEAGE |
|-----------|-------------------|------------|--------------------|---------|
| SKV8325P  | WBA2X92090VD11354 | 28/08/2018 | 216i Active Tourer | 34682   |

| DESCRIPTION                                         | QTY | PRIC                     | VALUE     |
|-----------------------------------------------------|-----|--------------------------|-----------|
| RH SEALING COLUMN B BOTTOM <i>am 1 x m</i>          | 1   | 57.10                    | 57.10     |
| REAR LH DOOR OUTER CHANNEL COVER (A) <i>11</i>      | 1   | 100.30 <i>101.80</i>     | 100.30    |
| REAR RH DOOR OUTER CHANNEL COVER (A) <i>11</i>      | 1   | 100.30 <i>101.80</i>     | 100.30    |
| REAR LH DOOR WINDOW FRAME COVER (AL) <i>11</i>      | 1   | 53.75 <i>54.60</i>       | 53.75     |
| REAR RH DOOR WINDOW FRAME COVER (AL) <i>11</i>      | 1   | 53.75 <i>54.60</i>       | 53.75     |
| COVER COLUMN B DOOR REAR LH <i>11</i>               | 1   | 56.00 <i>56.85</i>       | 56.00     |
| RR RH COLUMN B COVER <i>11</i>                      | 1   | 56.00 <i>56.85</i>       | 56.00     |
| HOOK AND LOOP FASTENER <i>11</i>                    | 4   | 2.50                     | 10.00     |
| REAR LH SIDE WINDOW FIXED (ALU HOCH) <i>11</i>      | 1   | 301.05 <i>305.60</i>     | 301.05    |
| REAR RH SIDE WINDOW FIXED (ALU HOCH) <i>11</i>      | 1   | 301.05 <i>305.60</i>     | 301.05    |
| FRT LH QUARTER LIGHT FIXED (ALU HOC) <i>11</i>      | 1   | 275.95 <i>280.10</i>     | 275.95    |
| FRT RH QUARTER LIGHT FIXED (ALU HOC) <i>11</i>      | 1   | 275.95 <i>280.10</i>     | 275.95    |
| (S/L) SOUND INSULATION F APRON L136 <i>11</i>       | 1   | 73.70 <i>74.85</i>       | 73.70     |
| REAR DOOR JOINT SEAL <i>(Front Door Joint Seal)</i> | 2   | 33.60 <i>34.05</i>       | 67.20     |
| LH SEAL A PILLAR <i>11</i>                          | 1   | 50.30                    | 50.30     |
| RH SEAL A PILLAR <i>11</i>                          | 1   | 50.30                    | 50.30     |
| PLAQUE 82MM <i>11</i>                               | 1   | 72.85                    | 72.85     |
| FRT DOOR JOINT SEAL <i>11</i>                       | 2   | 33.60 <i>34.05</i>       | 67.20     |
| LH HEADLIGHT LED TECHNOLOGY <i>11</i>               | 1   | 2,363.65 <i>2,399.10</i> | 2,363.65  |
| RH HEADLIGHT LED TECHNOLOGY <i>11</i>               | 1   | 2,363.65 <i>2,399.10</i> | 2,363.65  |
| REAR LH LIGHT IN THE SIDE PANEL <i>11</i>           | 1   | 376.30 <i>382</i>        | 376.30    |
| REAR RH LIGHT IN THE SIDE PANEL <i>11</i>           | 1   | 376.30 <i>382</i>        | 376.30    |
| REAR LH LIGHT IN TRUNK LID <i>11</i>                | 1   | 263.40 <i>267.40</i>     | 263.40    |
| REAR RH LIGHT IN TRUNK LID <i>11</i>                | 1   | 263.40 <i>267.40</i>     | 263.40    |
| LH GUTTER STRIP <i>11</i>                           | 1   | 53.30 <i>57.75</i>       | 53.30     |
| RH GUTTER STRIP <i>11</i>                           | 1   | 53.30 <i>57.75</i>       | 53.30     |
| THIRD STOPLAMP <i>11</i>                            | 1   | 186.50                   | 186.50    |
| (DG) CLEANER R1 (100ML) <i>11</i>                   | 18  | 26.15                    | 156.90    |
| (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>11</i>    | 28  | 131.55                   | 1,052.40  |
| (DG/SL)ADHESIVE PRIMER VP 206 (30ML) <i>11</i>      | 6   | 27.85                    | 167.10    |
| Total Parts :                                       |     |                          | 17,640.50 |

Steve (LKK)  
27/4/22, 11:00

ML NL  
29 16 dy  
PIP  
Ng B1 Sy

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after survey
- To display damaged part(s) during resurvey
- Part(s) are subject to confirmation
- on a "Without Prejudice" basis
- for insurance claim
- to be surveyed and
- approval from insurance Company



Acknowledged by Repairer  
Signature:

|                |   |           |
|----------------|---|-----------|
| Labour 1       | : | 31,320.00 |
| Parts          | : | 17,640.50 |
| Labour 2       | : | 0.00      |
| Excess         | : | 0.00      |
| Total GST @ 7% | : | 3,427.24  |
| Grand Total    | : | 52,387.74 |

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*