

J.E.W Motor Pte Ltd

60 Jalan Lam Huat #03-72, Carros Center Singapore 737869

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SJN 1848Y**
 Made : Toyota
 Model : Sienta Hybrid
 Chassis No : _____

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Rear Bumper	1	\$ 642.00	\$ del 642.00	✓
2	Rear Bumper Upper Centre	1	\$ 195.20	\$ del 195.20	✓
3	Rear Bumper Reflector RH	1	\$ 58.60	\$ X nn 58.60	
4	Rear Bumper Reflector LH	1	\$ 58.60	\$ cut 58.60	✓
5	Rear Bumper Reflector Garnish RH	1	\$ 128.70	\$ X nn 128.70	
6	Rear Bumper Reflector Garnish LH	1	\$ 128.70	\$ cut 128.70	✓
7	Rear Bumper Side Retainer RH	1	\$ 69.80	\$ X nn 69.80	
8	Rear Bumper Side Retainer LH	1	\$ 69.80	\$ cut 69.80	✓
9	Rear Bumper Tow Hook Cover	1	\$ 24.70	\$ del 24.70	✓
10	Rear Bumper Reverse Sensor	2	\$ 172.40	\$ del 344.80	200 ✓
11	Rear Taillamp Assembly RH	1	\$ 520.70	\$ X nn 520.70	
12	Rear Taillamp Assembly LH	1	\$ 520.70	\$ cut 520.70	450 ✓
13	Rear Taillamp Lower Bracket RH	1	\$ 45.60	\$ X nn 45.60	
14	Rear Taillamp Lower Bracket LH	1	\$ 45.60	\$ cut 45.60	✓
15	Rear Tailgate	1	\$ 1,142.50	\$ del 1,142.50	✓
16	Rear Tailgate Reflector Lamp RH	1	\$ 520.70	\$ X nn 520.70	
17	Rear Tailgate Reflector Lamp LH	1	\$ 520.70	\$ cut 520.70	281 ✓
18	Rear Tailgate Outer Garnish	1	\$ 243.70	\$ cut 243.70	✓
19	Rear Tailgate Inner Handle	1	\$ 76.40	\$ X nn 76.40	
20	Rear Tailgate Emblem	1	\$ 68.20	\$ del 68.20	✓
21	Rear Tailgate "Hybrid Synergy Drive" Emblem	1	\$ 52.50	\$ del 52.50	✓
22	Rear Tailgate Lock Assembly	1	\$ 472.40	\$ X nn 472.40	
23	Rear Tailgate Lock Catch	1	\$ 38.90	\$ X nn 38.90	
24	Rear Tailgate Hinge RH	1	\$ 61.20	\$ X nn 61.20	
25	Rear Tailgate Hinge LH	1	\$ 61.20	\$ X nn 61.20	
26	Rear Tailgate Damper RH	1	\$ 229.70	\$ X nn 229.70	
27	Rear Tailgate Damper LH	1	\$ 229.70	\$ X nn 229.70	
28	Rear Tailgate Inner Trim	1	\$ 578.60	\$ X nn 578.60	
29	Rear Tailgate Stopper	2	\$ 24.60	\$ X nn 49.20	
30	Rear Tailgate Weatherstrip	1	\$ 376.00	\$ cut 376.00	✓
31	Rear Tailgate Detector	1	\$ 239.10	\$ X nn 239.10	
32	Rear Tailgate Detector Wire Harness	1	\$ 288.90	\$ X nn 288.90	

33	Rear Tailgate Windscreen Glass Moulding	1	\$	97.80	\$ ne ✓	97.80	✓
34	Rear End Panel (Outer)	1	\$	438.20	\$ H ✓	438.20	✓
35	Rear End Panel (Inner)	1	\$	702.90	\$ Ry	702.90	
36	Rear End Panel Top Garnish	1	\$	145.20	\$ de ✓	145.20	✓
37	Rear Storage Box	1	\$	123.20	\$ de ✓	123.20	✓
38	Rear Storage Box Cover Board	1	\$	475.10	\$ X nn	475.10	
39	Rear Floor Panel	1	\$	698.20	\$ X nn	698.20	
40	Rear Fender Inner Trim Board RH	1	\$	627.10	\$ X nn	627.10	
41	Rear Fender Inner Trim Board LH	1	\$	627.10	\$ de ✓	627.10	✓
42	Rear Fender Inner Cowling RH	1	\$	129.10	\$ X nn	129.10	
43	Rear Fender Inner Cowling LH	1	\$	129.10	\$ X nn	129.10	
44	Rear Exhaust Pipe	1	\$	925.40	\$ X nn	925.40	
45	Rear Exhaust Pipe Mounting	2	\$	32.00	\$ X nn	64.00	
					Parts Sub Total :	\$ 13,285.50	
					Discount	\$ 3,321.38	
					PARTS TOTAL :	\$ 9,964.13	

5410
-25%
4057.50

25%

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Rear Number Plate	1	\$ 50.00	\$ X nn 50.00	
2	Rear Bumper Clips - Set	1	\$ 50.00	\$ 30 ne ✓	50.00
3	Rear Taillamp Assembly Clips - Set	1	\$ 50.00	\$ 10 ne ✓	50.00
4	Rear Tailgate Reflector Lamp Clips - Set	1	\$ 50.00	\$ X nn	50.00
5	Rear Tailgate inner Trim Clips - Set	1	\$ 40.00	\$ X nn	40.00
6	Rear Tailgate Outer Garnish Clips - Set	1	\$ 40.00	\$ X nn	40.00
7	Rear End Panel Top Garnish Clips - Set	1	\$ 50.00	\$ 20 ne ✓	50.00
8	Rear Fender Inner Trim Board Clips - Set	1	\$ 80.00	\$ X nn	80.00
9	Rear Fender Inner Cowling Clips - Set	1	\$ 40.00	\$ X nn	40.00
10	Rear Tailgate Windscreen Glass Sealant	1	\$ 120.00	\$ 50 ne ✓	120.00
11	Rear Tailgate Sealant	1	\$ 150.00	\$ X nn	150.00
12	Rear End Panel Outer Sealant	1	\$ 120.00	\$ 40 ne ✓	120.00
13	Rear End Panel Inner Sealant	1	\$ 120.00	\$ X nn	120.00
14	Rear Floor Panel Sealant	1	\$ 150.00	\$ X nn	150.00
15	Rear Tailgate Reverse Camera	1	\$ 500.00	\$ 250 ✓	500.00
				SPECIAL NETT TOTAL :	\$ 1,610.00

400

Nos.	LABOUR	S\$	
1	To Panel Beat, Remove & Refix Parts	\$ 700	1,800.00
2	To Spray Paint Affected Areas	\$ 700	1,600.00
3	Wiring & Bulb Check	\$ 30	100.00
4	To Transfer Rear Tailgate Mechanism	\$ 60	150.00
5	To Remove & Refix Rear Tailgate Windscreen Glass	\$ 120	150.00
6	To Remove & Refix Rear Bumper Reverse Sensor	\$ 30	120.00
7	To Remove & Refix Rear Tailgate Reverse Camera	\$ 30	150.00
8	To Remove & Refix Rear Exhaust Pipe	\$ X	120.00
9	To apply anti rust on affected parts	\$ 40.	100.00
10	To Remove & Refix Interior Upholstry to facilitate repairs	\$ 60	150.00
11	To Conduct Water Leak Test	\$ X	100.00
12	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ X	480.00
		1770	LABOUR TOTAL : \$ 5,020.00

Traffic 27475749 / 62563561

'WP' 22/4/22 @ 4pm 6227.50

c/s Resurvey after repair L/S - 4982
= 5000

fauphan @ khantoon
6 days

PARTS TOTAL : \$ 9,964.13

SPECIAL NETT TOTAL : \$ 1,610.00

LABOUR TOTAL : \$ 5,020.00

GRAND TOTAL : \$ 16,594.13

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: