

ASS. REC. BY: Taught

REF: CS/CTI 22003711/Ty3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: GBC 820K

Policy No. DMCVSNA00013262200

Claims No. SNM22D202677/C02/TANKL


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 199K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJN1848Y Yr Regn: 2019, July

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Sienta Hybrid. c.c 1496

Colour: white. A/C: Insured / Std / NI / NA

Sp. Reading: 77364 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NHP170 715 8004

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: 22

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 0 mm R/Bal. 0 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 19/4/2022 D.O.I. 22/4/22

Survey held at J.E.W

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
29/4/23	Lump Sum \$5000 confirmed by email (Red 11,594.13, 69%)

Date/Time, File Pass to? ☐ : Prel. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 2/5/23-typist

Report Format: Merimen

Lump Sum / L.S. / \$5000

Days Of Repair: 6

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

 S + RS SI

Photos

Others

TOTAL

J.E.W Motor Pte Ltd

60 Jalan Lam Huat #03-72, Carros Center Singapore 737869

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : SJN 1848Y
 Made : Toyota
 Model : Sienta Hybrid
 Chassis No : _____

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Bumper	1	\$ 642.00	\$ de ✓ 642.00
2	Rear Bumper Upper Centre	1	\$ 195.20	\$ de ✓ 195.20
3	Rear Bumper Reflector RH	1	\$ 58.60	\$ X 58.60
4	Rear Bumper Reflector LH	1	\$ 58.60	\$ cut ✓ 58.60
5	Rear Bumper Reflector Garnish RH	1	\$ 128.70	\$ X 128.70
6	Rear Bumper Reflector Garnish LH	1	\$ 128.70	\$ cut ✓ 128.70
7	Rear Bumper Side Retainer RH	1	\$ 69.80	\$ X 69.80
8	Rear Bumper Side Retainer LH	1	\$ 69.80	\$ cut ✓ 69.80
9	Rear Bumper Tow Hook Cover	1	\$ 24.70	\$ de ✓ 24.70
10	Rear Bumper Reverse Sensor	2	\$ 172.40	\$ cut ✓ 344.80
11	Rear Taillamp Assembly RH	1	\$ 520.70	\$ X 520.70
12	Rear Taillamp Assembly LH	1	\$ 520.70	\$ cut ✓ 520.70
13	Rear Taillamp Lower Bracket RH	1	\$ 45.60	\$ X 45.60
14	Rear Taillamp Lower Bracket LH	1	\$ 45.60	\$ cut ✓ 45.60
15	Rear Tailgate	1	\$ 1,142.50	\$ cut ✓ 1,142.50
16	Rear Tailgate Reflector Lamp RH	1	\$ 520.70	\$ X 520.70
17	Rear Tailgate Reflector Lamp LH	1	\$ 520.70	\$ cut ✓ 520.70
18	Rear Tailgate Outer Garnish	1	\$ 243.70	\$ cut ✓ 243.70
19	Rear Tailgate Inner Handle	1	\$ 76.40	\$ X 76.40
20	Rear Tailgate Emblem	1	\$ 68.20	\$ cut ✓ 68.20
21	Rear Tailgate "Hybrid Synergy Drive" Emblem	1	\$ 52.50	\$ cut ✓ 52.50
22	Rear Tailgate Lock Assembly	1	\$ 472.40	\$ X 472.40
23	Rear Tailgate Lock Catch	1	\$ 38.90	\$ X 38.90
24	Rear Tailgate Hinge RH	1	\$ 61.20	\$ X 61.20
25	Rear Tailgate Hinge LH	1	\$ 61.20	\$ X 61.20
26	Rear Tailgate Damper RH	1	\$ 229.70	\$ X 229.70
27	Rear Tailgate Damper LH	1	\$ 229.70	\$ X 229.70
28	Rear Tailgate Inner Trim	1	\$ 578.60	\$ X 578.60
29	Rear Tailgate Stopper	2	\$ 24.60	\$ X 49.20
30	Rear Tailgate Weatherstrip	1	\$ 376.00	\$ cut ✓ 376.00
31	Rear Tailgate Detector	1	\$ 239.10	\$ X 239.10
32	Rear Tailgate Detector Wire Harness	1	\$ 288.90	\$ X 288.90

33	Rear Tailgate Windscreen Glass Moulding	1	\$	97.80	\$ <i>neu</i>	97.80
34	Rear End Panel (Outer)	1	\$	438.20	\$ <i>H</i>	438.20
35	Rear End Panel (Inner)	1	\$	702.90	\$ <i>Ry</i>	702.90
36	Rear End Panel Top Garnish	1	\$	145.20	\$ <i>de</i>	145.20
37	Rear Storage Box	1	\$	123.20	\$ <i>de</i>	123.20
38	Rear Storage Box Cover Board	1	\$	475.10	\$ <i>X</i>	475.10
39	Rear Floor Panel	1	\$	698.20	\$ <i>X</i>	698.20
40	Rear Fender Inner Trim Board RH	1	\$	627.10	\$ <i>X</i>	627.10
41	Rear Fender Inner Trim Board LH	1	\$	627.10	\$ <i>de</i>	627.10
42	Rear Fender Inner Cowling RH	1	\$	129.10	\$ <i>X</i>	129.10
43	Rear Fender Inner Cowling LH	1	\$	129.10	\$ <i>X</i>	129.10
44	Rear Exhaust Pipe	1	\$	925.40	\$ <i>X</i>	925.40
45	Rear Exhaust Pipe Mounting	2	\$	32.00	\$ <i>R</i>	64.00
Parts Sub Total :					\$	13,285.50
25% Discount					\$	3,321.38
PARTS TOTAL :					\$	9,964.13

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear Number Plate	1	\$ 50.00	\$ <i>X</i> 50.00
2	Rear Bumper Clips - Set	1	\$ 50.00	\$ <i>30 neu</i> 50.00
3	Rear Taillamp Assembly Clips - Set	1	\$ 50.00	\$ <i>10 neu</i> 50.00
4	Rear Tailgate Reflector Lamp Clips - Set	1	\$ 50.00	\$ <i>X</i> 50.00
5	Rear Tailgate inner Trim Clips - Set	1	\$ 40.00	\$ <i>X</i> 40.00
6	Rear Tailgate Outer Garnish Clips - Set	1	\$ 40.00	\$ <i>X</i> 40.00
7	Rear End Panel Top Garnish Clips - Set	1	\$ 50.00	\$ <i>20 neu</i> 50.00
8	Rear Fender Inner Trim Board Clips - Set	1	\$ 80.00	\$ <i>X</i> 80.00
9	Rear Fender Inner Cowling Clips - Set	1	\$ 40.00	\$ <i>X</i> 40.00
10	Rear Tailgate Windscreen Glass Sealant	1	\$ 120.00	\$ <i>50 neu</i> 120.00
11	Rear Tailgate Sealant	1	\$ 150.00	\$ <i>X</i> 150.00
12	Rear End Panel Outer Sealant	1	\$ 120.00	\$ <i>40 neu</i> 120.00
13	Rear End Panel Inner Sealant	1	\$ 120.00	\$ <i>X</i> 120.00
14	Rear Floor Panel Sealant	1	\$ 150.00	\$ <i>X</i> 150.00
15	Rear Tailgate Reverse Camera	1	\$ 500.00	\$ <i>250</i> 500.00
SPECIAL NETT TOTAL :				\$ 1,610.00

Nos.	LABOUR	S\$	
1	To Panel Beat, Remove & Refix Parts	\$ 700	1,800.00
2	To Spray Paint Affected Areas	\$ 700	1,600.00
3	Wiring & Bulb Check	\$ 30	100.00
4	To Transfer Rear Tailgate Mechanism	\$ 60	150.00
5	To Remove & Refix Rear Tailgate Windscreen Glass	\$ 120	150.00
6	To Remove & Refix Rear Bumper Reverse Sensor	\$ 30	120.00
7	To Remove & Refix Rear Tailgate Reverse Camera	\$ 30	150.00
8	To Remove & Refix Rear Exhaust Pipe	\$ X	120.00
9	To apply anti rust on affected parts	\$ 40.	100.00
10	To Remove & Refix Interior Upholstry to facilitate repairs	\$ 60	150.00
11	To Conduct Water Leak Test	\$ X	100.00
12	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ X	480.00
LABOUR TOTAL :		\$	5,020.00

Trahan 97495749 / 62563561
 'WP' 22/4/22 @ 4pm
 c/s Resurvey after repair
 fauher@lkhauto.com
 6 days

PARTS TOTAL : \$ 9,964.13
 SPECIAL NETT TOTAL : \$ 1,610.00
 LABOUR TOTAL : \$ 5,020.00
GRAND TOTAL : \$ 16,594.13

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date of Accident : 19/4/2022 Accident Time: 16.57 (24-HR-Format)
Accident Place : Posir Ru Dr 1
Vehicle No. (Car Plate No.) : SJN 1848Y Make/Model: Toyota Sienna
Insurance Company : China Taiping Policy No: DMHCS/W00007552100
Owner or Company Name / IC No. : Lai Sok Keng Irene SF836942F
Owner or Company Contact No. : — Owner's Hp 9168 1784 Company Tel
DRIVER'S Name / IC No. : Lai Sok Keng Irene SF836942F
DRIVER'S Date Of Birth : 18/12/1978 DRIVER'S License Pass Date 18/9/2006
Relationship of Owner & Driver : Spouse \ Parent \ Children \ Sibling \ Employee \ Others
DRIVER'S Address : BIK 227, Posir Ru st 21 #08-100
DRIVER'S Contact No. / Alt No. : 1) — 2) S(510227)
DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)
Email Address : irene_cream@hotmail.com
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance
Number of Passengers (including Driver): 1

Was there any video Captured by car camera: YES NO

Exact purpose for which vehicle was being used at time of accident: Private use \ Work Purpose
Any Injury (If YES, Pls state): Yes. Neck and shoulder pain.

Other Party Driver's Particular (If any)

Vehicle No: <u>GBC 820K</u>	Vehicle No: _____
Vehicle Make \ Model: <u>Toyota Van.</u>	Vehicle Make \ Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

NEW - Passenger's name & gender:

Sketch Plan

IMPORTANT NOTICE

- [illegible]

2. Government under the Federal Reserve Act (1913)

1. பெரியகோட்டை, மதுரை மாவட்டம், கருமலை கிராமம்

[illegible]

經傳謂：「子思作春秋，而左丘明作傳，而左丘明作傳，而左丘明作傳。」

[illegible]

[Faint, illegible handwritten text]

1. 世界各國的歷史，都是經過無數次的革命而來的。革命是人類進步的動力，是人類解放的途徑。在人類歷史的長河中，革命是不可避免的。

1. 凡在本行开立存款账户的客户，均可向本行申请开立支票。

॥ श्रीगणेशाय नमः ॥

「我係香港人，香港係中國嘅一部分，中國係中國人嘅家鄉，中國人係中國嘅主人，中國係中國人嘅家鄉，中國係中國人嘅主人，中國係中國人嘅家鄉，中國係中國人嘅主人。」

[illegible]

1. Signature of the holder / Date 3
 12/12/2023

பெரிய கிணறுக்கு அருகில் உள்ள பழைய கட்டிடம்

ॐ नमो भगवते वासुदेवाय ॥ १ ॥
 श्रीकृष्णाय नमः ॥

Sketches of the

Poor Res Dr 1

① SIN 1848 Y

(B) GBC 820 K

Describe Circumstances of the Accident

veh in front all came to a stop as the traffic light was red. I also stop my veh. while stationary, I felt a very great impact from my veh rear portion. I then realised that veh B had hit onto my veh.

Declaration:

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
Time



Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	942F
Vehicle Details	
Vehicle No.:	SJN1848Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	21 Apr 2022
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA HYBRID 1.5G CVT
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	1NZR745910
Chassis No.:	NHP1707158004
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$27,675.00
Original Registration Date:	25 Jul 2019
First Registration Date:	25 Jul 2019
Transfer Count:	0
Actual ARF Paid:	\$20,745.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jul 2029
PARF Rebate Amount:	\$15,558.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jul 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$33,199.00
COE Rebate Amount:	\$24,096.00
Total Rebate Amount:	\$39,654.00

The information contained herein is correct as at 20 Apr 2022

OK