

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: **EST2200116**
Date: 19 Apr 2022
Veh Reg No: **SDV5336K**
Make/Model: TOYOTA HARRIER
ELEGANCE 2.0 A
Chasis No: ZSU600073099
Reg. Date: 08/04/2016
Your Ref No: SMR9046K

Claim Type: Third Party
Accident Date: 09/04/2022
TP Veh Reg No: SMR9046K

Estimate Repair Cost to Vehicle No :SDV5336K

Quantity	Description	List Price S\$	Amount S\$
Special Net			
1	1 PC FRT BUMPER	1,400.00	
2	1 PC FRT BUMPER GRILLE	350.00	
3	1 PC FRT GRILLE	650.00	
		2,400.00	2,400.00
Labour			
4	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	600.00	
5	1 TO SPRAY PAINTING	800.00	
6	1 TO CHECK WIRING	50.00	
		1,450.00	1,450.00
Total			S\$ 3,850.00
Add GST @ 7%			269.50
Total Amount Payable			<u>S\$ 4,119.50</u>

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND ONE HUNDRED NINETEEN AND CENTS FIFTY ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

AT

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE