



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2204780

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 03/08/2022
Reference CC3/CTI22003721/Vpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 6547J
Insured Veh. SLD 1061D
Claim No. SNM22D202717
Policy No. DMHCSNA00004192100
Accident Date 14/04/2022
Inspection Date 14/04/2022

Description	Total
Survey Inspection	280.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	280.00
GST (7%)	19.60
Grand Total	299.60

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI22003721/Vpa3q2 Date: 03/08/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLD 1061D	Veh. Inspected	SHD 6547J	
Policy No.	DMHCSNA00004192100	Coverage (\$)	0.00	
Claim No.	SNM22D202717	Excess (\$)	0.00	
Assign From		Assign Date	14/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI IONIQ	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KMHC851CVLU187858	Colour	BLUE	
Odometer	364159 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/04/2022	Inspection Date	14/04/2022	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6547J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER COVER	DEFORMED	459.40	459.40
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER CENTRE MOULDING ASSY	CUT	451.25	451.25
1	REAR BUMPER REINFORCEMENT	DENTED	394.80	394.80
2	REAR BUMPER REINFORCEMENT BRACKET LH/RH @ \$138.10	N/S DENTED	276.20	138.10
1	REAR BUMPER FOG LAMP	CRACKED	201.50	201.50
1	REAR BUMPER LICENCE LAMP	SERVICEABLE	85.30	-
1	ANTENNA ASSY SMARTKEY	SERVICEABLE	40.50	-
1	REAR BUMPER TOWING COVER	CUT	94.60	94.60
1	REAR PANEL	TO REPAIR SEE LABOUR	532.00	-
1	REAR PANEL GARNISH	SERVICEABLE	346.80	-
2	REAR BUMPER SIDE BRACKET LH RH @\$55.80	NECESSARY	111.60	111.60
1	REAR BUMPER LOWER CTR MOULDING	NECESSARY	155.00	155.00
1	BOOTLID	DENTED	2,549.70	2,549.70
1	BOOTLID HYUNDAI PLATE	NOT NECESSARY	24.30	-
1	EMBLEM HYBRID	NECESSARY	24.30	24.30
1	EMBLEM-LONIQ	NECESSARY	31.30	31.30
2	BOOT LID LAMP LH RH @\$822.00	SERVICEABLE	1,644.00	-
1	REAR BUMPER UNDER CENTRE COVER	SERVICEABLE	225.00	-
	LESS 20% DISCOUNT		-1,533.91	-926.71
			6,135.64	3,706.84
<u>SPECIAL NETT ITEMS</u>				
1	REAR FENDER ADVERTISEMENT LOGO LH (SN)	NECESSARY	100.00	100.00
1	REAR FENDER ADVERTISEMENT LOGO RH (SN)	NECESSARY	100.00	100.00
1	BOOTLID ADVERTISEMENT LOGO (SN)	NECESSARY	100.00	100.00
1	REAR NUMBER PLATE WITH TRIM COVER (SN)	NECESSARY	55.00	55.00
1	BOOTLID COMFORT TEL NO STICKER (SN)	NECESSARY	40.00	40.00
1	BOOTLID COMFORT LOGO STICKER (SN)	NECESSARY	30.00	30.00
1	BOOTLID COMFORT APP STICKER (SN)	NECESSARY	30.00	30.00

Report Ref No. CC3/CTI22003721/Vpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER REVERSE SENSOR (SN)	CUT	180.00	180.00
			635.00	635.00
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR PANEL .		1,100.00	700.00
	SPRAY PAINTING CHARGE.		800.00	500.00
	CHK ALL LIGHTING.		60.00	30.00
	TUFF KOTE.		60.00	30.00
	REMOVE/REFIX REVERSE SENSOR .		80.00	30.00
			2,100.00	1,290.00
GRAND TOTAL			8,870.64	5,631.84

RECOMMENDED COST OF REPAIRS				5,631.84
------------------------------------	--	--	--	-----------------

Report Ref No. CC3/CTI22003721/Vpa3q2

THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 6547J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 6547J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

