

(08/11/19)

ASS. REC. BY:

Thuvan

REF:

ntuc

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHD65495 Yr Regn: 30/10/19Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hyundai Ioniq c.c. 1550Colour: blue A/C: Insured / Std / NI / NASp. Reading: 364159 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 17MHC851CULU187858Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 14/4/22 D.O.I. 14/4/22 1645Survey held at CDGDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

no GIA provided

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Date/Time: 14.04.2022 12:30

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4196813

JC NO.305512440

USTOMER

IR/MS COMFORT TRANSPORTATION PTE LTD
USTOMER NO. 7010045
DDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
EL. (R) 65508755 (O)
(P)

ISCOUNT CARD NO.

REGN NO.:

SHD6547J

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

14.

DATE/TIME IN
04.2022 09:50

YR OF MANU.

30.10.2019

TARGET DATE

CHASSIS CODE

KMHC851CVLU187858

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 14.04.2022

NATURE: 3P 14.04.2022

S/NO

LABOR CODE

DESCRIPTION



HECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

re:

No.:

icle No.:

SHD6547J

YY

Vehicle No.:

SHD6547J

ne of Service Advisor

Signature/Date

Name of Service Advisor

Date

re returned to Service Reception upon collection

To be kept by Security Guard

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD6547J

Date: 14.04.2022

Make : HYUNDAI

Insurance: CHINA TAIPING

Model : IONIQ(G3)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	REAR BUMPER COVER			\$459.40	let
10	REAR BUMPER CLIPS			\$22.00	nec
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25	let
1	REAR BUMPER REINFORCEMENT			\$394.80	XSV
2	REAR BUMPER REINFORCEMENT BRACKET LH RH		\$138.10	\$276.20	XSV
1	REAR BUMPER FOG LAMP			\$201.50	XSV
1	REAR BUMPER LICENCE LAMP			\$85.30	XSV
1	ANTENNA ASSY SMARTKEY			\$40.50	XSV
1	REAR BUMPER TOWING COVER			\$94.60	let
1	REAR PANEL			\$532.00	XSV
1	REAR PANEL GARNISH			\$346.80	XSV
2	REAR BUMPER SIDE BRACKET LH RH		\$55.80	\$111.60	nec
1	REAR BUMPER LOWER CTR MOULDING			\$155.00	nec
1	BOOTLID			\$2,549.70	DT
1	BOOTLID HYUNDAI PLATE			\$24.30	nec
1	EMBLEM HYBRID			\$24.30	nec
1	EMBLEM - IONIQ			\$31.30	nec
2	BOOT LID LAMP LH RH		\$822.00	\$1,644.00	XSV
1	REAR BUMPER UNDER CENTRE COVER			\$225.00	XSV
SUB TOTAL				\$7,669.55	
LESS 20%				\$1,533.91	
DISCOUNTED TOTAL				\$6,135.64	
	REAR FENDER ADVERTISEMENT LOGO LH			\$100.00	nec
	REAR FENDER ADVERTISEMENT LOGO RH			\$100.00	nec
	BOOTLID ADVERTISEMENT LOGO			\$100.00	nec
	REAR NUMBER PLATE WITH TRIM COVER			\$55.00	nec
	BOOTLID COMFORT TEL NO STICKER			\$40.00	nec
	BOOTLID COMFORT LOGO STICKER			\$30.00	nec
	BOOTLID COMFORT APP STICKER			\$30.00	nec
	REAR BUMPER REVERSE SENSOR			\$180.00	let
				\$635.00	
	Labour Charge			\$1,100.00	700
	PANEL BEATING			\$800.00	500
	SPRAY PAINTING CHARGE			\$60.00	30
	CHK ALL LIGHTING			\$60.00	30
	TUFF KOTE			\$80.00	30
	REMOVE/REFIX REVERSE SENSOR				

	TOTAL LABOUR		\$2,100.00
	ESTIMATE TOTAL		\$8,870.64
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Thwcy
 8223 5969
 14/4/22 1645
 P/P 3 days wp

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: