



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2205601

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 13/09/2022
Reference CC3/CTI22003722/Vpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SH 6114Z
Insured Veh. SJM 5786X
Claim No. SNM22D202553/C02
Policy No. DMPCSNW00110902101
Accident Date 13/04/2022
Inspection Date 19/04/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI22003722/Vpa3q2	
			Date: 13/09/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJM 5786X	Veh. Inspected	SH 6114Z	
Policy No.	DMPCSNW00110902101	Coverage (\$)	0.00	
Claim No.	SNM22D202553/C02	Excess (\$)	0.00	
Assign From		Assign Date	19/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMGU091350	Colour	BLUE	
Odometer	811007 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	206/60 R16	WEST LAKE	5 mm	
L/H Front Tyre	206/60 R16	WEST LAKE	5 mm	
R/H Rear Tyre	206/60 R16	WEST LAKE	5 mm	
L/H Rear Tyre	206/60 R16	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/04/2022	Inspection Date	19/04/2022	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6114Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR PANEL LH	TO REPAIR SEE LABOUR	2,707.70	-
1	REAR DOOR PANEL LH	TO REPAIR SEE LABOUR	2,204.10	-
	LESS 20% DISCOUNT		-982.36	-
			3,929.44	-
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT DOOR ADVERTISEMENT LH (SN)	NECESSARY	100.00	100.00
1	REAR DOOR ADVERTISEMENT LH (SN)	NECESSARY	100.00	100.00
1	FRONT DOOR COMFORT STICKER (SN)	NECESSARY	75.00	75.00
1	REAR DOOR COMFORT APP STICKER (SN)	NECESSARY	80.00	80.00
			355.00	355.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT DOOR PANEL LH AND REAR DOOR PANEL LH .		600.00	560.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	REMOVE/REFIX DOOR PART FRONT & REAR.	NOT NECESSARY	180.00	-
	TUFF COAT.		90.00	30.00
			1,470.00	1,090.00
	GRAND TOTAL		5,754.44	1,445.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,150.00

Report Ref No. CC3/CTI22003722/Vpa3q2

THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 6114Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 6114Z

RE-INSPECTION

