



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2300965

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 18/02/2023
Reference CC6/CTI22003724/Upa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMD 4591J
Insured Veh. GBC 453L
Claim No. SNM22D202863/C02
Policy No. DMCVSNA00012982200
Accident Date 20/04/2022
Inspection Date 22/04/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22003724/Upa3q2 Date: 18/02/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 453L	Veh. Inspected	SMD 4591J	
Policy No.	DMCVSNA00012982200	Coverage (\$)	0.00	
Claim No.	SNM22D202863/C02	Excess (\$)	0.00	
Assign From		Assign Date	22/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT (A)	c.c	1339	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	GE61126571	Colour	BLACK	
Odometer	152032 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	TOURADOR	4 mm	
L/H Front Tyre	195/55 R15	TOURADOR	4 mm	
R/H Rear Tyre	195/55 R15	TOURADOR	4 mm	
L/H Rear Tyre	195/55 R15	TOURADOR	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/04/2022	Inspection Date	22/04/2022	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 4591J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DISTORTED / TORN	821.90	532.60
2	FRONT BUMPER SIDE RETAINERS @\$35.00	CRACKED / NECESSARY	70.00	70.00
1	SET FRONT BUMPER CLIPS	NECESSARY	39.00	39.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	387.80	-
1	HEADLAMP O/S	SCRATCHED	815.20	612.50
1	HEADLAMP LOWER BRACKET O/S	NOT NECESSARY	66.80	-
1	FRONT FENDER O/S	TO REPAIR SEE LABOUR	455.20	-
1	FRONT FENDER INNER SHIELD O/S	DEFORMED / TORN	166.20	148.80
1	SET FRONT FENDER INNER SHIELD CLIPS O/S	NECESSARY	39.00	39.00
1	FRONT FENDER INNER ARCH PANEL O/S	TO REPAIR SEE LABOUR	291.30	-
1	FRONT SPORT RIM O/S	TO REPAIR SEE LABOUR	800.00	-
	LESS 20% DISCOUNT		-	-288.38
			3,952.40	1,153.52
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-
	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM.		120.00	50.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	60.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER O/S,FRONT FENDER INNER ARCH PANEL O/S AND FRONT SPORT RIM O/S.		600.00	380.00
	TO PUTTY & SPRAY PAINTING.		800.00	600.00
			1,740.00	1,110.00
	GRAND TOTAL		5,692.40	2,263.52

Report Ref No. CC6/CTI22003724/Upa3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,800.00
---	--	--	-----------------

Report Ref No. CC6/CTI22003724/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMD 4591J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMD 4591J

RE-INSPECTION

