

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMD 45917

at Workshop m/s

of

Insured: GBC 453C

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 14k.

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 3

days

Res.: Yes or No

Lum Sum: 20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: 21/8k.

Veh No: SMD 45917

Yr Regn: 22/01/09

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA1

Make: Honda

Zif

c.c 1339

Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 152032

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 6E61126571

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Tourador

Front

Rear

R/Bal. 4

mm

R/Bal. 4

mm

L/Bal. 4

mm

L/Bal. 4

mm

D.O.A. 22/04/22

D.O.I. 22/4/22

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

corrected 21-01-2024 LTA 84551

have video at folder

28/4/22 2/5 @ 1800 informed AGN

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: _____

☐

Site Insp (\$

) S + RS, SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format : _____

Lump Sum / I.B.I. (\$) _____

TOTAL

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

LKK Asher

Not Authorized
her

22/4/22

2/5 \$1800
3 days

VEHICLE No: SMD 4591J

1PC	FRONT BUMPER	Dis/torn	532.60	\$821.90	✓
2PCS	FRONT BUMPER SIDE RETAINERS @\$35.00	Cra/ner		\$70.00	✓
1SET	FRONT BUMPER CLIPS	ner		\$39.00	✓
1PC	FRONT BUMPER REINFORCEMENT	ner		\$387.80	X
1PC	HEADLAMP O/S	SCA	612.50	\$815.20	✓
1PC	HEADLAMP LOWER BRACKET O/S	11		\$66.80	X
1PC	FRONT FENDER O/S	R		\$455.20	X
1PC	FRONT FENDER INNER SHIELD O/S	De/torn	148.80	\$166.20	✓
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	ner		\$39.00	✓
1PC	FRONT FENDER INNER ARCH PANEL O/S	R		\$291.30	X
1PC	FRONT SPORT RIM O/S	R		\$800.00	X
				\$3,952.40	

TO CHECK WIRING	\$50.00	20
TO SPRAY RUST PROOFING	\$50.00	X
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	\$120.00	50
TO CONDUCT WHEEL ALIGNMENT	\$120.00	60
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$600.00	380
TO PUTTY & SPRAY PAINTING	\$800.00	600
TOTAL	\$5,692.40	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1441-90

202

P-1153.52

L-1110.00

2263.52

202

1810.81