Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance

(Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Jacqueline Tan Date: 12 May 2022

Preliminary Advice

: SJX2229A Insured

Vehicle No

TP Vehicle : GBK4426Y

Accident Date

: 15/04/2022

: 4

No Make

: NISSAN NV200 Assignment Date: 22/04/2022

Date of : 25/04/2022 Est. Duration of

Inspection

Repair

Inspection At: N-51 AUTOMOTIVE PTE LTD (HQ)

BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB

SINGAPORE 417921

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 6,981.45 **Revised Amount** :S\$ 3,894.75 Check Items (Estimated) :S\$ 0.00 Total :S\$ 3,894.75

Lump Sum Repair :S\$ 3,100.00

Total Loss Consideration

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$ Margin for Repair :S\$

Remarks

() The vehicle is repairable at our adjusted amount. We have also confirmed
	excess and policy coverage. Kindly let us have your authorisation.

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.