

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22003731/EVY3N2**Date:** 05/05/2022**REFERENCE**

|                              |                                               |                             |                    |           |                         |
|------------------------------|-----------------------------------------------|-----------------------------|--------------------|-----------|-------------------------|
| Handling Insurer:            | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:                  | DMB1SNW00005442200 |           |                         |
| <b>Claimant Vehicle No :</b> | PC3249A                                       | <b>Insured Vehicle No :</b> | PC8929M            |           |                         |
| Date of Loss:                | 20/04/2022                                    | Nature of Claim:            | TP                 | Claim No: | SNM22D202683/C02/TANCHC |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                    |
|-----------------------------|-----------------------------------|-------------|--------------------|
| Reg No:                     | <b>PC3249A</b>                    |             |                    |
| Make & Model:               | YUTONG ZK6107H, 6.7 D (A)         | Engine No:  | ISB67E525022101632 |
| Reg. Date:                  | 16/12/2014 (Man. Year: 2013)      | Chassis No: | LZYTBTDF8D1064010  |
| Colour:                     | Multi-colour                      | Odometer:   | 364414 km          |
| Engine Capacity:            | 6690 cc                           |             |                    |
| Market Value/New Car Price: | N/A                               |             |                    |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                    |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 295/80R22.5      | Rear Tyre Size:  | 295/80R22.5      |
| Front Left Side:  | Bridgestone 4 mm | Rear Left Side:  | Bridgestone 4 mm |
| Front Right Side: | Bridgestone 4 mm | Rear Right Side: | Bridgestone 4 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 1,743.00          | 1,580.00          | 163.00            | 9.35          |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 640.00            | 430.00            | 210.00            | 32.81         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>2,383.00</b>   | <b>2,010.00</b>   | <b>373.00</b>     | <b>15.65</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b> | 166.81            | 140.70            | 26.11             | 15.65         |
| <b>Nett Amount (S\$)</b>      | <b>2,549.81</b>   | <b>2,150.70</b>   | <b>399.11</b>     | <b>15.65</b>  |

**INSPECTION**

|                             |            |               |                                                         |
|-----------------------------|------------|---------------|---------------------------------------------------------|
| Date of Assignment:         | 22/04/2022 |               |                                                         |
| Date Inspected:             | 22/04/2022 | Inspected At: | Connect3 (HQ)<br>566 Woodlands Road<br>Singapore 728697 |
| Estimated Period of Repair: | 2.0 days   |               |                                                         |

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

|               |                                                                                                                                                                              |                                                            |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------|
| Reference     |                                                                                                                                                                              |                                                            |
| Part Source:  | (Last Synchronised: 05 May 2022)                                                                                                                                             |                                                            |
| Parts:        | N/A                                                                                                                                                                          | YUTONG ZK6107H 6.7 D (A) (Model not available in database) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                          |
| Print Code:   | (Unsubmitted, no print-code for PC3249A)                                                                                                                                     |                                                            |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                            |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                            |

Recommended Parts

| No.                                               | Qty | Part No. | Particulars                     | Condition | Repairer's | Amount       |
|---------------------------------------------------|-----|----------|---------------------------------|-----------|------------|--------------|
| 1                                                 | 1   |          | *FRONT RH REAR VIEW MIRROR ASSY | Broken    | 1,630.00 F | *1,630.00 FL |
| 2                                                 | 1   |          | *BLIND SPOT MIRROR              | Broken    | 113.00 FS  | *113.00 FS   |
| F=Franchise part. S=SpcNett. L=ListItemDisc.      |     |          |                                 |           |            |              |
| Sub Total (S\$)                                   |     |          |                                 |           | 1,743.00   | 1,743.00     |
| - List Item Discount on L Items 0.00/10.00% (S\$) |     |          |                                 |           | 0.00       | 163.00       |
| Total Parts (S\$)                                 |     |          |                                 |           | 1,743.00   | 1,580.00     |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                              | Particulars    | Lab.Type | Repairer's    | Amount        |
|---------------------------------|----------------|----------|---------------|---------------|
| <b>Labour Items</b>             |                |          |               |               |
| 1                               | CHECK WIRING   | New      | 40.00         | 30.00         |
| 2                               | LABOUR CHARGES | New      | 300.00        | 200.00        |
| 3                               | SPRAY PAINTING | New      | 300.00        | 200.00        |
| <b>Gross Labour Cost (\$\$)</b> |                |          | <b>640.00</b> | <b>430.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >