COMFORTDELGRO

	ENGINEERING						
Our Job Ref No :	_	ComfortDolGro Engineering Pte Ltd 59 Loyang Drive Singapore 508989					
FINALIZATION FORM				46 8156			
To :	LKK		Fax:				
Attn :	HEVAN						
Vehicle Reg No. : SHA	7317R	Da	te of Accident :	18.04.2022			
The survey and estimates of	the repairs of the ab	ove-mentioned	í vehicle are as	follows:-			
The repair job shall bill	to:	NTUC		FBE1354Y			
2. The finalized amount s	hall be:						
(a) Spare Parts after	r List discount			\$1,043.77			
(b) Labour Charges	etc,if any)	\$630.00					
	y-Part Repair Cost			\$1,673.77			
(c.) Lumpsum Repa	(c.) Lumpsum Repair (if applicable)  Total for Lumpsum repair cost after Less: 20%  Final Lumpsum Repair cost						
		_					
<ol> <li>Estimated normal period</li> </ol>	d for repairs:	w	orking days.				
We shall treat the abo within 7 working days		rect and Confi	rmed if there i	s no reply from you			
i. Thank you for your ass	Thank you for your assistance.		We confirm the estimates and finalized amount				
	1.			1			
ĺ	TIMPS						
Signature :	Signature :		gnature:	THEVAN			
Name : LIMTS		-	ame :	20/11/22			
Tel : <u>6214839</u>	: 62148398 Date :			2014/12			
Fax : <u>6546815</u>	6	-		<u> </u>			
or Official Use Only							
		Document	Confirm By				
Item	Amount	Attached Yes or No	(Signature)	Remarks			
B. del Data D/Data	-	YES					
. Rental Rate P/Day . Loss of Income Paid		N					
Survey Fees							
TA Search Fee	\$7.49 /\$2.00						

٥.	Survey Fees		
4.	LTA Search Fee	\$7.49 /\$2.00	 
5.	Medical Fees (on behalf of driver, if applicable)		
6	Overrun		

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

DATE:

19.04.22

MODEL:

Toyota Prius G4A

VEHICLE NO.: SHA7317R

INSURANCE: NTUC (P)

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT CUL
2712-G	Rear Bumper - G4A	1		\$551.89 1
	Rear Bumper Re-Inforcement	1		\$378.32 X50C
2713-G	Rear Bumper Lower Cover-Black	1		\$654.96
2723-G	Rear Bumper Reflector RH	1		\$55.00 X 5 CC
2715-G	Rear Bumper Tow Cover	1		\$82.70 XSUC
	Rear Bumper Clips	10	\$2.20	\$22.00 / huc
	SUB TOTAL LESS 25% DISCOUNTED TOTAL			\$1,744.87 \$436.21 <b>\$1,308.65</b>
	Reverse Sensor  SUB NETT TOTAL  LESS 10% S/NETT TOTAL	1		\$135.70 A F \$13.57 <b>\$122.13</b>
	Rear Bumper Mat	1	-	\$50.00 XNN
	TOTAL SPARE PARTS		-	\$1,480.78
	Labour Charge			\$400.00 350
	Panel Beating			· · · · · · · · · · · · · · · · · · ·
	Spray Painting Charge			T
	Remove/Refix Reverse Sensor			\$120.00 30
	TOTAL LABOUR			\$820.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the

**ESTIMATE TOTAL** 

vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Therau 82235769 PIP 2days wp 19/4/22 1619

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

\$2,300.78

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: