

ASS. REQ. BY: Thevan

REF: ntac

NS/INC22003737/Vqc

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: MT/1171418-001

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHA7317R Yr Regn: 19/2 /20

Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) Prime Mover /

Truck / Trailer or

Make: TOYOTA prius hybrid cc 1798

Colour: blue A/C: Insured / Std / NI / NA

Sp. Reading: 265241 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STDHB3FU1030912213

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or westlake

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 18/4/22 D.O.I. 19/4/22 1615

Survey held at CDOE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

NO GIA provided

Thevan finalised final fig \$1673.77, 2 days. (Red \$627.01, 27%)

Date/Time, File Pass to?

1) 12/05 Typist

Date/Time, File Return to?

2)

Report Format : TP

~~Lump Sum~~ / I.B.I: (\$ 1673.77)

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:

- ☐ : Site Insp (\$ _____)
- ☐ : Interview (\$ _____)
- ☐ : Tech. Invs (\$ _____)
- ☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ S + RS ____ SI

Photos

Others

TOTAL

Date/Time: 19.04.2022 14:35

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4197823

JC NO 305513038

OWNER COMFORT TRANSPORTATION PTE LTD OWNER NO. 7010045 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65508755 (O) (P)	REGN NO. SHA7317R	MILEAGE
	MAKE TOYOTA	FUEL E 1/2 F
	MODEL PRIUS HYBRID(G4A19)	DATE/TIME IN 04.2022 12:35
	YR OF MANU. 19.02.2020	TARGET DATE
	CHASSIS CODE JTDKB3FU103091213	COMPLETION DATE/TIME


QUANTITY CARD NO.

JOB DESCRIPTION

Accident Date: 18.04.2022
NATURE: 3P 18.04.2022

/NO LABOR CODE
00010 PB

DESCRIPTION
LUMPSUM REPAIR-SHA7317R-TP



BOOKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Handover Slip

Exit Pass

No.: **SHA7317R** **LIMITS**

Vehicle No.: **SHA7317R**

Signature/Date

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

LKK-

DATE: 19.04.22

INSURANCE: NTUC C P / P

MODEL: Toyota Prius G4A

MVA: LIM T S

VEHICLE NO.: SHA7317R

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
2712-G	Rear Bumper - G4A	1		\$551.89
	Rear Bumper Re-Inforcement	1		\$378.32
2713-G	Rear Bumper Lower Cover-Black	1		\$654.96
2723-G	Rear Bumper Reflector RH	1		\$55.00
2715-G	Rear Bumper Tow Cover	1		\$82.70
	Rear Bumper Clips	10	\$2.20	\$22.00
SUB TOTAL				\$1,744.87
LESS 25%				\$436.21
DISCOUNTED TOTAL				\$1,308.65
	Reverse Sensor	1		\$135.70
SUB NETT TOTAL				\$135.70
LESS 10%				\$13.57
S/NETT TOTAL				\$122.13
	Rear Bumper Mat	1		\$50.00
TOTAL SPARE PARTS				\$1,480.78
Labour Charge				
Panel Beating				\$400.00
Spray Painting Charge				\$300.00
Remove/Refix Reverse Sensor				\$120.00
TOTAL LABOUR				\$820.00
ESTIMATE TOTAL				\$2,300.78

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thevan
82235469
P/P 2 days w/p
19/4/22 1615

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: