

Our Job Ref No : 305513035  
Date : 23/04/22

**COMFORTDELGRO**  
**ENGINEERING**

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK  
Attn : Mr Thevan  
Vehicle Reg No. : SHC3421M


Fax :


18/04/2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SLZ2505T
2. The finalized amount shall be:
  - (a) Spare Parts after List discount
  - (b) Labour Charges \$0.00
  - Total for Part-By-Part Repair Cost**
  - (c.) Lumpsum Repair (If applicable)  
Total for Lumpsum repair cost after Less: 20% \$1,000.00  
**Final Lumpsum Repair cost**
3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : Ms. Loke YY  
Tel : 62148355  
Fax : 65468156

Signature :   
Name : Thevan  
Date : 28/4/22

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SHC3421M

Date: 04/19/22

Make : HYUNDAI

Insurance: NTUC

Model : IONIQ(G2)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
1	ANTENNA SMARTKEY			\$40.50
1	REAR BUMPER FOG LAMP			\$201.50
1	LICENCE LAMP			\$85.30
	<b>SUB TOTAL</b>			\$1,654.75
	<b>LESS 20%</b>			\$330.95
	<b>DISCOUNTED TOTAL</b>			\$1,323.80
	REAR NUMBER PLATE WITH TRIM COVER			\$55.00
	REAR BUMPER REVERSE SENSOR			\$180.00
				\$235.00
	<b>Labour Charge</b>			
	PANEL BEATING			\$400.00
	SPRAY PAINTING CHARGE			\$600.00
	CHECK ALL LIGHTING			\$60.00
	REMOVE/REFIX REVERSE SENSOR			\$80.00
	<b>TOTAL LABOUR</b>			\$1,140.00
	<b>ESTIMATE TOTAL</b>			\$2,698.80

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan  
82235769  
19/4/22  
1630 on 2 days up  
LIS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- To display damaged part(s) during resurvey
- To display damaged part(s) during resurvey
- Parts prices are subject to "without prejudice" basis
- Third party survey is on a "without prejudice" basis
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: