

						COMFORTDELGRO				
Our Job Ref No : 305512384						ENGINEERING				
Date :			:	21.04.2022			Com 59 L	fortDelGro Engineering Pte Ltd oyang Drive Singapore 508969		
FINA	LIZAT	ION	FORM							
То	: _			LKK			Fax:			
Attn	:			THEVAN						
Vehic	le Re	g No.	: SH6	673B				13.04.2022		
The s	urvey	and e	estimates o	f the repairs of the above-n	nentioned v	vehicl	e are as follow	vs:-		
Z	The repair job shall bill to:					uc		FBR7278B		
2.	The finalized amount shall be:									
	(a)	Spa	re Parts af	ter List discount						
	(b)	Lab	our Charge	es						
		Tota	al for Part-	By-Part Repair Cost						
	(c.)	Lum	npsum Rep	air (if applicable)						
		Tota	al for Lump	sum repair cost after Less: m Repair cost		70 Sales		\$2,450.00		
				repair odst				<u>φ2,430.00</u>		
3.	Estim	ated	normal per	iod for repairs:	3	wo	orking days.			
	We s			ove amount as Correct a	nd Confirr	ned i	f there is no r	reply from you within		
	Thank you for your assistance.							estimates and		
						fin	alized amount			
				91//						
	Signature :					Signature:				
	Name : CHIANG					Name : NUGY				
	Tel	:	6214831	4		Da	te :	7614172		
	Fax	:	6546815	6	_					
or Of	ficial	Use (Only			0				
	1	tem		Amount	Docum		Confirm By	Remarks		

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	•			
4. LTA Search Fee	\$7.49/\$2.00	YES		
Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks	:				
			 	ž.	,

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO

SH6673B

REG 28.07.2016

MAKE

13.04.2022

ODEL	HYU- 140		CHIANG/ NTUC	
Qty	Parts Description/ Labour	Type	Unit Price	Amount
	REAR BUMPER COVER			\$553.00⁄
	REAR BUMPER LOWER COVER			\$228.00
1	REAR BUMPER REINFORCEMENT			\$428.407
2	REAR BUMPER BRACKET SIDE /RH		\$35.60	\$35.60
10	REAR BUMPER CLIPS		\$2.20	\$22.00
10	BOOTLID EMBLEM I-40			\$67.90
1	BOOTLID EMBLEM CRDI			\$52.40
1	REAR FENDER SHIELD RH			\$174.90
1	TAIL LAMP RH			\$697.80
1	REAR FENDER AIR DUCT			\$51.60
1	REAR WHEEL CAP			\$214.20
1	REAR FENDER RH			\$2,171.40
				\$4,697.20
	20.00%			\$939.44
	DISCOUNTED TOTAL			\$3,757.76
1 1 1 1 2	REAR DOOR COMPORT APP REAR DOOR ADVERTISEMENT REAR FENDER ADVERTISEMENT REAR BUMPER ADVERTISEMENT REAR BUMPER MAT COMFORTDEGRO / TEL NUMBER STICKER REVERSE SENSOR			\$80.00, \$100.00, \$100.00, \$50.00, \$50.00, \$60.00, \$135.70, \$548.13
1	Labour Charge Panel Beating			\$980.00
- 1	Spray Painting Charge			\$800.00
	Remove/Refix Upholstery			\$90.00
- 1	Check lighting			\$60.00
1	Tuff Kote		,	\$90.00
	TOTAL LABOUR			\$2,020.00
	TOTAL LABOUR	_		\$2,020.00
	ESTIMATE TOTAL		LKK Auto Consultants he the Repairer of the follow • To resurvey before/after spray • To display damaged part(s) dur	ng:
Т	his is an initial estimate based on a visual inspection of the a	bove veh	iclearthreichar febientoceal	irentierwill
1	e prepared after the vehicle is surveyed by a motor Surveyo	r appoints	Third party survey is on a with	out Prejudice" basis

Thurst 87235769
13/(1/72 17/5)
LIS Mpair 3clays wp

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: