

Date/Time: 14.04.2022 13:55 Page : 1

Sam: ARC Repair TP(CFSO)1 JOB CARD Sales Order: 4196842 JC NO.305512443


OMER	REGN NO: SHC7179L	MILEAGE
IS CITYCAB PTE LTD	MAKE: HYUNDAI	FUEL
OMER NO 7010070	MODEL I-40	E.....1/2.....F
ESS 383 SIN MING DRIVE	YR OF MANU 14.07.2016	DATE/TIME IN 14.04.2022 11:20
Singapore SINGAPORE 575717	CHASSIS CODE KMHLB41UMGU092393	TARGET DATE
(R) 65551188 (O)		COMPLETION DATE/TIME:
(P)		
JUNT CARD NO.		

Accident Date: 14.04.2022
ATURE: 3P 14.04.2022/C

JOB DESCRIPTION

/NO LABOR CODE
00010 PB

DESCRIPTION
PANEL BEATING-SHC7179L-TP



ED & PASSED OUT BY: _____

SERVICE ADVISOR CUSTOMER'S SIGNATURE

dgement Slip

Exit Pass

SHC7179L LIMITS

Vehicle No.: SHC7179L

Service Advisor Signature/Date

Name of Service Advisor Date

ned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

SAS-KIV

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK-

DATE: 14.04.22INSURANCE: NTUC - 45MODEL: Hyundai i40MVA: LIM T SVEHICLE NO.: SHC7179L - CityCab

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper	1		\$ 1,052.20 <i>act</i>
	Front Bumper Clips	10	\$ 2.20	\$ 22.00 <i>nae</i>
	Front Bumper Side Bracket LH	1		\$ 22.40 <i>nae</i>
	Front Fender LH	1		\$ 663.00 <i>PT</i>
	Front Fender Shield LH	1		\$ 174.90 <i>XSE</i>
	Front Fender Retainer LH	1		\$ 217.20 <i>XSC</i>
	HeadLamp LH	1		\$ 1,388.00 <i>XSC</i>
	Front Wheel Cap LH	1		\$ 217.20 <i>SC</i>
	Front Wheel Rim LH	1		\$ 325.60 <i>XSC</i>
	SUB TOTAL			\$ 4,082.50
	LESS 20%			\$ 816.50
	DISCOUNTED TOTAL			\$ 3,266.00
	Front Wheel Tyre LH	1		\$ 216.00 <i>XSC</i>
	Front Fender Adv.Sticker LH	1		\$ 100.00 <i>nae</i>
	NETT TOTAL			\$ 316.00
	SPARE PARTS TOTAL			\$ 3,582.00
	<u>Labour Charge</u>			
	Panel Beating			\$ 800.00 <i>560</i>
	Spray Painting Charge			\$ 600.00 <i>500</i>
	Check Lightings			\$ 40.00 <i>20</i>
	Tuff Kote			\$ 60.00 <i>30</i>
	Wheel Alignment			\$ 120.00 <i>30</i>
	TOTAL LABOUR			\$ 1,620.00
	ESTIMATE TOTAL			\$ 5,202.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan
82235769
14/4/22 1615
L/S 3days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: