

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305512443
Date : 19.04.22

FINALIZATION FORM

To : LKK
Attn : THEVAN
Vehicle Reg No. : SHC7179L

Fax :


Date of Accident : 14.04.22


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: NTUC --- GBE7247J
- The finalized amount shall be:
 - Spare Parts after List discount
 - Labour Charges (include advertisement stickers etc, if any)Total for Part-By-Part Repair Cost
- Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$2,250.00
Final Lumpsum Repair cost \$2,250.00

- Estimated normal period for repairs: 3 working days.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
- Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : 
Name : THEVAN
Date : 26/4/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

SAS-KIV

LKK-

DATE: 14.04.22

INSURANCE: NTUC - 45

MODEL: Hyundai i40

MVA: LIM T S

VEHICLE NO.: SHC7179L - CityCab

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper	1		\$ 1,052.20 <i>X 1.1</i>
	Front Bumper Clips	10	\$ 2.20	\$ 22.00 <i>X 1.1</i>
	Front Bumper Side Bracket LH	1		\$ 22.40 <i>X 1.1</i>
	Front Fender LH	1		\$ 663.00 <i>X 1.1</i>
	Front Fender Shield LH	1		\$ 174.90 <i>X 1.1</i>
	Front Fender Retainer LH	1		\$ 217.20 <i>X 1.1</i>
	HeadLamp LH	1		\$ 1,388.00 <i>X 1.1</i>
	Front Wheel Cap LH	1		\$ 217.20 <i>X 1.1</i>
	Front Wheel Rim LH	1		\$ 325.60 <i>X 1.1</i>
	SUB TOTAL			\$ 4,082.50
	LESS 20%			\$ 816.50
	DISCOUNTED TOTAL			\$ 3,266.00
	Front Wheel Tyre LH	1		\$ 216.00 <i>X 1.1</i>
	Front Fender Adv.Sticker LH	1		\$ 100.00 <i>X 1.1</i>
	NETT TOTAL			\$ 316.00
	SPARE PARTS TOTAL			\$ 3,582.00
	Labour Charge			
	Panel Beating			\$ 800.00 <i>560</i>
	Spray Painting Charge			\$ 600.00 <i>500</i>
	Check Lightings			\$ 40.00 <i>20</i>
	Tuff Kote			\$ 60.00 <i>30</i>
	Wheel Alignment			\$ 120.00 <i>30</i>
	TOTAL LABOUR			\$ 1,620.00
	ESTIMATE TOTAL			\$ 5,202.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Therion
82235769
14/4/22 1615
L/S 3days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: